

1 GPS Device Description

1.1 About

Ruptela's FM-Eco4 light / FM-Eco4 light 3G device is a 4th generation low cost, low power consumption basic tracking device. It acquires its position by a GPS/GLONASS signal and transfers data to a server via cellular GSM/GPRS/3G network. 3G network support was not previously available for FM4 devices. This new feature in FM-Eco4 light 3G is the main advantage over the FM-Eco4 light devices.

Both device versions FM-Eco4 light and FM-Eco4 light 3G have various improvements over the older 3rd generation FM-Eco3 devices:

- Lower power consumption
- 1-Wire interface
- Internal GPS/GLONASS antenna



FM-Eco4 light



FM-Eco4 light 3G

Both devices can have an internal power supply source. Device versions with batteries are labeled FM-Eco4 light+ and FM-Eco4 light+ 3G.

1.2 Device Dimension and Properties:

Properties Enclosure dimensions



FM-Eco4 light



FM-Eco4 light 3G

Properties Enclosure :

- Dimensions 64,5L x 61W x 22H mm
- Indication 3 LEDs:
- GNSS status, GSM status,
- 1-Wire status Housing Plastic Configuration interface USB Connectors 12 PINs insulated
- Ambient temperature ratings, °C:
- Temperature range for device
- Storage temperature, °C -40 ~ +65
- Operating temperature, °C -30 ~ +60
- Temperature range for battery
- Charge, °C 0 ~ +45
- Discharge (operating), °C -20 ~ +60
- Storage, °C -20 ~ +60

Common specifications :

- Power supply 10/24 V DC (range: 10 - 32 DC)
- Digital input threshold 4 V
- Analogue input resolution 12 bit (Analogue input range: 0-30 V)
- GPS/GLONASS module Ublox EVA-M8M
- Channels 72
- Sensitivity -163 dBm
- GPS/GLONASS antenna Internal
- Frequency 1575.0 ± 3 MHz
- FM-Eco4 light / light+ GSM modem Quectel M95
- Bands 850/900/1800/1900 MHz @ GSM
- GSM antenna Internal, Quad band
- FM-Eco4 light 3G / light+ 3G GSM modem Quectel UG96
- Bands 800/850/900/1900/2100 MHz @ UMTS
- 850/900/1800/1900 MHz @ GSM
- GSM antenna Internal, Quad band
- Protections
- Short circuit protection
- Reverse polarity protection
- Unit provides internal protection F2 (1 A slow-blow 63 V fuse)

1.3 Package contents

FM-Eco4 light / FM-Eco4 light 3G device is supplied in a cardboard.

Package contents:

- FM-Eco4 light / FM-Eco4 light 3G device or its variant with battery
- 12 PINs cable
- USB 2.0 cable: USB A - male to mini USB B (as an optional accessory)



Note

Providing a SIM card is optional, according to your payment plan. The SIM card is necessary for connection to the GSM network. The SIM card can be obtained from your local GSM service provider. The SIM card can work with the terminal only when all SIM card security codes are disabled.

1.4 Physical characteristics


Properties	
Enclosure dimensions	64.5L x 61W x 22H mm
Indication	3 LEDs: GNSS status, GSM status, 1-Wire status
Housing	Plastic
Configuration interface	USB
Connectors	12 Pin, insulated

1.5 Technical characteristics

Technical characteristics can be found in FM-Eco4 light and FM-Eco4 light 3G datasheets.

1.6 IO pin out

Pin	Wire color	Description
10-32 V	Red	Power supply 12/24 V (range: 10-32 V)
Chassis	Black	Ground connection
DIN1	Pink	Digital input, threshold 4 V
DIN2	Blue	Digital input, threshold 4 V
DIN3	White	Digital input, threshold 4 V (invertible)
DIN4	Yellow	Digital input, threshold 4 V (invertible)
AIN1	Grey	Analogue input (range: 0-30 V)
AIN2	Green	Analogue input (range: 0-30 V)
DOUT1	Purple	Digital output open collector up to 32 V, 1 A
DOUT2	Orange	Digital output open collector up to 32 V, 1 A
1-Wire POWER	White with red stripe	1-Wire power output: 80 mA @ 4.1 V
1-Wire DATA	Green with yellow stripe	1-Wire data transfer



1.7 Peripheral accessories

There are several peripheral accessories that can be connected to the FM-Eco4 light/ FM-Eco4 light 3G device. With these peripherals you can get even more features and extended functionalities. All available peripherals can be purchased from Ruptela. Please contact your manager for more details.

Note

- 4 × Temperature sensors DS18B20/DS18S20
- 1 × iButton DS1990
- 1 × 1-Wire RFID
- 1 × Buzzer/LED
- 1 × ECO Driving panel (power supply from 1-Wire)
- 1 × Ignition lock
- 1 × Panic button
- 1 × Door sensor
- 2 × Analog fuel sensors

1.8 LED Status

The device has three LEDs with different blinking patterns that show the state of the device's communication.

LED	Pattern	Description
GNSS	Once every second	Accurate signal
	Once every 0.4 seconds	No signal
GSM	Once every 4 seconds	Accurate signal
	Once every 0.2 seconds	No signal
	Always on	Link with the server is open
1-Wire	Always off	No devices connected
	Once every 5 seconds	One device connected
	Twice every 5 seconds	Two devices connected
	Three times every 5 seconds	Three devices connected
All	Once every 5 seconds	Sleep/deep sleep mode

2 Device preparation

In order for the device to work you have to configure it and insert a SIM card. To do so, you have to open the device enclosure and perform certain actions described below.

2.1 Opening/Closing the device

Use a screwdriver or a similar tool to open up the plastic housing of the device. It is recommended to use a flat-head type screwdriver (*see figure on the right*). Inappropriate tools might cause permanent damage to the device.

To correctly assemble the device you have to know

No	Name
1	The intermediary PCB pin
2	The PCB stabilizer pin
3	The PCB support pin


1. Make sure that the PCB is facing up. Only then it can be mounted in its plastic housing.
2. The PCB goes under the intermediary plastic pin - 1.
3. Then it is mounted on the stabilizer - 2.
4. The PCB must be correctly placed on the PCB support pin - 3.

When the assembly sequence described above is completed, push the other side of the PCB down into a stable position.



The plastic lid of the device can be mounted only when all of the PCB pins are holding the PCB in a stable position (*see figure above*).

To correctly seal the plastic housing of the device, start by placing the plastic lid at either side of the device (*see figure on the right*). Then push the remaining side down until the housing is fully closed.



2.2 Connecting the USB cable


Connect a mini USB cable to the device (*see figure on the right*). The cable can be connected only in one way, be careful not to damage the plug. Connect the other end to your PC or a laptop.

Before starting the configuration procedure of the device, make sure that it is connected to the external power supply.



2.3 Inserting a SIM card

If you received a device without a SIM card, place your own SIM card into the device as shown in the picture below. The microchip must be facing down.



2.4 IO cable

Connect the IO cables plug to the Micro - Fit slot on the device (*see figure on the right*). The cable can be connected only in one way.



3 Installation recommendations

3.1 Device installation

When installing the device into a vehicle please obey these instructions otherwise your device may not work properly.

- The module should not be seen or easily reached.
- The module should be firmly fixed to the surface. Please avoid mounting module near a metal surface or cables.
- The module must be facing up, so that the internal GPS/GLONASS antenna is facing up as well (*see figure on the right*).
- A wrong module mounting may result in a malfunction.
- The module cannot be fixed to heat emitting or moving parts.
- A SIM card should be inserted in the module, while the connector is plugged off (while the module has no power).
- The module must be fitted with double sided stick tape!



3.2 Device mounting position

The device must be tightly installed in a service access area (e.g. under dashboard, behind fuse box), it cannot move or shake.



CORRECT



INCORRECT

The device can be installed within 45° angle in any axis, but the top surface in all cases must be facing up.

3.3 Installing Device on Vehicle Dashboard:

- When installing device into vehicle please obey these instructions otherwise your device may not work Properly
- The module shouldn't be visible or easily accessible
- Module should be firmly fixed to the surface. Please avoid mounting module near the metal surface or cables
- Module must be fitted with double sided stick tape or use cable tie.



Make sure that device position is correct, it has cable tie, or double sided 3M tape , To avoid device movements which can affect device reporting accuracy , GPS should be on top of the dashboard ,open to be able to generate accurate data

For Built in antenna devices, make sure that device position is facing the window and make sure that device is not flipped on wrong face that might not let device communicate properly ,or give less accurate data



TILL 17/02/2025						
S/N	DEVICE MODEL	IMEI	Removal Date	BO Number	Plate no	VIN
1	FM ECO4 LIGHT+ 3G	869530043802350	10/9/2024	B0041937	R-11562	JTG SX22P4J6197377
2	FM ECO4 LIGHT+ 3G	869530045214950	10/8/2024	C0045113	DXB-V-82383	MALC741C6KM108768
3	FM ECO4 LIGHT+ 3G	863003042150649	10/9/2024	C0056046	F-49233	VSKDD3C28LA130383
4	FM ECO4 LIGHT+ 3G	867688039784107	10/9/2024	C0051761	P-73541	VSKDD3C47LA133583
5	FM ECO4 LIGHT+ 3G	869530045185986	10/9/2024	C0019225	M-93438	MDHBN7AD9EG513380
6	FM ECO4 LIGHT+ 3G	869530045215346	10/9/2024	C0046925	DXB-L-53141	MDHBN7AD2KG682250
7	TRACE5 LTM (Rev.A) 4G	863940058768469	10/9/2024	C0059927	AD-15-94186	1N4BL4A97NN325958
8	TRACE5 LTM (Rev.A) 4G	863257067801169	10/9/2024	C0061767	DXB-E-95272	RKLBA0BE5N1004502
9	FM ECO4 LIGHT+ 3G	869530045116890	10/9/2024	C0047944	DXB-N-82273	JTNB29HK5K3016656
10	FM ECO4 LIGHT+ 3G	866381051053558	10/9/2024	C0040717	DXB-V-48588	RKLBL9HE3K5265492
11	FM ECO4 LIGHT+ 3G	867688038869487	10/9/2024	C0049562	14-28569	JTNBZ4HK4K3010670
12	FM ECO4 LIGHT+ 3G	869530041393907	10/9/2024	C0027994	R-25473	MDHBN7AD6GG709604
13	FM ECO4 LIGHT+ 3G	869530045150881	1/0/1900	B0046702	AD-6-27154	JTG SX22P2K6204313
14	FM ECO4 LIGHT+ 3G	866381051085097	10/9/2024	C0036814	DXB-S-15361	MR0DX8CD3H0591528
15	FM ECO4 LIGHT+ 3G	869530041401825	10/8/2024	C0028004	D-79848	MDHBN7AD5GG709075
16	TRACE5 LTM (Rev.A) 4G	863257067817728	10/9/2024	C0061765	DXB-E-95408	RKLBA0BE1N1004528
17	FM ECO4 LIGHT+ 3G	869530045287154	6/12/2023	C0012440	2-98597	MNTDD22S8B6001728
18	FM ECO4 LIGHT+ 3G	869530045187222	10/8/2024	C0019215	O-90546	MDHBN7AD9EG512908
19	TRACE5 LTM (Rev.A) 4G	863940058786719	10/9/2024	C0059941	AD-15-94205	1N4BL4A95NN326039
20	FM ECO4 LIGHT+ 3G	867553057661910	10/9/2024	C0046102	DXB-H-58207	JTNBF9HK8K3029034
21	FM ECO4 LIGHT+ 3G	869530041369675	3/14/2023	C0008436	M-48205	JTEBU25J895157121
22	FM ECO4 LIGHT+ 3G	869530045164262	7/21/2022	C0040441	SHJ-3-97147	JTNBF9HK8J3006707
23	FM ECO4 LIGHT+ 3G	866381051070032	8/10/2022	C0049764	DXB-O-59497	KMHD741C7KU921913
24	FM ECO4 LIGHT+ 3G	868899046747594	8/1/2022	C0061339	AD-18-45374	VSKDD3C42NA178630
25	FM ECO4 LIGHT+ 3G	869530045131352	4/25/2024	C0028545	DXB-1-73121	MHKMC13F0FK019441
26	FM ECO4 LIGHT+ 3G	867553056682677	10/9/2024	C0046619	DXB-C-50281	JTHY00WXX4299067
27	FM ECO4 LIGHT+ 3G	869530045176456	10/9/2024	C0035096	DXB-K-29942	RKLBB9HE9H5188042
28	FM ECO4 LIGHT+ 3G	869530045249089	10/9/2024	C0028972	G-73225	MDHBN7AD8GG712424
29	FM ECO4 LIGHT+ 3G	867688034495733	10/9/2024	B0051781	P-91764	JN6BE6DS3L9062935
30	FM ECO4 LIGHT+ 3G	867688039834761	10/9/2024	C0051833	L-64634	MDHBN7AD3LG687958
31	FM ECO4 LIGHT+ 3G	869530045306582	10/9/2024	C0028734	K-61174	MDHBN7AD6GG710431
32	FM ECO4 LIGHT+ 3G	868899043975677	10/9/2024	B0031721	E-27044	JTGJX02P1G5046057
33	FM ECO4 LIGHT+ 3G	867688032988648	10/8/2024	C0047179	6-27496	MHFDX8FS2K0098251
34	TRACE5 LTM (Rev.A) 4G	863940058748016	10/8/2024	C0059910	AD-18-54941	1N4BL4A94NN325934
35	TRACE5 LTM (Rev.A) 4G	863257067815060	10/10/2024	C0053814	DXB-R-68076	MHKEF8BF3LK011576
36	FM ECO4 LIGHT+ 3G	867553057649519	10/10/2024	C0047736	DXB-H-57287	JN6BE6BSXXK9030520
37	FM ECO4 LIGHT+ 3G	869530045171739	1/0/1900	B0026679	G-94371	JTGFB5182F1073219
38	FM ECO4 LIGHT+ 3G	869530045142490	10/27/2023	C0046030	SHJ-3-51870	KL1ZA5CA0JB052327
39	FM ECO4 LIGHT+ 3G	869530045312341	1/0/1900	B0027269	R-24476	JL5B3J6P2FRN21215
40	FM ECO4 LIGHT+ 3G	869530045209810	10/10/2024	C0039863	AJM-B-56021	RKLBB9HE1J5220617

41	FM ECO4 LIGHT+ 3G	867688036601577	1/0/1900	C0044424	9-40668	JTEBU9FJXKK162237
42	FM ECO4 LIGHT+ 3G	869530045182884	2/24/2024	C0047413	DXB-M-63103	RKLBB9HE9K5241281
43	FM ECO4 LIGHT+ 3G	869530045134901	10/10/2024	C0046014	DXB-I-16948	MALC741C8KM117293
44	FM ECO4 LIGHT+ 3G	869530045185994	8/22/2022	C0023994	Q-30694	JS3JB4C14F4200814
45	FM ECO4 LIGHT+ 3G	868899043923867	10/10/2024	C0054805	S-35956	MNTBB7A9XL6071659
46	FM ECO4 LIGHT+ 3G	869530045310857	10/10/2024	C0039494	AD-17-60834	MR0CX8CD6J0693536
47	FM ECO4 LIGHT+ 3G	863003042116301	10/10/2024	C0028701	C-40225	MDHBN7AD3GG712847
48	FM ECO4 LIGHT+ 3G	869530045211568	10/10/2024	C0023213	B-50367	MDHBN7AD5FG710287
49	FM ECO4 LIGHT+ 3G	867688038869537	7/7/2022	C0061290	DXB-Y-85868	MHKEF8BF9PK032874
50	FM ECO4 LIGHT+ 3G	867688039301274	10/10/2024	C0051749	I-97959	JN6BE6AS5L9031240
51	FM ECO4 LIGHT+ 3G	863257067816936	10/10/2024	C0061772	DXB-E-95251	RKLBA0BE0N1004486
52	FM ECO4 LIGHT+ 3G	866381051025648	8/9/2022	B0031305	DXB-V-46249	JTGSX23P4G6167867
53	FM ECO4 LIGHT+ 3G	867688032986311	4/1/2022	B0021064	C-35527	MB1PBEFA9EE1N2111
54	FM ECO4 LIGHT+ 3G	867688039806405	10/11/2024	C0047932	16-71218	MR0KX9CBXL2361087
55	FM ECO4 LIGHT+ 3G	869530045157902	10/11/2024	C0025645	AD-15-45199	6T1BF9FK5FX577093
56	FM ECO4 LIGHT+ 3G	869530045186489	10/11/2024	H0043750	C-60085	JL7B6E1P0HK012670
57	FM ECO4 LIGHT+ 3G	867553058471004	10/11/2024	C0046120	AD-7-46519	JTNBF9HK5K3029184
58	FM ECO4 LIGHT+ 3G	863003042130278	10/11/2024	C0051819	O-61539	MDHBN7AD2LG695419
59	FM ECO4 LIGHT+ 3G	869530045242217	Removed- 06-Sept- 2021	C0027079	R-20637	3N6DD23X3GK005848
60	FM ECO4 LIGHT+ 3G	866381051077938	10/11/2024	C0039355	DXB-U-26377	JE3AB36UXHU713772
61	FM ECO4 LIGHT+ 3G	867688038845289	10/11/2024	C0051843	J-49390	MDHBN7AD4LG686463
62	FM ECO4 LIGHT+ 3G	866381051052915	10/11/2024	B0027270	DXB-R-24479	JL5B3J6P8FRN21221
63	FM ECO4 LIGHT+ 3G	869530045217433	10/11/2024	C0042633	W-19620	RKLBB9HE6K5235356
64	FM ECO4 LIGHT+ 3G	867688035672017	10/11/2024	C0020351	DXB-V-81726	JTNGE52M9EA043021
65	FM ECO4 LIGHT+ 3G	867688039808534	10/11/2024	C0050558	15-68895	JTNBZ4HK4K3010524
66	FM ECO4 LIGHT+ 3G	869530041408176	1/0/1900	B0034889	N-46036	JTGJX02P9G5048039
67	FM ECO4 LIGHT+ 3G	869530041360393	10/11/2024	C0021316	P-82561	RKLBB9HE4E5021020
68	FM ECO4 LIGHT+ 3G	866381051052832	10/11/2024	C0031452	UAQ-A-13408	MR0CX6CD2G0160774
69	FM ECO4 LIGHT+ 3G	869530045262132	10/11/2024	C0025746	I-63098	3N6DD23X7FK033487
70	FM ECO4 LIGHT+ 3G	869530045189996	10/12/2024	C0040119	AD-8-69062	JTNBF9HK7J3006441
71	FM ECO4 LIGHT+ 3G	867688039845130	5/25/2023	C0047569	14-79237	MHFKU8F51K0178656
72	FM ECO4 LIGHT+ 3G	867688039329713	10/12/2024	B0051782	P-91774	JN6BE6DS3L9063051
73	TRACES LTM (Rev.A) 4G	863940058673875	10/12/2024	C0043302	DXB-W-42908	KMHWG81R1KU014319
74	FM ECO4 LIGHT+ 3G	869530045202740	Removed- 07-Mar-21	C0059203	AD-18-79492	MMBMGU5SHXMH006070
75	FM ECO4 LIGHT+ 3G	867553059767376	10/12/2024	C0045084	DXB-E-60297	VF18SRB43KG459713
76	FM ECO4 LIGHT+ 3G	869530045300262	1/0/1900	C0025896	W-57258	MNTBB7A99F6031982
77	FM ECO4 LIGHT+ 3G	867553056759012	10/12/2024	C0043874	DXB-D-91104	3N1CP5C94KL466720
78	FM ECO4 LIGHT+ 3G	869530045187990	1/0/1900	C0032152	S-49833	JTFHX02P0G0105972
79	FM ECO4 LIGHT+ 3G	863003042129999	10/12/2024	B0051780	P-91875	JN6BE6DS3L9062921
80	FM ECO4 LIGHT+ 3G	866381051074083	9/30/2021	C0037255	DXB-O-48797	2G113553XJ9102633
81	FM ECO4 LIGHT+ 3G	869530045204340	10/12/2024	B0031669	17-98312	JTGJX02PXG0066093

82	FM ECO4 LIGHT+ 3G	869530045263965	1/0/1900	C0019205	W-91802	RKLBB9HE0E5016560
83	FM ECO4 LIGHT+ 3G	863003042062950	10/12/2024	C0028695	C-16805	MDHBN7AD3GG712945
84	FM ECO4 LIGHT+ 3G	869530045142433	10/12/2024	C0046847	DXB-M-44819	MDHBN7AD0KG682425
85	TRACE5 LTM (Rev.A) 4G	863940058344311	10/12/2024	B0029536	DXB-P-46237	JL5B3J6P9GRP20411
86	FM ECO4 LIGHT+ 3G	867553056746985	6/8/2023	C0023635	DXB-I-66273	MDHBN7ADXFG710897
87	FM ECO4 LIGHT+ 3G	869530045185101	10/14/2024	C0019221	O-91801	MDHBN7AD9EG513282
88	FM ECO4 LIGHT+ 3G	869530045228323	11/7/2023	C0050388	DXB-Q-28173	MHKEF8BF6KK005737
89	FM ECO4 LIGHT+ 3G	869530045312887	2/23/2024	C0051393	E-46784	JTFLMFCP1L6002118
90	FM ECO4 LIGHT+ 3G	869530045164239	10/30/2023	C0033419	DXB-T-11873	JMYSRCY1AGU752636
91	FM ECO4 LIGHT+ 3G	869530045244437	Removed-30-06-2021	C0060359	AD-18-52171	1N4BL4A90NN339510
92	FM ECO4 LIGHT+ 3G	869530043186572	10/14/2024	C0043247	DXB-W-39837	MDHBN7AD6KG649235
93	FM ECO4 LIGHT+ 3G	869530045125461	11/7/2023	B0022704	O-52465	JTGF8518XE1069028
94	FM ECO4 LIGHT+ 3G	866381051070248	7/17/2023	C0034462	SHJ-3-55796	MDHBN7AD5GG745364
95	FM ECO4 LIGHT+ 3G	866381051074000	7/17/2023	C0034476	SHJ-3-55872	MMBMG45H6HH012177
96	FM ECO4 LIGHT+ 3G	869530045170111	10/14/2024	C0055478	DXB-S-92120	RKLBB0BE4L0025003
97	FM ECO4 LIGHT+ 3G	869530045200801	10/14/2024	C0019269	W-58497	RKLBB9HE8E5019755
98	FM ECO4 LIGHT+ 3G	866381051078852	10/14/2024	C0045089	DXB-E-49619	1N4AA6AP9JC381725
99	FM ECO4 LIGHT+ 3G	869530043220983	10/14/2024	C0050050	DXB-O-69809	MR2K19F37K1054333
100	FM ECO4 LIGHT+ 3G	866381051019179	1/0/1900	C0049882	DXB-O-71087	MHFDX8F51K0099293
101	FM ECO4 LIGHT+ 3G	869530045290554	1/0/1900	C0046155	AJM-B-3408	MHFku8F5S0K178529
102	FM ECO4 LIGHT+ 3G	869530043176094	11/9/2021	B0043064	DXB-W-40370	JL5BHJ6S5KRP20646
103	FM ECO4 LIGHT+ 3G	866381051055579	10/25/2023	B0032961	DXB-S-62172	JTGF85187G1079387
104	FM ECO4 LIGHT+ 3G	869530045148182	6/8/2023	C0045815	H-63191	VF14SRAB6KT508425
105	FM ECO4 LIGHT+ 3G	869530045291982	11/20/2023	B0026134	M-22843	KMJWA37R6GU749640
106	FM ECO4 LIGHT+ 3G	869530045139942	1/0/1900	C0042015	P-24128	MHFDX8F50J0091703
107	FM ECO4 LIGHT+ 3G	869530043203815	10/30/2023	C0034451	SHJ-3-55439	MHFDX8FSXH0081867
108	FM ECO4 LIGHT+ 3G	867553058469925	12/7/2023	C0047987	DXB-O-30645	MDHBN7AD8KG685959
109	FM ECO4 LIGHT+ 3G	869530045216039	11/20/2023	C0020740	J-24985	MR0FX22G0E1401479
110	FM ECO4 LIGHT+ 3G	867553059804393	10/18/2023	C0034242	AD-15-90161	JTNGE52M2H7141759
111	FM ECO4 LIGHT+ 3G	869530045187065	11/20/2023	C0042389	T-75469	MDHBN7AD5KG648965
112	FM ECO4 LIGHT+ 3G	867553058469776	10/14/2024	C0020751	DXB-P-64623	MR0FX22G3E1401315
113	FM ECO4 LIGHT+ 3G	866381051070156	12/7/2023	C0047966	DXB-O-28489	MDHBN7AD2KG685259
114	FM ECO4 LIGHT+ 3G	866381051067517	7/18/2023	C0034480	SHJ-3-55694	MMBMG35H3HH012583
115	FM ECO4 LIGHT+ 3G	869530045179666	10/14/2024	C0025898	10-77860	MNTBB7A9XF6032042
116	FM ECO4 LIGHT+ 3G	866381051030598	10/30/2023	C0036869	SHJ-3-77056	JTFLU71J9H7053842
117	FM ECO4 LIGHT+ 3G	867688039834324	1/0/1900	C0051823	A-12345	MDHBN7AD3LG686633
118	FM ECO4 LIGHT+ 3G	869530045245533	10/14/2024	C0042007	R-10754	MHFDX8F57J0091519
119	FM ECO4 LIGHT+ 3G	869530041899119	10/30/2023	B0048654	O-28792	KMJWA37R6LU089593
120	FM ECO4 LIGHT+ 3G	866381051067350	9/13/2023	C0034499	SHJ-3-55468	MHFDX8F55H0082134
121	FM ECO4 LIGHT+ 3G	869530045158801	11/20/2023	C0042387	DXB-T-76439	MDHBN7AD5KG648657
122	FM ECO4 LIGHT+ 3G	869530041933058	10/25/2023	B0027122	R-20665	JTGF85180F1073512
123	FM ECO4 LIGHT+ 3G	866381051073879	10/14/2024	C0047942	DXB-C-26802	5N1DR2M59KC575641

124	TRACE5 LTM (Rev.A) 4G	863257068941410	10/14/2024	C0062509	AD-6-54905	JTNB24HK6P3134533
125	FM ECO4 3G	867553058478637	12/27/2022	B0005659	AJM-A-97583	JN6FE54S47X438670
126	FM ECO4 LIGHT+ 3G	869530043176136	10/16/2024	C0042538	AD-11-56927	2G1135S36K9104753
127	FM ECO4 LIGHT+ 3G	869530045186422	10/16/2024	C0024774	15-83521	MDHBN7AD7FG716785
128	FM ECO4 LIGHT+ 3G	869530045243249	10/16/2024	C0050351	D-84023	MHKEF8BFXLK007573
129	FM ECO4 LIGHT+ 3G	869530045135189	Removed-01-Sept-2021	C0003145	AD-8-85506	JN6FE52S74X406441
130	FM ECO4 LIGHT+ 3G	869530045124365	10/16/2024	C0028417	R-88569	MR0HX8CD4G1343721
131	FM ECO4 LIGHT+ 3G	869530045268097	1/26/2023	C0003887	D-95793	JN6DD23S15X174492
132	FM ECO4 LIGHT+ 3G	869530045261431	10/16/2024	C0024765	15-85876	MDHBN7AD6FG717555
133	FM ECO4 LIGHT+ 3G	869530045139082	10/16/2024	C0010211	B-32388	6T1BE42K0AX650715
134	FM ECO4 LIGHT+ 3G	869530045135379	10/16/2024	C0046112	DXB-U-52865	JTNBF9HK2K3029269
135	FM ECO4 LIGHT+ 3G	869530045157845	8/15/2022	C0007272	AD-7-37502	MR0FX22G281309178
136	FM ECO4 LIGHT+ 3G	869530045212764	10/16/2024	C0021103	P-87262	MDHBN7AD6EG523493
137	FM ECO4 LIGHT+ 3G	869530045133697	1/26/2023	C0024778	15-83514	5N1AN0N60FN655267
138	FM ECO4 LIGHT+ 3G	869530041391836	10/16/2024	C0020141	P-57472	JL7B6E1P4EK008584ET1
139	FM ECO4 LIGHT+ 3G	869530045152333	10/16/2024	C0046125	DXB-H-58454	JTNBF9HK4K3031184
140	FM ECO4 LIGHT+ 3G	869530045288558	10/16/2024	C0050341	DXB-K-81724	MHKEF8BF3KK005923
141	FM ECO4 LIGHT+ 3G	869530045287220	10/16/2024	C0039209	AD-13-74922	MR0DB8CD5J0117391
142	FM ECO4 LIGHT+ 3G	867553053272910	10/16/2024	C0042460	DXB-U-90849	JTNBF9HK0K3020148
143	FM ECO4 LIGHT+ 3G	866381051073762	10/16/2024	C0030686	DXB-E-17360	MR0DX6CD8G0201414
144	FM ECO4 LIGHT+ 3G	869530045142946	Removed-02-Sept-2021	N/A	F-30836	3N6DD23S5EK055233
145	FM ECO4 LIGHT+ 3G	869530041372406	10/16/2024	C0030081	F-57827	3N6DD23XXGK010691
146	FM ECO4 LIGHT+ 3G	863003042087668	1/26/2023	C0007382	9-62344	6T1BE42K78X510610
147	FM ECO4 LIGHT+ 3G	869530045299183	7/14/2022	B0019983	P-34483	MB1PBFA0EE1M5127
148	FM ECO4 LIGHT+ 3G	869530045181860	10/16/2024	C0039870	RAK-C-19153	JTNBF9HK6J3003644
149	FM ECO4 LIGHT+ 3G	869530045214745	10/16/2024	C0027201	R-29205	RKLBB9HE7F5107553
150	FM ECO4 LIGHT+ 3G	867688036761264	5/18/2023	C0047690	14-38486	RLKB30BE8L0001686
151	FM ECO4 LIGHT+ 3G	869530045238900	10/16/2024	C0028442	R-88587	MR0DX6CD9G0010942
152	FM ECO4 LIGHT+ 3G	869530045122724	10/16/2024	C0017386	3-85144	6T1BF9FK8DX470052
153	FM ECO4 LIGHT+ 3G	869530041405339	10/16/2024	C0055993	I-95784	MDHBN7AD1LG725851
154	FM ECO4 LIGHT+ 3G	869530045313687	10/16/2024	C0052139	DXB-Q-80034	MHKEF8BF1LK009017
155	FM ECO4 LIGHT+ 3G	869530045242951	10/16/2024	C0030078	F-56587	3N6DD23X9GK011461
156	FM ECO43G	867553058477142	1/3/2023	C0026051	DXB-R-12956	MR0EX12G2F2355705
157	FM ECO43G	867553057630014	10/16/2024	B0030833	FUJ-C-25673	JTGSX23P3G6168329
158	TRACE5 LTM (Rev.A) 4G	863257067783227	10/16/2024	C0061769	DXB-E-95234	RKLBA0BE2N1004487
159	FM ECO4 LIGHT+ 3G	867688038864991	10/17/2024	C0051891	I-42934	MDHBN7AD9LG695532
160	FM ECO4 LIGHT+ 3G	869530045171408	10/17/2024	C0046023	I-47698	MALC281C4KM517616
161	FM ECO4 LIGHT+ 3G	869530045144983	10/17/2024	C0043775	SHJ-2-66310	MDHBN7AD8KG658390
162	FM ECO4 LIGHT+ 3G	869530041408390	10/17/2024	C0025769	W-88798	3N6DD23X9FK028369
163	FM ECO4 LIGHT+ 3G	869530045141633	10/17/2024	C0029332	C-28956	MR2KW9F31G1097462
164	FM ECO4 LIGHT+ 3G	869530045253503	10/17/2024	B0037480	3-80544	JTGF87184H6002525

165	FM ECO4 LIGHT+ 3G	869530045165673	10/17/2024	C0019261	H-17758	RKLBL9HE1E5204257
166	FM ECO4 LIGHT+ 3G	863257067933236	8/12/2022	B0032570	DXB-G-35474	JTGFB5188G1079723
167	FM ECO4 LIGHT+ 3G	869530045146764	10/17/2024	B0023750	C-97540	JTGJX02P6E5038713
168	FM ECO4 LIGHT+ 3G	869530045255813	Removed-02-Sept-2021	C0012463	N-77890	MR0EX19G6B3438158
169	FM ECO4 LIGHT+ 3G	869530045298169	10/17/2024	B0043738	2-10878	JTGSX22P5J6202148
170	FM ECO4 LIGHT+ 3G	869530045311590	10/17/2024	C0028419	R-88586	MR0HX8CD0G0890491
171	FM ECO4 LIGHT+ 3G	869530045114580	10/17/2024	C0043777	SHJ-66128	MDHBN7AD8KG658227
172	FM ECO4 LIGHT+ 3G	869530045145998	10/17/2024	B0056004	S-62086	JTGHN9CPXL6005700
173	FM ECO4 LIGHT+ 3G	869530045280142	10/17/2024	B0052585	Q-57824	JTGHN9CP3K6002653
174	FM ECO4 LIGHT+ 3G	867688038869818	10/17/2024	C0050554	15-68564	JTNBZ4HK5K3010466
175	FM ECO4 LIGHT+ 3G	869530045256860	10/17/2024	C0043802	SHJ-2-66153	MDHBN7ADXXKG658276
176	FM ECO4 LIGHT+ 3G	866381051086996	10/17/2024	C0043797	SHJ-2-66146	MDHBN7AD0KG662854
177	FM ECO4 LIGHT+ 3G	869530041403292	10/17/2024	C0019433	1-75403	JTFHX02P9E0084780
178	FM ECO4 LIGHT+ 3G	869530045126717	12/12/2023	C0044479	W-13417	MMBMG35H1JH029436
179	FM ECO4 LIGHT+ 3G	866381051067285	10/17/2024	C0046499	SHJ-3-69705	JTNBF9HK2K3031958
180	FM ECO4 LIGHT+ 3G	869530045251804	9/14/2022	C0048721	SHJ-3-57035	JTMR13FV4KD017730
181	FM ECO4 LIGHT+ 3G	869530041359643	10/17/2024	B0029204	1-76356	JTGJX02P5F5043970
182	FM ECO4 LIGHT+ 3G	869530045248305	10/28/2021	C0026482	E-64393	6T1BF9FKXGX593310
183	FM ECO4 LIGHT+ 3G	869530045134885	10/16/2024	H0055991	3-19639	WMA26WZZ3GM704310
184	FM ECO4 LIGHT+ 3G	869530045142011	2/21/2024	C0048352	O-30731	JE4LP21U5KU700734
185	FM ECO4 LIGHT+ 3G	866381051033394	12/7/2023	C0040726	DXB-V-67402	JL6B9H6J6HK011301
186	FM ECO4 LIGHT+ 3G	869530045267263	12/7/2023	C0047997	DXB-O-28524	MDHBN7ADXXKG685834
187	FM ECO4 LIGHT+ 3G	869530045145246	10/15/2024	C0028416	R-88581	MR0HX8CD1G0890693
188	FM ECO4 LIGHT+ 3G	867688036731960	5/25/2023	C0047574	16-34217	MROCX9CB4K3960273
189	FM ECO4 LIGHT+ 3G	869530045167869	12/7/2023	C0025250	2-44858	JN8AY2NY2F9122505
190	FM ECO4 LIGHT+ 3G	866381051031877	12/7/2023	C0040744	DXB-V-67395	JL6B9H6J9HK011874
191	FM ECO4 LIGHT+ 3G	867688036772154	5/25/2023	C0047686	14-38278	RLKB30BE0L0001682
192	FM ECO4 LIGHT+ 3G	869530045191570	10/15/2024	C0046935	DXB-L-53056	MDHBN7AD3KG682208
193	FM ECO4 LIGHT+ 3G	869530045131329	10/15/2024	C0052014	P-69144	VF1HSRMXXLA538579
194	FM ECO4 LIGHT+ 3G	869530045309438	12/7/2023	B0019118	A-16319	JTGJX02PXE5034504
195	FM ECO4 LIGHT+ 3G	867688036768657	5/25/2023	C0047458	16-34159	2G1135S33K9108548
196	FM ECO4 LIGHT+ 3G	869530045308877	11/19/2022	C0027167	R-10727	MHFXX42G8F5035560
197	TRACES LTM (Rev.A) 4G	863257068941444	10/15/2024	C0036908	DXB-U-29139	5N1CR2M86JC601682
198	FM ECO4 LIGHT+ 3G	869530045124076	8/2/2022	C0019464	7-12217	1GNSK6E08ER242849
199	FM ECO4 LIGHT+ 3G	866381051070511	10/30/2023	C0036854	SHJ-3-77196	MMBMG35H5HH026727
200	FM ECO4 LIGHT+ 3G	869530045136567	11/9/2021	0	MR0DX9CD3N2646131	MR0DX9CD3N2646131
201	FM ECO4 LIGHT+ 3G	869530045186182	2/23/2024	C0046582	C-67230	MDHBN7AD3KG680779
202	FM ECO4 LIGHT+ 3G	869530045191885	12/7/2023	C0047992	DXB-N-82344	MDHBN7ADXXKG685185
203	FM ECO4 LIGHT+ 3G	867688036772238	10/15/2024	C0047329	17-71275	JTEBU3FJ9KK169385
204	FM ECO4 LIGHT+ 3G	869530045115819	12/7/2023	C0052000	P-69091	VF1HSRMX4LA538500
205	FM ECO4 LIGHT+ 3G	869530045184930	2/23/2024	C0046579	DXB-C-39022	MDHBN7AD9KG681029
206	FM ECO4 LIGHT+ 3G	869530045309305	6/15/2023	B0012957	B-97546	JTGFB5185B1044145

207	TRACE5 LTM (Rev.A) 4G	864145065049742	10/18/2024	B0023551	I-61742	JL5B3J6P9FRN20076
208	FM ECO4 LIGHT+ 3G	863003042142216	10/18/2024	N/A	15-86461	RKLB89HE0F5075156
209	FM ECO4 LIGHT+ 3G	863257067940173	5/25/2023	B0049502	AD-9-71425	MB1PBEHD4KU0B1421
210	FM ECO4 LIGHT+ 3G	867688036749582	5/15/2023	B0053145	15-64136	LSFD132E8GC000970
211	FM ECO4 LIGHT+ 3G	869530045217300	10/18/2024	C0045778	H-32510	1N4BL4A94KC143920
212	FM ECO4 LIGHT+ 3G	869530045286958	12/15/2022	B0027911	K-63506	JN6BE6DS1G9017062
213	FM ECO4 LIGHT+ 3G	869530041908951	9/14/2023	B0013511	9-60462	JTGFB5187C1046030
214	FM ECO4 LIGHT+ 3G	867688039844596	5/26/2023	C0053144	11-23613	WV13TNSB0F6001080
215	FM ECO4 LIGHT+ 3G	869530045180326	9/7/2023	C0034049	T-57685	RKLBL9HEXG5255078
216	FM ECO4 LIGHT+ 3G	869530041916590	9/14/2023	B0015555	12-89255	JTGFB5182C1053192
217	FM ECO4 LIGHT+ 3G	869530045198161	9/14/2023	B0015616	12-22510	JTGFB5181C1053202
218	FM ECO4 LIGHT+ 3G	869530045267271	12/19/2022	C0029599	H-82271	MHKMC13F4FK019717
219	FM ECO4 LIGHT+ 3G	867688039844851	5/26/2023	C0047416	16-35288	JTFHX02P8K0122432
220	FM ECO4 LIGHT+ 3G	869530045150998	6/12/2023	B0026150	K-62041	KMJWA37R0GU749679
221	FM ECO4 LIGHT+ 3G	869530045132467	2/9/2023	C0046140	I-44328	MDHBN7AD8KG674668
222	FM ECO4 LIGHT+ 3G	867688036770760	5/25/2023	C0046756	14-58632	JTNBF4HK8K3030705
223	FM ECO4 LIGHT+ 3G	867553056751803	9/28/2023	C0053349	SHJ-43474	JN8BY2NY2L9305757
224	FM ECO4 LIGHT+ 3G	869530045285794	10/18/2024	C0036751	3-77162	RKLB89HE0H5189189
225	TRACE5 LTM (Rev.A) 4G	863257069031088	5/9/2023	B0053155	12-86972	LZYTATE60D1000318
226	FM ECO4 LIGHT+ 3G	869530045129364	10/18/2024	C0036750	3-77157	RKLB89HE2H5188982
227	FM ECO4 LIGHT+ 3G	869530045250863	10/21/2024	B0023560	L-54006	JL5B3JJ6P7FRN20108
228	FM ECO4 LIGHT+ 3G	867688039341767	10/21/2024	B0051779	P-91854	JN6BE6DS2L9063008
229	FM ECO4 LIGHT+ 3G	869530045245046	7/12/2023	C0044609	D-68847	MDHBN7AD6KG671431
230	FM ECO4 LIGHT+ 3G	869530045218894	9/14/2023	B0013978	11-34014	JTGFB5189C1047681
231	FM ECO4 LIGHT+ 3G	869530045206139	10/21/2024	B0043073	W-40456	JL5BHJ6S8KRP20656
232	FM ECO4 LIGHT+ 3G	869530045180623	3/1/2024	C0034085	DXB-T-63761	NHKMF52F3HK004516
233	FM ECO4 LIGHT+ 3G	869530045242027	9/21/2023	C0043688	W-69560	VSKDD3C28KA103750
234	FM ECO4 LIGHT+ 3G	867688036771420	5/17/2023	B0048880	12-96136	JTGFE7289K6270404
235	FM ECO4 LIGHT+ 3G	867553057649824	11/3/2023	C0041951	DXB-V-22486	MHFB29F30J2035060
236	FM ECO4 LIGHT+ 3G	869530045183148	9/20/2023	C0034080	DXB-T-65993	MHKMF53F0HK012474
237	FM ECO4 LIGHT+ 3G	867688036740813	5/18/2023	C0047621	6-23518	WD4WG3E18J3619527
238	FM ECO4 LIGHT+ 3G	863003048341804	7/14/2023	C0043829	10-64501	SALGA2BE3KA528315
239	FM ECO4 LIGHT+ 3G	869530043774245	11/11/2021	C0042112	DXB-N-59236	MHFB29F30J2033907
240	FM ECO4 LIGHT+ 3G	869530045180177	10/21/2024	B0057343	U-89867	MB1PAEHDXMU1B3599
241	FM ECO4 LIGHT+ 3G	867688036731242	5/25/2023	C0047662	9-70921	RLKB30BE4L0001118
242	FM ECO4 LIGHT+ 3G	869530043221874	11/3/2023	C0033539	DXB-T-36074	MR2B29F36H1021524
243	FM ECO4 LIGHT+ 3G	869530045310626	9/28/2023	C0042490	T-79410	MHFB29F34K2048573
244	FM ECO4 LIGHT+ 3G	869530045167844	5/31/2023	B0033354	17-62805	JL5B3J6P0GRP20992
245	FM ECO4 LIGHT+ 3G	869530045119431	11/3/2023	C0050081	DXB-Q-34230	MHKEF8BF0LK006934
246	FM ECO4 LIGHT+ 3G	867688036770505	5/25/2023	C0047476	16-34209	2G1135S31K9116521
247	FM ECO4 LIGHT+ 3G	867688036773376	5/19/2023	B0049137	12-96675	JTGFE7285K6270402
248	FM ECO4 LIGHT+ 3G	869530045243850	6/12/2023	B0043745	C-57706	JL5BHJ6S3KRP20757
249	FM ECO4 LIGHT+ 3G	869530045306004	10/21/2024	B0023569	L-55312	JL5B3J6P6FRN20097

250	FM ECO4 LIGHT+ 3G	869530045297963	5/21/2024	C0030173	L-7889	MDHBN7AD3GG721497
251	FM ECO4 LIGHT+ 3G	867553053335055	10/6/2023	C0054977	DXB-S-35846	MR0JX9CD5L4086102
252	FM ECO4 LIGHT+ 3G	867553057634974	6/19/2023	C0037461	AD-17-94045	JTMR9EV0HJ136844
253	FM ECO4 LIGHT+ 3G	869530045212996	9/28/2023	B0043046	W-40452	JL5BHJ6S3KRP20659
254	FM ECO4 LIGHT+ 3G	867688036760712	5/25/2023	B0049132	10-35810	JTGFE7289K6270399
255	FM ECO4 LIGHT+ 3G	867688039341171	9/21/2023	H0051645	F-24691	MEC201DP5LP039239
256	FM ECO4 LIGHT+ 3G	867688036770604	5/19/2023	C0046755	14-58278	JTNBF4HK7K3030985
257	FM ECO4 LIGHT+ 3G	869530045210388	6/12/2023	C0044633	D-46933	MDHBN7AD9KG671567
258	FM ECO4 LIGHT+ 3G	867688038863480	9/21/2023	C0051924	K-12695	JL6B6E6P9HK018688
259	FM ECO4 LIGHT+ 3G	869530045275621	10/21/2024	B0046267	H-27829	JL5BHJ6S3KRP20853
260	FM ECO4 LIGHT+ 3G	869530045177199	10/21/2024	B0043964	W-58540	JL5BHJ6S0KRP20778
261	FM ECO4 LIGHT+ 3G	866381051068408	7/18/2023	C0034620	SHJ-3-56452	MDHBN7AD4GG745162
262	FM ECO4 LIGHT+ 3G	869530045199797	10/21/2024	B0043969	W-91772	JL5BHJ6S3KRP20562
263	FM ECO4 LIGHT+ 3G	869530045314131	4/10/2023	C0046690	AD-17-70362	JTNBF9HK1K3029408
264	FM ECO4 LIGHT+ 3G	869530045240526	5/23/2023	B0015235	9-53159	JTGFB5186C1052188
265	FM ECO4 LIGHT+ 3G	867688036731846	5/25/2023	C0046751	14-51778	JTNBF4HK6K3030542
266	FM ECO4 LIGHT+ 3G	869530045144066	9/28/2023	B0029618	J-61046	JN6EW12S7FZ040019
267	FM ECO4 LIGHT+ 3G	869530045201049	11/17/2021	B0049261	DXB-M-71168	JTGFE7280K6270257
268	FM ECO4 LIGHT+ 3G	867688034489819	5/17/2023	B0049965	14-59818	LSFD132E0LC000052
269	FM ECO4 LIGHT+ 3G	867688038844266	9/20/2023	C0051923	DXB-K-41295	JL6B6E6P0HK018644
270	FM ECO4 LIGHT+ 3G	869530045197494	11/16/2021	B0025472	DXB-J-41978	JTGFB5184F1071410
271	FM ECO4 LIGHT+ 3G	869530045209679	11/3/2023	C0044732	AD-12-90284	JHHZCP2H1KK010129
272	FM ECO4 LIGHT+ 3G	869530045119753	7/17/2023	C0044623	D-47299	MDHBN7AD8KG671298
273	FM ECO4 LIGHT+ 3G	869530041909454	9/14/2023	B0015249	12-17627	JTGFB5186C1052434
274	FM ECO4 LIGHT+ 3G	863003048305072	5/26/2023	B0026202	11-16659	KMJWA37R9GU750197
275	FM ECO4 LIGHT+ 3G	869530045129240	9/28/2023	C0050096	G-18825	MHKEF8BF6LK006551
276	FM ECO4 LIGHT+ 3G	868899043953906	5/23/2023	B0013882	8-83247	JTGFB5188C1047462
277	FM ECO4 LIGHT+ 3G	869530043177076	10/25/2023	C0043868	DXB-D-92710	MDHBN7AD8KG648698
278	FM ECO4 LIGHT+ 3G	869530045299704	10/27/2023	C0044476	C-60933	JE3AB36U4HU714318
279	TRACE5 LTM (Rev.A) 4G	869084061831354	5/22/2023	C0047685	14-38259	RLKB30BE6L0001685
280	TRACE5 LTM (Rev.A) 4G	869084063964260	5/19/2023	C0047655	9-70856	RLKB30BE2L0001389
281	FM ECO4 LIGHT+ 3G	869530043205356	10/24/2024	C0047261	AD-9-70689	JHHZCP2H7KK010569
282	FM ECO4 LIGHT+ 3G	869530043176060	10/24/2024	C0050960	AD-17-46379	JHHZCP2H8LK010968
283	FM ECO4 LIGHT+ 3G	869530045183213	10/24/2024	C0047243	AD-10-43094	JHHZCP2H3KK010520
284	FM ECO4 LIGHT+ 3G	869530043175609	10/25/2024	C0051362	AD-6-47340	JHHZCP2H0KK010767
285	FM ECO4 LIGHT+ 3G	869530043204631	10/24/2024	C0045456	AD-16-44516	JHHZCP2H5KK010084
286	FM ECO4 LIGHT+ 3G	869530043176490	10/25/2024	C0046205	AD-16-44502	JHHZCP2H8KK010337
287	FM ECO4 LIGHT+ 3G	867553057635641	10/24/2024	C0045454	AD-16-44539	JHHZCP2H6KK010076
288	FM ECO4 LIGHT+ 3G	869530043177027	10/24/2024	C0047265	AD-9-70874	JHHZCP2H0KK010574
289	FM ECO4 LIGHT+ 3G	869530045143787	10/24/2024	C0047264	AD-10-43106	JHHZCP2H9KK010573
290	FM ECO4 LIGHT+ 3G	869530043778154	10/24/2024	C0056077	AD-7-35394	JHHZCP2H8LK012428
291	FM ECO4 LIGHT+ 3G	867553057650004	10/24/2024	C0050956	AD-17-78146	JHHZCP2H6LK010953
292	FM ECO4 LIGHT+ 3G	867553053328993	10/25/2024	C0050964	AD-17-39730	JHHZCP2H3LK010991

293	FM ECO4 LIGHT+ 3G	867553057634149	10/24/2024	C0045455	AD-16-44530	JHHZCP2HXKK010078
294	FM ECO4 LIGHT+ 3G	867553057659682	10/25/2024	C0047229	AD-7-71036	JHHZCP2H2KK010236
295	FM ECO4 LIGHT+ 3G	867553053276937	10/24/2024	C0045453	AD-16-44571	JHHZCP2H4KK010075
296	FM ECO4 LIGHT+ 3G	869530041387297	10/25/2024	C0050951	AD-8-67632	JHHZCP2H3LK010926
297	FM ECO4 LIGHT+ 3G	867553053335477	10/24/2024	C0056081	AD-7-35327	JHHZCP2H7LK012436
298	FM ECO4 LIGHT+ 3G	869530043205273	10/24/2024	C0047501	AD-9-70914	JHHZCP2H9KK010363
299	FM ECO4 LIGHT+ 3G	869530041911120	1/0/1900	B0025894	A-59293	MB1PBEFAXFUBA0881
300	FM ECO4 LIGHT+ 3G	869530045153539	6/20/2023	C0020620	H-98519	3N6DD23S5EK067852
301	FM ECO4 LIGHT+ 3G	869530043198908	10/26/2024	C0058793	SHJ-3-71446	MR0DX9CD8M2645281
302	FM ECO4 LIGHT+ 3G	869530045290067	10/26/2024	C0036361	DXB-L-81453	JL7B6E1P8HK006941
303	FM ECO4 LIGHT+ 3G	869530045116528	10/26/2024	C0036380	SHJ-2-87625	RKLB89HEXH5195453
304	FM ECO4 LIGHT+ 3G	869530045255987	10/26/2024	C0039290	DXB-E-65612	JN6BE6BS5J9030195
305	FM ECO4 LIGHT+ 3G	867688036746307	10/26/2024	C0049543	6-66915	JTNBZ4HK1K3009928
306	FM ECO4 LIGHT+ 3G	869530045186083	10/26/2024	C0027019	16-94864	6T1BF9FK8GX588414
307	FM ECO4 LIGHT+ 3G	869530045145261	Removed- 05-Sept- 2021	C0009994	10-29154	6T1BE42K8AX633614
308	FM ECO4 LIGHT+ 3G	869530045278294	9/14/2022	C0017168	C-48961	6T1BF9FK4DX465107
309	FM ECO4 LIGHT+ 3G	869530041908746	4/1/2022	C0040152	DXB-V-39916	2G1135S34J9140231
310	FM ECO 4 MG ET	867553056785405	10/26/2024	C0058816	SHJ-3-78568	MR0DX9CD8M2645264
311	FM ECO 4 MG ET	867553057596223	1/26/2023	C0013460	RAK-B-86804	MNTDD22S7C6002161
312	FM ECO4 LIGHT+ 3G	869530045116270	1/26/2023	C0008234	SHJ-2-10729	JN6BY15Y89A508257
313	FM ECO4 LIGHT+ 3G	869530045149446	10/28/2024	C0043857	DXB-W-91839	3N1CP5C90KL466231
314	FM ECO4 LIGHT+ 3G	867688038824672	10/28/2024	C0050544	14-28579	4T1BZ1FB2KU034333
315	FM ECO4 LIGHT+ 3G	869530041401205	10/28/2024	B0031363	S-42181	MB1PBEFA5GUBA4452
316	FM ECO4 LIGHT+ 3G	869530045314214	11/1/2024	C0046730	AD-7-72658	JTNBF4HK5K3032153
317	FM ECO4 LIGHT+ 3G	869530043773809	11/1/2024	C0056813	AD-13-55906	RKLB80BE8L0027045
318	FM ECO4 LIGHT+ 3G	869530043802491	11/1/2024	C0056995	AD-12-59708	JTNBF9HK3L3056949
319	FM ECO4 LIGHT+ 3G	867553056760481	11/1/2024	C0056223	AD-12-43550	JTNBF9HK2L3055565
320	FM ECO4 LIGHT+ 3G	867688036751877	1/0/1900	C0055410	AD-16-93806	JTNBF9HKXL3050386
321	FM ECO4 LIGHT+ 3G	869530045281199	11/1/2024	C0055731	AD-15-85634	RKLB80BE8L0026574
322	FM ECO4 LIGHT+ 3G	869530045142441	11/1/2024	C0056822	AD-13-55791	RKLB80BE7L0025156
323	FM ECO4 LIGHT+ 3G	869530043778014	11/1/2024	C0056814	AD-16-53246	RKLB80BE7L0025576
324	FM ECO4 LIGHT+ 3G	869530045281306	11/1/2024	C0056852	AD-16-56979	RKLB80BE8L0025036
325	FM ECO4 LIGHT+ 3G	867553053372595	11/1/2024	C0056817	AD-13-55904	RKLB80BE7L0027960
326	FM ECO4 LIGHT+ 3G	869530045281058	11/1/2024	C0056851	AD-13-55843	RKLB80BEXL0027676
327	FM ECO4 LIGHT+ 3G	867553053262853	11/1/2024	C0046726	AD-7-72682	JTNBF9HK9K3031892
328	FM ECO4 LIGHT+ 3G	869530045290828	11/1/2024	C0055730	AD-15-64806	RKLB80BE3L0026594
329	FM ECO4 LIGHT+ 3G	869530045261993	11/1/2024	C0040121	AD-8-69054	MHFKU8FS0J0175617
330	FM ECO4 LIGHT+ 3G	869530045280274	11/1/2024	C0056819	AD-13-55846	RKLB80BEXL0027886
331	FM ECO4 LIGHT+ 3G	869530045149974	11/1/2024	C0036458	AD-15-87021	4T1BK1EB4HU265121
332	FM ECO4 LIGHT+ 3G	868899043909247	11/1/2024	C0054837	16-31376	JTMHU01J2L4196518
333	FM ECO4 LIGHT+ 3G	868899043910872	11/1/2024	C0054838	14-82719	2G1135S39K9155180
334	FM ECO4 LIGHT+ 3G	867688036773152	5/18/2023	C0047672	9-70751	RLKB30BE1L0001402

335	FM ECO4 LIGHT+ 3G	869530045191844	11/1/2024	C0036456	AD-15-84337	RKLBB9HE5H5189043
336	FM ECO4 LIGHT+ 3G	867688039844828	5/23/2023	C0047468	14-40584	2G1135S30K9123539
337	FM ECO4 LIGHT+ 3G	868899043908066	11/1/2024	C0055022	6-43795	JN8BY2NY6L9313585
338	FM ECO4 LIGHT+ 3G	869530045307671	4/4/2023	C0051599	14-28706	MHF6X8EM2L0229440
339	FM ECO4 LIGHT+ 3G	868899046744138	11/1/2024	C0056706	7-37850	JTNBF4HK6L3057290
340	FM ECO4 LIGHT+ 3G	869530045244551	11/3/2022	C0033433	17-55190	2G1155S30H9112334
341	FM ECO4 LIGHT+ 3G	868899043910674	11/1/2024	C0054836	16-31285	JTMHU01J5L4196433
342	FM ECO4 LIGHT+ 3G	869530045114036	11/1/2024	C0036457	AD-15-85917	4T1BK1EB0HU260613
343	FM ECO4 LIGHT+ 3G	869530045134307	11/1/2024	N/A	6-72294	RKLBL9HE7K5265642
344	FM ECO4 LIGHT+ 3G	868899043908199	11/1/2024	C0055023	6-43803	JN8BY2NY9L9315668
345	FM ECO4 LIGHT+ 3G	867688036758104	2/12/2020	B0053051	13-91445	LSFD132E3FC000938
346	FM ECO4 LIGHT+ 3G	869530045240468	11/1/2024	B0055515	9-54203	JTGHN9CP2L6004993
347	FM ECO4 LIGHT+ 3G	869530043176920	11/1/2024	C0046694	AD-6-27106	JTNBF9HK1K3031174
348	TRACE5 LTM (Rev.A) 4G	863940058748420	11/1/2024	C0059932	AD-15-94067	1N4BL4A99NN325962
349	TRACE5 LTM (Rev.A) 4G	863940058755615	11/1/2024	C0059929	AD-15-94183	1N4BL4A98NN324835
350	TRACE5 LTM (Rev.A) 4G	863257067805384	4/4/2023	C0043843	AD-13-35056	MDHBN7AD4KG656040
351	TRACE5 LTM (Rev.A) 4G	863257067805616	4/4/2023	C0043840	AD-13-35058	MDHBN7ADXKG662697
352	TRACE5 LTM (Rev.A) 4G	863940058639165	11/1/2024	C0059926	AD-15-94189	1N4BL4A97NN325927
353	TRACE5 LTM (Rev.A) 4G	863940058255467	5/18/2022	C0060801	AD-18-46452	MNTAD3N08N6003356
354	TRACE5 LTM (Rev.A) 4G	863257067808172	11/1/2024	C0061628	AD-18-38630	1N4BL4A92NN404275
355	TRACE5 LTM (Rev.A) 4G	863257067805566	4/4/2023	C0043841	AD-13-35059	MDHBN7ADXKG662831
356	TRACE5 LTM (Rev.A) 4G	863940058757991	11/1/2024	C0060132	AD-50-83677	JTNB29HK6N3118391
357	FM ECO4 LIGHT+ 3G	869530045152473	11/2/2024	C0018535	11-52680	MR0FX22GXD1380297
358	FM ECO4 LIGHT+ 3G	869530045160435	11/2/2024	C0016919	10-54796	MR0EX12G5D2340399
359	FM ECO4 LIGHT+ 3G	869530045246275	11/2/2024	C0017026	10-30178	JTFHX02P6D0070530
360	FM ECO4 LIGHT+ 3G	869530045134935	11/2/2024	C0021730	14-69548	JTFHX02P6E0087846
361	FM ECO4 LIGHT+ 3G	869530045144876	11/2/2024	C0016928	10-74098	MR0EX12GXD2340527
362	FM ECO4 LIGHT+ 3G	869530045248727	11/2/2024	B0035201	6-87137	MB1PBFA7HU0A5985
363	FM ECO4 LIGHT+ 3G	869530045191000	11/2/2024	C0029486	AD-16-62757	MR0JB6CDXG1750110
364	FM ECO4 LIGHT+ 3G	869530045170608	3/1/2023	B0036462	17-93830	JTGFK7185H6000279
365	FM ECO4 LIGHT+ 3G	869530045200736	11/2/2024	C0029724	AD-16-49920	MR0CX6CD6G0160289
366	FM ECO4 LIGHT+ 3G	869530045290448	11/2/2024	C0029485	AD-16-62764	MR0CX6CDXG0290513
367	FM ECO4 LIGHT+ 3G	869530045199094	11/2/2024	C0041119	AD-11-70172	MR0JX9CD4K4085103
368	FM ECO4 LIGHT+ 3G	867688039781293	5/9/2023	B0049972	14-76933	LSFD132E3LC000059
369	FM ECO4 LIGHT+ 3G	869530045186794	11/2/2024	C0033256	AD-17-67312	MR0HX8CD8G0905173
370	FM ECO4 LIGHT+ 3G	869530045190903	11/2/2024	C0029484	AD-16-62761	MR0CX6CD9G0160318
371	FM ECO4 LIGHT+ 3G	869530045158728	11/2/2024	H0031695	AD-17-62808	JL6B6E6P2GK011466
372	FM ECO4 LIGHT+ 3G	869530043186614	5/25/2023	C0004147	SHJ-17713	JN6DD23S45X178004
373	FM ECO4 LIGHT+ 3G	869530045179617	11/2/2024	C0025770	16-21908	3N6DD23XXFK030048
374	FM ECO4 LIGHT+ 3G	869530045133267	5/25/2023	C0045893	15-89538	JTNBF9HK0K3029089
375	FM ECO4 LIGHT+ 3G	867553057657504	11/2/2024	C0036409	DXB-M-26396	6T1BF9FK2HX692317
376	FM ECO4 LIGHT+ 3G	869530045291529	11/2/2024	C0016861	9-25180	6T1BF9FK7DX450990
377	FM ECO4 LIGHT+ 3G	869530043187083	11/2/2024	C0030703	DXB-E-40844	MR0DX6CD0G0011591

378	FM ECO4 LIGHT+ 3G	869530045277866	11/2/2024	C0028918	N-30078	MDHBN7AD2GG710765
379	FM ECO4 LIGHT+ 3G	869530045223852	11/2/2024	C0020561	6-15309	6T1BF9FK8EX504282
380	FM ECO4 LIGHT+ 3G	869530045180334	11/2/2024	C0014391	AD-17-75679	MR0FX22GXC1073405
381	FM ECO4 LIGHT+ 3G	869530045202690	11/2/2024	C0053847	50845-1-AbuDhabi	MEC201DP3LP041006
382	FM ECO4 LIGHT+ 3G	869530045312606	11/2/2024	C0041118	AD-5-63870	MR0JX9CD1K4085057
383	FM ECO4 LIGHT+ 3G	869530045182991	11/2/2024	C0014490	17-75674	MROFX22G9C1344468
384	FM ECO4 LIGHT+ 3G	866381051040621	6/15/2023	C0024071	AD-12-26481	JN8AY2NY2F9115764
385	FM ECO4 LIGHT+ 3G	866381051092929	11/2/2024	C0026024	DXB-Q-17309	MR0CX12G0F0127799
386	FM ECO4 LIGHT+ 3G	869530045158413	11/2/2024	C0029483	AD-16-62759	MR0CX6CD4G0160324
387	FM ECO4 LIGHT+ 3G	869530045119910	11/2/2024	C0011647	10-90592	JTFHX02P9A0054351
388	FM ECO4 LIGHT+ 3G	869530045123078	11/2/2024	C0016918	10-54861	MR0EX12G5D2340368
389	FM ECO4 LIGHT+ 3G	869530045152945	11/2/2024	C0016803	AD-6-24708	MR0FX22G3D1370727
390	FM ECO4 LIGHT+ 3G	869530045229131	4/29/2022	C0008461	WHITE-92375	JTDBR42E899024778
391	FM ECO4 LIGHT+ 3G	869530045186901	6/16/2023	B0031526	Q-70861	JN6BE6DS5G9020739
392	FM ECO4 LIGHT+ 3G	869530045170590	11/5/2024	C0056749	DXB-C-26809	1GNSK7ECXLR260184
393	FM ECO4 LIGHT+ 3G	867688037008756	11/5/2024	B0051537	C-38854	JNGBE6D53L9063079
394	FM ECO4 LIGHT+ 3G	867688038864801	11/5/2024	C0051013	P-44026	MNTBB7A93K6066138
395	FM ECO4 LIGHT+ 3G	869530045221997	11/5/2024	C0056644	DXB-R-61145	JN8BY2NY1L9318239
396	FM ECO4 LIGHT+ 3G	869530045192800	11/5/2024	C0047420	DXB-M-72157	JTMHU01J2K4180592
397	TRACES LTM (Rev.A) 4G	863257068937467	11/5/2024	C0062515	AD-6-54787	JTNB24HK9P3134882
398	FM ECO4 LIGHT+ 3G	869530045255011	11/5/2024	C0044575	DXB-D-20834	MHFDX8FS1K0096667
399	FM ECO4 LIGHT+ 3G	867688038824615	11/5/2024	C0051012	P-44029	MNTBB7A91K6066431
400	FM ECO4 LIGHT+ 3G	869530045294143	11/5/2024	C0037827	U-66975	RKLBB9HEXJ5204772
401	FM ECO4 LIGHT+ 3G	869530045291180	2/21/2024	C0042807	W-98312	JTFHX02P8J0121201
402	FM ECO4 LIGHT+ 3G	867553058475773	8/10/2022	C0046016	DXB-I-17472	MALC741C8KM117262
403	FM ECO4 LIGHT+ 3G	869530045147218	11/9/2021	C0059295	DXB-P-13041	1N4BL4A96MN404780
404	FM ECO4 LIGHT+ 3G	869530045180342	11/6/2024	C0045024	DXB-C-80758	MHFDX8FS6K0096552
405	FM ECO4 LIGHT+ 3G	867688039835990	11/6/2024	C0051024	P-44021	MNTBB7A95K6066237
406	FM ECO4 LIGHT+ 3G	869530045191646	11/6/2024	C0057312	3-24922	MDHBN7ADXLG743829
407	FM ECO4 LIGHT+ 3G	869530045165400	11/6/2024	B0017432	L-74882	JTGJX02P7D5030392
408	FM ECO4 LIGHT+ 3G	869530041417078	2/2/2023	B0030936	S-14822	MB1PBFA1GUEA3646
409	FM ECO4 LIGHT+ 3G	869530045281348	11/6/2024	B0056727	RAK-C-95278	JN6BE6DS8L9064602
410	FM ECO4 LIGHT+ 3G	869530045195159	11/6/2024	C0036317	N-99831	RKLBB9HE6H5190833
411	FM ECO4 LIGHT+ 3G	869530045179658	11/7/2024	H0028414	C-57069	JL6B6E6P4FK026484
412	FM ECO4 LIGHT+ 3G	869530045134778	8/8/2022	C0030120	DXB-G-35093	JTGF85187F1072843
413	FM ECO4 LIGHT+ 3G	866381051071600	9/7/2023	C0046144	DXB-E-87262	MDHBN7AD8KG675433
414	FM ECO4 LIGHT+ 3G	863003048306252	11/7/2024	C0056678	15-50328	RKLBA0BE1L1001836
415	FM ECO4 LIGHT+ 3G	869530043186457	7/11/2023	C0034446	SHJ-3-55489	JTFHX02P9G0110815
416	FM ECO4 LIGHT+ 3G	869530045219181	9/6/2022	B0061317	DXB-Y-82072	JL5BHJ6S2NRP22293
417	FM ECO4 LIGHT+ 3G	869530041908597	10/28/2021	B0049267	DXB-M-72679	JTGFE7289K6270273
418	FM ECO4 LIGHT+ 3G	869530041909868	11/7/2024	B0036818	L-65731	MB1PAEHD4HUDA6646
419	FM ECO4 LIGHT+ 3G	869530045291925	11/7/2024	B0036816	L-65734	MB1PAEHD8HUDA6777
420	FM ECO4 LIGHT+ 3G	869530045122575	11/7/2024	C0055406	10-73936	JTNBF9HK6L3050403

421	FM ECO4 LIGHT+ 3G	866381051055553	7/11/2023	C0028471	DXB-H-95177	JTEBU9FJ0GK095414
422	FM ECO4 LIGHT+ 3G	868899043927850	11/7/2024	B0056057	Q-95580	JN6BE6DS6L9063528
423	FM ECO4 LIGHT+ 3G	869530045299589	11/7/2024	B0036817	L-65732	MB1PAEHD8HUCA6811
424	FM ECO4 LIGHT+ 3G	869530045290901	2/27/2024	C0055057	SHJ-2-59767	KL1ZB5DS1LB301693
425	FM ECO4 LIGHT+ 3G	869530045138969	11/7/2024	C0044563	DXB-D-26016	MHFDX8FS8K0096486
426	FM ECO4 LIGHT+ 3G	866381051090584	11/7/2024	C0055966	DXB-I-94593	MEC201DP0LP040458
427	FM ECO4 LIGHT+ 3G	869530045292923	11/7/2024	B0036815	L-65724	MB1PAEHD4HUCA6868
428	FM ECO4 LIGHT+ 3G	867553057625816	11/7/2024	B0051400	DXB-P-55430	MB1PBEHDXLU0B2087
429	FM ECO4 LIGHT+ 3G	869530045275902	11/7/2024	B0030298	1-37234	MB1PBEFA0GUEA3475
430	FM ECO4 LIGHT+ 3G	866381051068390	11/7/2024	B0032845	DXB-F-54315	JTGJX02P3G5046366
431	FM ECO4 LIGHT+ 3G	867553058480633	10/25/2021	B0026007	DXB-D-12979	JTGJX02P0F5040586
432	FM ECO4 LIGHT+ 3G	866381051067905	11/7/2024	B0055812	DXB-D-23035	JL5BHJ6S0LRP21687
433	FM ECO4 LIGHT+ 3G	869530045157936	11/7/2024	C0045027	C-80759	MHFDX8FS4K0097022
434	TRACE5 IP-67 LTM (Rev.A) 4G	863257069033563	11/7/2024	B0062612	DXB-Z-33845	MB1PBEHD9NU1B7142
435	TRACE5 IP-67 LTM (Rev.A) 4G	863257069020990	11/7/2024	C0062665	AJM-B-2963	JN1BT2MU4NW025760
436	TRACE5 LTM (Rev.A) 4G	863257067808727	1/0/1900	C0059647	DXB-O-73649	MK2K6T1Y0MN001160
437	TRACE5 LTM (Rev.A) 4G	863257069131391	11/7/2024	C0062298	AD-15-80738	JN1BT2MU3NW025751
438	TRACE5 LTM (Rev.A) 4G	863257067789323	11/7/2024	C0059305	DXB-C-73719	MA3NC2B12NA394131
439	FM ECO4 LIGHT+ 3G	869530045135262	11/8/2024	C0057568	DXB-T-90525	JN6BE6AS8M9032853
440	FM ECO4 LIGHT+ 3G	869530045290059	10/4/2021	C0042128	DXB-N-93725	MHFDX8FS8K0092583
441	FM ECO4 LIGHT+ 3G	869530041931664	11/8/2024	C0040668	V-15569	MHFKU8FS6J0176139
442	FM ECO4 LIGHT+ 3G	869530045114903	11/8/2024	C0045913	DXB-H-65147	MHKEF8BF2KK004648
443	FM ECO4 LIGHT+ 3G	869530045118409	6/7/2023	C0033896	SHJ-3-50297	JL6B6E6P3GK021469
444	FM ECO4 LIGHT+ 3G	869530045289994	11/8/2024	C0045910	DXB-C-12864	MHKEF8BF2KK004598
445	FM ECO4 LIGHT+ 3G	869530045200629	11/8/2024	C0057521	AD-14-25314	MHKEF8BF8LK016434
446	FM ECO4 LIGHT+ 3G	869530041908720	11/8/2024	C0044478	C-60849	JE3AB36U5HU714327
447	FM ECO4 LIGHT+ 3G	869530045115660	9/7/2023	C0042832	W-10936	MDHBN7AD1KG652382
448	FM ECO4 LIGHT+ 3G	869530041402518	6/5/2024	B0021255	P-79491	JL5B3J6P1ERM10900
449	FM ECO4 LIGHT+ 3G	869530045281082	11/8/2024	C0039610	DXB-K-38078	JTFHX02P8H0115098
450	FM ECO4 LIGHT+ 3G	867688036612533	11/8/2024	C0045957	I-81716	MHKEF8BF9KK004050
451	FM ECO4 LIGHT+ 3G	869530045291230	11/8/2024	C0046861	J-86455	MDHBN7AD0KG682232
452	FM ECO4 LIGHT+ 3G	867688037018581	11/8/2024	C0046945	L-53923	MDHBN7AD3KG682354
453	FM ECO4 LIGHT+ 3G	869530045120504	11/8/2024	N/A	S-35932	JN6BE6DS2L903896
454	FM ECO4 LIGHT+ 3G	869530045182439	10/24/2022	B0026760	DXB-R-20530	JTGJX02P2F5042100
455	FM ECO4 LIGHT+ 3G	866381051068499	8/12/2022	C0038701	SHJ-3-36807	JTFHX02P2H0114738
456	FM ECO4 LIGHT+ 3G	867553057661944	10/24/2023	C0037763	AD-11-46551	JL6B9H6J6GK025665
457	FM ECO4 LIGHT+ 3G	866381051098256	11/8/2024	C0053304	DXB-N-17411	MHKEF8BF1LK010880
458	FM ECO4 LIGHT+ 3G	867553057635450	11/8/2024	C0046589	DXB-C-69936	MDHBN7ADXXKG680813
459	FM ECO4 LIGHT+ 3G	863003042151761	11/8/2024	C0050354	9-58613	5N1DR2M59KC575042
460	FM ECO4 LIGHT+ 3G	869530045280225	11/8/2024	C0056618	DXB-R-46351	JTHB21B15L2090316
461	FM ECO4 LIGHT+ 3G	867553059803106	11/8/2024	C0047273	DXB-M-43376	MMBMG35H3KH034638
462	FM ECO4 LIGHT+ 3G	869530045180565	11/8/2024	C0046559	DXB-J-57036	JN8BY2NY4K9192098

463	FM ECO4 LIGHT+ 3G	869530041991940	11/8/2024	C0041138	V-84609	WDDUG8DB0JA387786
464	FM ECO4 LIGHT+ 3G	866381051098454	11/8/2024	C0048382	DXB-O-28704	JE4LP21U1KU701217
465	FM ECO4 LIGHT+ 3G	869530045209497	11/8/2024	0	DXB-R-37936	MHKEF8BF4LK015345
466	FM ECO4 LIGHT+ 3G	869530045117070	6/10/2023	B0033972	DXB-T-49610	JTGFB5188G1080192
467	FM ECO4 LIGHT+ 3G	866381051025242	11/8/2024	C0038378	DXB-G-47739	JN1BT2MU2JW010829
468	FM ECO4 LIGHT+ 3G	867553056712854	11/8/2024	C0057004	DXB-U-83063	JTNBF9HK7L3056811
469	FM ECO4 LIGHT+ 3G	869530045211931	11/8/2024	C0048390	DXB-O-28694	JE4LP21U7KU701271
470	TRACE5 LTM (Rev.A) 4G	863257067798894	9/7/2023	C0028718	DXB-K-29932	MDHBN7AD9GG710312
471	TRACE5 LTM (Rev.A) 4G	863257067905838	11/8/2024	C0039582	AD-5-54721	WDDUG8DB9JA374132
472	FM ECO4 LIGHT+ 3G	869530045152457	11/8/2024	C0046554	DXB-J-56894	JN8BY2NY6K9212481
473	FM ECO4 LIGHT+ 3G	868899043799259	11/9/2024	B0051795	P-91836	JN6BE6DSXL9062947
474	FM ECO4 LIGHT+ 3G	869530041916939	11/9/2024	B0055807	D-67349	JN6BE6DS2L9063266
475	FM ECO4 LIGHT+ 3G	868899046768673	11/9/2024	B0055685	J-82046	JN6BE6DSXL9064066
476	FM ECO4 LIGHT+ 3G	863003042155747	11/9/2024	B0055673	D-94084	JN6BE6DS7L9063988
477	FM ECO4 LIGHT+ 3G	868899046782302	11/9/2024	B0055709	C-21176	JN6BE6DS8L9063949
478	FM ECO4 LIGHT+ 3G	868899046769291	11/9/2024	B0055669	F-35939	JN6BE6DS1L9063999
479	FM ECO4 LIGHT+ 3G	863003042169912	11/9/2024	C0055551	S 29443	VF1HSRMX4LA567074
480	FM ECO4 LIGHT+ 3G	863003042152314	11/9/2024	B0055663	M-65510	JN6BE6DS8L9063210
481	FM ECO4 LIGHT+ 3G	863003042152595	11/9/2024	B0055445	L-69208	MB1PAEHD6LU1B2786
482	FM ECO4 LIGHT+ 3G	863003042146118	11/9/2024	C0055558	Q 99325	VF1HSRMX1LA564522
483	FM ECO4 LIGHT+ 3G	868899046736498	11/9/2024	B0055687	D-23208	JN6BE6DS1L9064134
484	FM ECO4 LIGHT+ 3G	863003042117051	11/9/2024	B0055698	C-88526	JN6BE6DS1L9063050
485	FM ECO4 LIGHT+ 3G	866381051070107	11/9/2024	B0033115	S-73785	JTGFB5181G1080017
486	FM ECO4 LIGHT+ 3G	863003042151043	11/9/2024	B0055713	Q-86189	JN6BE6DS8L9063238
487	FM ECO4 LIGHT+ 3G	868899046735219	11/9/2024	B0055695	D-89126	JN6BE6DS9L9064138
488	FM ECO4 LIGHT+ 3G	868899046772964	11/9/2024	B0055710	Q-86358	JN6BE6DS9L9063796
489	FM ECO4 LIGHT+ 3G	863003042153049	11/9/2024	B0055705	D-11548	JN6BE6DS6L9063223
490	FM ECO4 LIGHT+ 3G	869530043186911	11/9/2024	B0037211	DXB-D-13493	JTGSX22PXH6184532
491	FM ECO4 LIGHT+ 3G	869530045123409	11/9/2024	B0046959	L-14315	JTGSX22P8J6203097
492	FM ECO4 LIGHT+ 3G	868899046769093	11/9/2024	B0055692	J-74457	JN6BE6DS5L9064170
493	FM ECO4 LIGHT+ 3G	868899046782153	11/9/2024	B0053697	DXB-R-50321	MB1PAEHD5LU1B2441
494	FM ECO4 LIGHT+ 3G	868899046774424	11/9/2024	B0055429	N-51220	MB1PAEHD7LU1B2621
495	FM ECO4 LIGHT+ 3G	868899046792707	11/9/2024	B0055437	L-15745	MB1PAEHD1LU1B2761
496	FM ECO4 LIGHT+ 3G	868899046769051	11/9/2024	B0055693	Q-87458	JN6BE6DS6L9064193
497	FM ECO4 LIGHT+ 3G	868899046731812	11/9/2024	C0055561	C 69210	VF1HSRMX4LA564515
498	FM ECO4 LIGHT+ 3G	868899046783151	11/9/2024	B0055674	C-66128	JN6BE6DS7L9064008
499	FM ECO4 LIGHT+ 3G	869530045149180	11/9/2024	B0038162	U-92656	JTG5X22P6H6187993
500	FM ECO4 LIGHT+ 3G	868899046783128	11/9/2024	B0055686	M-56640	JN6BE6DSXL9064083
501	FM ECO4 LIGHT+ 3G	868899046731705	11/9/2024	C0056155	I-16835	VF1HSRMX0LA576029
502	FM ECO4 LIGHT+ 3G	863003042151076	11/9/2024	B0055672	C-26466	JN6BE6DS7L9063974
503	FM ECO4 LIGHT+ 3G	869530045167984	11/9/2024	C0033856	T-27946	MHFB29F32H2000465
504	FM ECO4 LIGHT+ 3G	867553058480146	9/7/2022	C0061277	DXB-Y-79304	MHKEF8BF0PK032889
505	FM ECO4 LIGHT+ 3G	863003042033696	11/9/2024	B0055694	J-74254	JN6BE6DS8L9064146

506	FM ECO4 LIGHT+ 3G	869530045308802	11/9/2024	C0042432	1-28506	JTGSX22P0J6198557
507	FM ECO4 LIGHT+ 3G	869530045163025	9/15/2022	B0053698	DXB-R-50345	MB1PAEHDXLU1B2449
508	FM ECO4 LIGHT+ 3G	868899046736811	11/9/2024	B0055706	D-42518	JN6BE6DS6L9063836
509	FM ECO4 LIGHT+ 3G	863003042028704	11/9/2024	B0055704	S-80284	JN6BE6DSXL9063192
510	FM ECO4 LIGHT+ 3G	868899046736274	11/9/2024	B0055678	D-40639	JN6BE6DS1L9064070
511	FM ECO4 LIGHT+ 3G	868899046784365	11/9/2024	B0055697	C-83947	JN6BE6DSXL9064133
512	FM ECO4 LIGHT+ 3G	863003042156570	11/9/2024	B0055690	J-78313	JN6BE6DS3L9064166
513	FM ECO4 LIGHT+ 3G	866381051078910	11/9/2024	B0037215	DXB-D-13262	JTGSX22P8H6184593
514	FM ECO4 LIGHT+ 3G	868899046783011	11/9/2024	C0056062	F-30925	VF1HSRMX0LA572403
515	FM ECO4 LIGHT+ 3G	869530041917150	11/9/2024	B0055808	D-10369	JN6BE6DS3L9063972
516	FM ECO4 LIGHT+ 3G	869530045184666	11/9/2024	C0042277	N-13327	1N4AL3APXJC237027
517	FM ECO4 LIGHT+ 3G	868899046784738	11/9/2024	B0055691	J-75953	JN6BE6DS3L9064183
518	FM ECO4 LIGHT+ 3G	863003042156422	11/9/2024	B0055682	M-44039	JN6BE6DS9L9064043
519	FM ECO4 LIGHT+ 3G	868899046782401	11/9/2024	B0055680	J-73818	JN6BE6DS3L9064040
520	FM ECO4 LIGHT+ 3G	869530045120405	11/9/2024	B0022382	P-32336	JTGF85188E1066371
521	FM ECO4 LIGHT+ 3G	863003042148502	11/9/2024	B0055433	N 24579	MB1PAEHDXLU1B2743
522	FM ECO4 LIGHT+ 3G	868899046781056	11/9/2024	B0055679	F-29705	JN6BE6DS2L9064109
523	FM ECO4 LIGHT+ 3G	868899046770497	11/9/2024	C0055559	D 93207	VF1HSRMX2LA564514
524	FM ECO4 LIGHT+ 3G	863003042147702	11/9/2024	B0034636	T-87229	JTGJX02P6G0067404
525	FM ECO4 LIGHT+ 3G	863003042156448	11/9/2024	B0055703	P-83820	JN6BE6DS9L9063149
526	FM ECO4 LIGHT+ 3G	868899046766750	11/9/2024	C0055533	M 46212	VF1HSRMXXLA567130
527	FM ECO4 LIGHT+ 3G	867553058478850	8/9/2022	B0018851	DXB-D-54482	JTGF85183E1062292
528	TRACE5 LTM (Rev.A) 4G	863257067831794	11/9/2024	B0055688	P-89886	JN6BE6DS1L9064215
529	TRACE5 LTM (Rev.A) 4G	863257067805756	8/9/2022	B0026763	DXB-R-20526	JTGJX02P6F5042035
530	FM ECO4 LIGHT+ 3G	868899046782427	11/11/2024	B0055440	N-22539	MB1PAEHD7LU1B2764
531	FM ECO4 LIGHT+ 3G	868899046782625	11/11/2024	B0055671	C-62532	JN6BE6DS6L9064033
532	FM ECO4 LIGHT+ 3G	869530045295280	11/11/2024	B0022425	D-76590	JTGF85188E1066175
533	FM ECO4 LIGHT+ 3G	868899046731291	11/11/2024	B0055700	M-40172	JN6BE6DSXL9063063
534	FM ECO4 LIGHT+ 3G	868899046803041	11/11/2024	B0055701	M-38390	JN6BE6DS8L9063255
535	FM ECO4 LIGHT+ 3G	868899046768541	11/11/2024	B0055443	L-59101	MB1PAEHD9LU1B2779
536	FM ECO4 LIGHT+ 3G	868899046736258	11/11/2024	C0056065	F-79115	VF1HSRMX7LA572396
537	FM ECO4 LIGHT+ 3G	867553056737901	11/11/2024	C0051998	DXB-P-69125	VF1HSRMX3LA538519
538	FM ECO4 LIGHT+ 3G	867553057598930	11/11/2024	B0042380	DXB-N-36107	JTGSX22P1J6198390
539	FM ECO4 LIGHT+ 3G	863003042056648	11/11/2024	B0055444	L-83881	MB1PAEHD7LU1B2781
540	FM ECO4 LIGHT+ 3G	868899046779332	11/11/2024	B0055707	C-46056	JN6BE6DS6L9063948
541	FM ECO4 LIGHT+ 3G	863003042156547	11/11/2024	B0055699	C-96804	JN6BE6DS0L9063072
542	FM ECO4 LIGHT+ 3G	863003042146985	11/11/2024	B0055668	F-33893	JN6BE6DSXL9064004
543	FM ECO4 LIGHT+ 3G	868899046780934	11/11/2024	B0055683	Q-24743	JN6BE6DS9L9064088
544	FM ECO4 LIGHT+ 3G	868899046768764	11/11/2024	C0056063	F-15926	VF1HSRMX2LA572399
545	FM ECO4 LIGHT+ 3G	869530045290109	2/10/2023	C0033548	T-36068	JTNGE52M4H7143450
546	FM ECO4 LIGHT+ 3G	869530045129604	11/12/2024	C0050355	9-58615	5N1DR2M56KC575080
547	FM ECO4 LIGHT+ 3G	866381051072145	11/12/2024	B0058222	DXB-J-71763	JN6BE6DS7M9066147
548	FM ECO4 LIGHT+ 3G	869530045181126	2/5/2024	C0040044	DXB-V-21425	MDHBN7AD0JG640612

549	FM ECO4 LIGHT+ 3G	869530045130172	11/12/2024	C0055000	DXB-S-48391	RKLBA0BE3L1001448
550	FM ECO4 LIGHT+ 3G	866381051067921	11/12/2024	C0053330	DXB-H-65218	MHKEF8BF1LK010894
551	FM ECO4 LIGHT+ 3G	869530045311038	11/12/2024	C0042402	DXB-O-23206	JTMHU01J4J4163937
552	FM ECO4 LIGHT+ 3G	867553059810309	11/12/2024	C0058108	DXB-N-23996	MDHBN7AD4MG115105
553	FM ECO4 LIGHT+ 3G	869530045244148	11/12/2024	C0049763	O-59501	KMHD741C6KU921191
554	FM ECO4 LIGHT+ 3G	866381051105861	2/28/2023	C0027197	DXB-R-29202	RKLBB9HE7F5108055
555	FM ECO4 LIGHT+ 3G	866381051026604	11/12/2024	C0058220	DXB-M-72503	MDHBN7AD3MG119825
556	FM ECO4 LIGHT+ 3G	869530045233950	11/12/2024	C0056621	DXB-R-84190	JTHB21B15L2089411
557	FM ECO4 LIGHT+ 3G	869530045238090	11/12/2024	C0038405	G-48085	JN6BE6AS4J9030075
558	FM ECO4 LIGHT+ 3G	869530045210123	11/12/2024	C0042397	R-16359	VF18SRB40JG426411
559	FM ECO4 LIGHT+ 3G	867688038831040	11/12/2024	C0046917	L-90735	MNTBB7A99K6065222
560	FM ECO4 LIGHT+ 3G	869530045209778	11/12/2024	C0047277	M-48355	MMBMG35H4KH037984
561	FM ECO4 LIGHT+ 3G	869530045164510	11/12/2024	C0047442	M-75650	MDHBN7AD2KG681020
562	TRACE5 IP-67 LTM (Rev.A) 4G	864145064949645	11/12/2024	C0062404	DXB-Z-16998	MDHBN7AD2PG313055
563	FM ECO4 LIGHT+ 3G	869530043220942	11/12/2024	C0043935	DXB-W-73823	JTNBF9HK4K3026597
564	FM ECO4 LIGHT+ 3G	867553058485160	11/12/2024	C0051348	DXB-P-52582	VSKDD3C41LA131019
565	TRACE5 LTM (Rev.A) 4G	863940058649891	11/12/2024	C0059921	AD-50-96582	1N4BL4A91NN326006
566	TRACE5 LTM (Rev.A) 4G	863257067818759	11/13/2024	C0059702	DXB-Q-34007	MK2K6T1Y4NN000420
567	TRACE5 LTM (Rev.A) 4G	863257067798779	11/13/2024	C0059679	DXB-G-86091	MK2K6T1Y6NN000483
568	FM ECO4 LIGHT+ 3G	869530045299639	11/13/2024	0	DXB-T-89685	HN6BE6AS3M9032842
569	FM ECO 4 3G ET	867553056690928	11/13/2024	C0040333	DXB-V-46958	JTNGE52M2J7161743
570	FM ECO4 LIGHT+ 3G	869530045153323	11/13/2024	C0053352	DXB-F-11548	MHF829F32K2073889
571	FM ECO4 LIGHT+ 3G	869530045137771	2/21/2024	C0051416	DXB-E-48652	MDHBN7AD3KG680992
572	FM ECO4 LIGHT+ 3G	869530045136823	11/13/2024	C0046565	C-36737	MDHBN7AD8KG681037
573	FM ECO4 LIGHT+ 3G	869530045119886	11/13/2024	C0057550	DXB-R-41095	MHKEF8BF3LK015997
574	FM ECO4 LIGHT+ 3G	869530045152275	9/9/2022	C0061328	MA3NC2B16PA472624	MA3NC2B16PA472624
575	FM ECO4 LIGHT+ 3G	867553056755481	8/12/2022	C0028376	DXB-R-92668	JTFHX02P9F0100932
576	FM ECO4 LIGHT+ 3G	867553057624751	5/17/2023	C0034028	DXB-T-57617	MR2K19F32H1014945
577	FM ECO4 LIGHT+ 3G	869530045126915	8/26/2022	C0059671	DXB-D-42210	MK2K6T1Y6NN000435
578	FM ECO4 LIGHT+ 3G	866381051070115	5/15/2024	C0050785	DXB-Q-79840	MDHBN7AD6LG691289
579	FM ECO4 LIGHT+ 3G	867553057656647	11/13/2024	C0058111	DXB-H-84127	MMBMG35H4LH013105
580	FM ECO4 LIGHT+ 3G	867553056736911	11/13/2024	C0058700	DXB-U-12076	VR3E1NFJ2NJ512861
581	TRACE5 IP-67 LTM (Rev.A) 4G	863257068997040	11/13/2024	C0059657	DXB-O-94168	MK2K6T1Y9MN000556
582	TRACE5 LTM (Rev.A) 4G	863257067788689	11/13/2024	C0059655	DXB-O-93206	MK2K6T1Y2MN000446
583	TRACE5 LTM (Rev.A) 4G	863257067894263	11/13/2024	C0059649	DXB-O-64806	MK2K6T1YXMN000369
584	FM ECO4 LIGHT+ 3G	869530045148612	5/24/2023	B0026203	11-16697	KMJWA37R0GU750198
585	FM ECO4 LIGHT+ 3G	869530041909892	5/22/2023	B0013873	11-58691	JTGFB5185C1047290
586	FM ECO4 LIGHT+ 3G	867688039832302	5/22/2023	B0013947	5-36544	JTGFB5186C1047637
587	FM ECO4 LIGHT+ 3G	869530045151707	11/30/2021	B0035230	SHJ-3-64621	MB1PBEFA9HUCA6855
588	FM ECO4 LIGHT+ 3G	869530045128382	11/15/2024	B004511	9-84313	MB1PAEHD8KU1B1105
589	FM ECO4 LIGHT+ 3G	863940058308175	5/24/2023	B0049388	12-97186	JTGFE7288K6270426
590	FM ECO4 LIGHT+ 3G	869530045313356	11/15/2024	B0036348	AD-10-26548	JTGSX22P8H6183461

591	FM ECO4 LIGHT+ 3G	869530045202237	11/15/2024	C0055642	DXB-H-70845	MHKEF8BF9LK011226
592	FM ECO4 LIGHT+ 3G	866381051077078	7/18/2023	C0036881	SHJ-3-77067	MR1DX8FS0H0008869
593	FM ECO4 LIGHT+ 3G	868899043826854	11/15/2024	C0051763	P-73544	VSKDD3C48LA132085
594	TRACE5 LTM (Rev.A) 4G	863257069098244	2/28/2023	B0015425	12-17902	JTGFB5182C1052933
595	TRACE5 LTM (Rev.A) 4G	863257067755522	11/15/2024	C0028771	DXB-D-18630	MMBJNKL40GH009566
596	FM ECO4 LIGHT+ 3G	869530045156516	11/15/2024	B0018879	13-45372	JTGFB5188E1062322
597	FM ECO4 LIGHT+ 3G	869530045246556	1/0/1900	B0017579	C-30598	JTGSX22P0D6137455
598	FM ECO4 LIGHT+ 3G	869530043777016	1/25/2023	0	H-96019	JS2ZC8B29D6100392
599	FM ECO4 LIGHT+ 3G	867688036768103	5/25/2023	C0047573	14-65227	MHFKU8FS9K0178744
600	FM ECO4 LIGHT+ 3G	869530041934593	9/12/2023	B0017299	12-32875	JTGFB5181D1059163
601	FM ECO4 LIGHT+ 3G	867688039302900	10/27/2023	C0051030	P-23516	1N4BL4A91KC206732
602	FM ECO4 LIGHT+ 3G	869530045290034	10/30/2023	C0046181	SHJ-3-55385	KL1ZA5CA7JB051787
603	FM ECO4 LIGHT+ 3G	869530041408333	10/26/2023	C0023765	Q-16829	MR0FX22G3F1439211
604	FM ECO4 LIGHT+ 3G	868899043910732	5/24/2023	B0026205	11-16722	KMJWA37R3GU749840
605	FM ECO4 LIGHT+ 3G	869530045293194	10/25/2023	C0046920	L-53116	MDHBN7AD1KG682417
606	FM ECO4 LIGHT+ 3G	867688039793108	5/25/2023	C0047666	9-70935	RKLB30BE8L0001106
607	FM ECO4 LIGHT+ 3G	867553059766022	6/2/2023	C0053120	12-68253	WDDUG6FB4FA134396
608	FM ECO4 LIGHT+ 3G	866381051093208	6/20/2023	C0052305	AD-10-29834	RKLBB0BE2L0013612
609	FM ECO4 LIGHT+ 3G	869530045183825	10/27/2023	C0042426	R-16382	MDHBN7AD6KG642933
610	FM ECO4 LIGHT+ 3G	869530045200520	5/22/2023	B0013949	5-29301	JTGFB5186C1047699
611	FM ECO4 LIGHT+ 3G	869530045131089	11/16/2022	C0047614	DXB-C-7403	JN8AY2NY5K9370323
612	FM ECO4 LIGHT+ 3G	869530045203912	10/27/2023	C0033212	56206	JTFPX22P6G0067378
613	FM ECO4 LIGHT+ 3G	867688036772261	5/25/2023	C0047667	9-70946	RLKB30BE8L0001249
614	FM ECO4 LIGHT+ 3G	867553056736531	10/30/2023	C0040725	IO-9481	JTHBK1GGXJ2263497
615	FM ECO4 LIGHT+ 3G	866381051053442	12/8/2023	C0036849	SHJ-3-77205	MMBMG35H3HH028265
616	FM ECO4 LIGHT+ 3G	867688036730962	11/18/2024	C0048912	O-51021	MNTBB7A95K6066139
617	FM ECO4 LIGHT+ 3G	867688039341718	11/18/2024	C0051896	L-32759	MDHBN7ADXLG695393
618	FM ECO4 LIGHT+ 3G	869530045290356	12/7/2023	C0047986	N-95012	MDHBN7AD8KG685914
619	FM ECO4 LIGHT+ 3G	866381051069505	10/30/2023	C0034465	SHJ-3-55490	MHFDX8FS6H0081901
620	FM ECO4 LIGHT+ 3G	866381051071923	10/23/2023	C0034500	SHJ-3-55470	MHFDX8FS6H0082059
621	FM ECO4 LIGHT+ 3G	867688039334655	11/18/2024	C0051803	P-91657	MDHBN7AD0LG695046
622	FM ECO4 LIGHT+ 3G	869530045114622	10/27/2023	C0047980	O-28414	MDHBN7AD8KG684889
623	FM ECO4 LIGHT+ 3G	867688036610578	11/18/2024	C0044427	9-40628	JTEBU9FJXKK162304
624	FM ECO4 LIGHT+ 3G	869530043794003	12/7/2023	C0029559	1-10351	JL7B6E1P3FK019951
625	FM ECO4 LIGHT+ 3G	869530045277148	10/27/2023	B0021220	A-12026	JTGJX02P5E5036760
626	FM ECO4 LIGHT+ 3G	869530045301013	9/2/2022	C0061334	AD-18-45373	VSKDD3C4XNA178469
627	FM ECO4 LIGHT+ 3G	869530043186754	12/7/2023	C0034899	SHJ-2-28625	JL7B6E1P6HK004010
628	FM ECO4 LIGHT+ 3G	869530045229255	2/21/2024	B0048725	O-28098	JN6BE6DS8K9062251
629	FM ECO4 LIGHT+ 3G	869530045296148	12/7/2023	C0047967	O-28559	MDHBN7AD2KG685343
630	FM ECO4 LIGHT+ 3G	869530045241573	12/7/2023	C0047969	O-28474	MDHBN7AD3KG685089
631	FM ECO4 LIGHT+ 3G	869530045144504	10/3/2021	B0039385	DXB-F-24461	MB1PBFA5HUJA9178
632	FM ECO4 LIGHT+ 3G	867688038865105	11/18/2024	C0051813	J-56847	MDHBN7AD2LG687515
633	FM ECO4 LIGHT+ 3G	869530045133671	12/7/2023	C0039884	FUJ-C-31403	JL7B6E1P4HK016317

634	FM ECO4 LIGHT+ 3G	869530045197841	12/7/2023	C0044075	10-83187	JL7B6E1P6HK012012
635	FM ECO4 LIGHT+ 3G	869530045190697	10/26/2023	C0036499	T-40669	MDHBN7AD2JG614223
636	FM ECO4 LIGHT+ 3G	869530043186598	9/13/2023	C0036825	SHJ-3-77210	MDHBN7AD4JG619858
637	FM ECO4 LIGHT+ 3G	869530045314016	11/19/2024	C0043902	12-42162	MR0HX8CD3K0930569
638	FM ECO4 LIGHT+ 3G	866381051069729	6/6/2024	C0050772	DXB-Q-79883	MDHBN7AD9LG691805
639	FM ECO4 LIGHT+ 3G	869530045147549	2/3/2024	C0055741	F-76480	MDHBN7AD6LG688151
640	FM ECO4 LIGHT+ 3G	866381051072236	11/19/2024	C0056041	SHJ-2-70251	JTFPX22P4L0093939
641	FM ECO4 LIGHT+ 3G	869530043778097	2/5/2024	C0052019	K-73967	VF1HSRMX7LA545537
642	FM ECO4 LIGHT+ 3G	869530045144363	11/19/2024	C0045006	SHJ-3-47792	JTNBF9HK1K3028548
643	FM ECO4 LIGHT+ 3G	866381051025937	8/9/2022	B0031308	DXB-P-26823	JTGSX23PXG6167775
644	FM ECO4 LIGHT+ 3G	869530045176787	5/18/2023	C0034767	DXB-T-95761	MR2B29F36H1031275
645	FM ECO4 LIGHT+ 3G	867553057650517	11/20/2024	B0036376	SHJ-57041	JTGFB7187H6001952
646	FM ECO4 LIGHT+ 3G	869530041917309	5/4/2023	B0027125	R-20655	JTGFB5187F1073149
647	FM ECO4 LIGHT+ 3G	869530045168685	11/20/2024	C0041965	R-10765	MHFDX8FS6K0092307
648	FM ECO4 LIGHT+ 3G	869530045261944	11/20/2024	B0046961	L-12468	JTGSX22PXJ6203179
649	FM ECO4 LIGHT+ 3G	869530041911278	11/20/2024	C0036301	N-99576	RKLB89HE5H5188779
650	FM ECO4 LIGHT+ 3G	869530045144579	11/20/2024	C0042135	K-75204	MHFDX8FS6K0092713
651	FM ECO4 LIGHT+ 3G	869530045310436	5/4/2023	C0040371	V-50624	3N1CP5C95JL490684
652	FM ECO4 LIGHT+ 3G	869530045134190	11/20/2024	C0042922	SHJ-2-10445	1GNSK7EC8KR121492
653	FM ECO4 LIGHT+ 3G	867688039342070	11/20/2024	C0051890	F-83289	MDHBN7AD9LG695465
654	FM ECO4 LIGHT+ 3G	863003042057133	11/20/2024	C0055118	C-54237	MNTBB7A9XL6072343
655	FM ECO4 LIGHT+ 3G	863003042036616	11/20/2024	C0051884	P-84527	MDHBN7AD8LG695490
656	FM ECO4 LIGHT+ 3G	869530045214448	9/30/2022	C0028803	DXB-D-21039	MMBJNKL40GH009632
657	TRACES LTM (Rev.A) 4G	863257067817686	1/0/1900	B0061724	SHJ-1-74305	MB1PBEHD7NU1B6233
658	FM ECO4 LIGHT+ 3G	867688038865147	11/20/2024	C0051832	J-90028	MDHBN7AD3LG687877
659	FM ECO4 LIGHT+ 3G	869530045207384	11/20/2024	B0022508	SHJ-1-38416	JTGFB5187E1067625
660	FM ECO4 LIGHT+ 3G	867688036601304	1/0/1900	0	3-78165	JL6BDG6A7MK000729
661	FM ECO4 LIGHT+ 3G	863003048307623	1/26/2024	B0033962	T-53996	JTGFB5189G1080556
662	FM ECO4 LIGHT+ 3G	866381051068424	12/7/2023	C0040706	DXB-V-48594	RKLBL9HE6K5265566
663	FM ECO4 LIGHT+ 3G	869530045163389	12/8/2023	C0049896	O-32296	KL1CD6CA8KC785482
664	FM ECO4 LIGHT+ 3G	869530045228281	11/21/2024	C0034147	T-60841	JTFHX02P8G0111020
665	FM ECO4 LIGHT+ 3G	869530045153398	11/21/2024	B0024977	15-80273	JTGFB5189F1071001
666	FM ECO4 LIGHT+ 3G	869530045187560	Removed- 11-Aug- 2021	B0039377	DXB-U-50716	MB1PBEFB7HUJA9224
667	FM ECO4 LIGHT+ 3G	863003042156232	8/19/2022	B0032563	DXB-G-25833	JTGFB5180G1079263
668	FM ECO4 LIGHT+ 3G	866381051069927	12/8/2023	C0049898	DXB-O-32302	KL1CD6CA9KC786351
669	FM ECO4 LIGHT+ 3G	869530045312416	12/7/2023	C0049922	DXB-O-71375	KL1CD6CA0KC786321
670	FM ECO4 LIGHT+ 3G	869530045293780	2/3/2024	C0046686	J-89125	RKLB89HEXK5238888
671	FM ECO4 LIGHT+ 3G	863003048342398	8/17/2022	C0051848	DXB-J-45792	MDHBN7AD4LG687158
672	FM ECO4 LIGHT+ 3G	869530045293798	12/8/2023	B0015658	2-69982	JTGFB5182C1053371
673	FM ECO4 LIGHT+ 3G	869530043178082	12/7/2023	C0033892	SHJ-3-50316	JL6B6F6P7GK021474
674	FM ECO4 LIGHT+ 3G	869530045125131	2/26/2024	B0039442	U-26396	KMJWA37R0JU967080
675	FM ECO4 LIGHT+ 3G	869530045164312	5/7/2024	C0050778	DXB-L-69184	MDHBN7AD1LG691331

676	FM ECO4 LIGHT+ 3G	869530045137698	11/21/2024	C0051958	DXB-Q-64375	JN6BE6AS4L9031441
677	FM ECO4 LIGHT+ 3G	869530045133580	1/0/1900	C0052458	SHJ-2-12742	RKLBB0BE3L0013618
678	FM ECO4 LIGHT+ 3G	863003042113530	3/15/2024	C0051864	P-84549	MDHBN7AD5LG686617
679	FM ECO4 LIGHT+ 3G	869530045130065	11/21/2024	B0047516	M-92761	JL5BHJ655LRP20955
680	FM ECO4 LIGHT+ 3G	867553058478959	12/13/2023	C0036877	SHJ-3-77063	MR1DX8FS8H0008845
681	FM ECO4 LIGHT+ 3G	869530045146533	2/3/2024	C0051414	E-47882	MDHBN7ADXKG680990
682	FM ECO4 LIGHT+ 3G	869530045141500	2/3/2024	C0046939	DXB-M-50038	MDHBN7AD3KG682256
683	FM ECO4 LIGHT+ 3G	869530045179393	11/21/2024	B0028218	DXB-U-40057	MB1PBefa3GU0A2385
684	FM ECO4 LIGHT+ 3G	869530045180151	11/21/2024	B0024980	15-80277	JTGFB5188F1070728
685	FM ECO4 LIGHT+ 3G	869530045114226	12/8/2023	B0018787	M-58168	JTGFB518XE1060961
686	FM ECO4 LIGHT+ 3G	869530045191802	12/7/2023	C0047952	O-25086	MDHBN7AD0KG685888
687	FM ECO4 LIGHT+ 3G	869530045299449	3/21/2024	B0010216	DXB-O-24883	JTGFB5181A1037868
688	TRACE5 LTM (Rev.A) 4G	863257067744054	12/7/2023	C0049891	DXB-O-31757	KL1CD6CA8KC786888
689	FM ECO 4 3G ET	867553057596322	11/21/2024	C0058926	SHJ-3-91823	MDHBN7ADXNG127776
690	TRACE5 LTM (Rev.A) 4G	869738069911340	11/21/2024	B0027054	DXB-R-20586	JTGFB5187F1073345
691	TRACE5 LTM (Rev.A) 4G	863257067814394	11/21/2024	B0032971	SHJ-3-37468	JTGJX02P9G5047358
692	FM ECO4 LIGHT+ 3G	869530045171176	7/19/2023	C0045949	I-39695	MHKEF8BF7KK003141
693	FM ECO4 LIGHT+ 3G	869530041366796	12/13/2023	C0042738	DXB-W-12564	JN6BE6AS2J9030236
694	FM ECO4 LIGHT+ 3G	869530045170046	11/21/2024	C0030284	2-60197	1GCZG9FG2G1160591
695	FM ECO4 LIGHT+ 3G	866381051068697	12/8/2023	C0036847	SHJ-3-77187	MMBMG35H7HH028138
696	FM ECO4 LIGHT+ 3G	863003042140921	12/8/2023	C0018833	J-13830	MDHBN7AD2EG509560
697	FM ECO4 LIGHT+ 3G	866381051052782	12/8/2023	C0036856	SHJ-3-77190	MMBMG35H6HH026882
698	FM ECO4 LIGHT+ 3G	867553058480724	11/23/2024	B0036945	SHJ-1-43082	JTGsx22P2H6183309
699	FM ECO4 LIGHT+ 3G	869530045143845	11/24/2024	B0042519	DXB-W-84395	JTGsx22P4J6198948
700	FM ECO4 LIGHT+ 3G	867553058479940	11/24/2024	B0058197	DXB-M-72047	JTGHN9CPXM6009053
701	FM ECO4 LIGHT+ 3G	867553058470139	11/24/2024	B0058199	DXB-M-68915	JTGHN9CP9M6009321
702	TRACE5 LTM (Rev.A) 4G	863940059819568	11/24/2024	B0049278	DXB-M-71922	JTGFE7280K6270274
703	FM ECO4 LIGHT+ 3G	863003048344600	11/24/2024	B0034281	T-67516	JTGsx73P1G6174551
704	FM ECO4 LIGHT+ 3G	867553057624652	11/24/2024	B0042521	DXB-W-84393	JTGsx22P5J6198893
705	FM ECO4 LIGHT+ 3G	867553057660094	11/24/2024	B0032088	DXB-S-49428	JTGFB5188G1078913
706	FM ECO4 LIGHT+ 3G	863003042056432	11/24/2024	B0033030	S-64963	JTGJX02P3G5046528
707	FM ECO4 LIGHT+ 3G	869530045245137	11/24/2024	B0026005	DXB-C-99207	JTGFB5189F1072939
708	FM ECO4 LIGHT+ 3G	869530045282924	11/24/2024	B0015995	2-77936	JTGFB5180D1054424
709	FM ECO4 LIGHT+ 3G	869530045181910	11/24/2024	B0042297	U-86654	JL5BHJ6SXJRP20365
710	FM ECO4 LIGHT+ 3G	869530045242167	11/24/2024	B0039783	N-65172	JTGsx22P7J6188866
711	TRACE5 LTM (Rev.A) 4G	863940058387757	11/24/2024	B0023495	M-42371	JTGFB5188E1069867
712	FM ECO4 LIGHT+ 3G	866381051107396	11/24/2024	B0025989	DXB-D-12694	JTGFB5189F1072892
713	FM ECO4 LIGHT+ 3G	869530045177397	11/24/2024	B0023813	Q-16867	JTGFB5180E1070365
714	FM ECO4 LIGHT+ 3G	869530045131311	11/24/2024	B0026680	G-85897	JTGFB5185F1073215
715	FM ECO4 LIGHT+ 3G	866381051091541	10/4/2021	B0049276	AD-9-64143	JTGFE7288K6270281
716	FM ECO4 LIGHT+ 3G	866381051077995	11/24/2024	B0036864	DXB-G-94275	JTGFB718XH6002187
717	FM ECO4 LIGHT+ 3G	869530045239262	11/17/2021	B0049269	DXB-P-93430	JTGFE7289K6270287
718	FM ECO4 LIGHT+ 3G	866381051079892	9/30/2021	B0026010	DXB-D-13698	JTGJX02P8F5040707

719	FM ECO4 LIGHT+ 3G	869530045295462	9/12/2023	C0036283	D-32346	MHFCX8EMXH0108709
720	FM ECO4 LIGHT+ 3G	869530045243926	11/24/2024	B0039784	N-64456	JTG5X22P9J6189355
721	FM ECO4 LIGHT+ 3G	866381051031174	8/11/2022	B0015667	DXB-V-53342	JTGFB5181C1053507
722	FM ECO4 LIGHT+ 3G	866381051057096	8/12/2022	B0041936	DXB-R-10811	JTG5X22P1J6197286
723	FM ECO 43G ET	869530043210794	9/30/2022	B0021284	P-82472	JL5B3J6PXERM10510
724	FM ECO4 LIGHT+ 3G	869530045135601	11/25/2024	C0045403	RAK-C-81359	MHFku8F53K0178464
725	FM ECO4 LIGHT+ 3G	869530043785100	11/25/2024	B0036397	RAK-C-47267	JTGFB7181H6001400
726	FM ECO4 LIGHT+ 3G	869530045153216	11/25/2024	C0048646	RAK-C-46025	JTNB29HK5K3022800
727	FM ECO4 LIGHT+ 3G	869530043773908	11/25/2024	PV30764	SHJ-3-83654	JE4LP21U3HZ702395
728	FM ECO4 LIGHT+ 3G	869530045312523	11/25/2024	C0056911	RAK-C-95987	VSKDD3C21LA137109
729	FM ECO4 LIGHT+ 3G	867553057649071	11/25/2024	C0051535	RAK-C-12604	MHFku8F57K0178550
730	FM ECO4 LIGHT+ 3G	869530045282510	11/25/2024	B0036398	RAK-C-47265	JTGFB7185H6001691
731	FM ECO4 LIGHT+ 3G	869530045281496	1/0/1900	C0056907	RAK-C-96021	VSKDD3C20LA136873
732	FM ECO4 LIGHT+ 3G	867553057629495	11/25/2024	C0056908	RAK-C-49232	VSKDD3C25LA136318
733	FM ECO4 LIGHT+ 3G	869530043777081	11/25/2024	HL1228	RAK-C-17328	JN6BE6AS09003514
734	FM ECO4 LIGHT+ 3G	867553057650756	11/25/2024	C0056444	RAK-C-74804	JTFPX22P6L0093568
735	FM ECO4 LIGHT+ 3G	867553057659104	11/25/2024	C0056959	RAK-C-96241	JTNBF9HK9L3056356
736	FM ECO4 LIGHT+ 3G	867553057652232	11/25/2024	C0045406	RAK-C-81354	JTNGE52MXK7170661
737	FM ECO4 LIGHT+ 3G	869530045312671	11/25/2024	C0056637	RAK-C-95284	MR0DX9CD4L2640805
738	FM ECO4 LIGHT+ 3G	867553057593741	11/25/2024	H0056438	RAK-C-90784	MEC201DP2LP040834
739	TRACE5 LTM (Rev.A) 4G	863940058199277	11/25/2024	C0051534	RAK-C-16506	JTNBF9HKXK3043808
740	FM ECO4 LIGHT+ 3G	869530045310931	11/25/2024	C0056636	RAK-C-95276	MR0DX9CD4L2640769
741	FM ECO4 LIGHT+ 3G	869530045179278	11/25/2024	C0048645	RAK-C-43990	JTNB29HK6K3022398
742	FM ECO4 LIGHT+ 3G	867553057659492	11/25/2024	C0056443	RAK-C-90783	JTFPX22P5L0093576
743	FM ECO4 LIGHT+ 3G	867553057671554	11/25/2024	C0051536	RAK-C-18355	RKLB89HEXK5241516
744	FM ECO4 LIGHT+ 3G	869530045164387	11/25/2024	C0056635	RAK-C-95277	MR0DX9CD4L2640738
745	FM ECO4 LIGHT+ 3G	869530045188659	11/25/2024	C0056914	RAK-C-96012	VSKDD3C23LA135197
746	FM ECO4 LIGHT+ 3G	869530045177934	11/25/2024	B0038381	C-92654	JTGFB7187H6003233
747	FM ECO4 LIGHT+ 3G	869530045152879	11/25/2024	C0056906	RAK-C-48986	VSKDD3C24LA136682
748	FM ECO4 LIGHT+ 3G	869530045184559	11/25/2024	C0051695	DXB-P-60881	JN6BE6AS6L9031439
749	FM ECO4 LIGHT+ 3G	869530043787965	11/25/2024	C0056939	RAK-C-96112	RKLB80BE3L0027258
750	FM ECO4 LIGHT+ 3G	867553057668568	11/25/2024	C0056942	RAK-C-96094	RKLB80BE5L0027410
751	FM ECO4 LIGHT+ 3G	867553057671760	11/25/2024	C0056638	RAK-C-95279	MR0CX9CB4L3960680
752	FM ECO4 LIGHT+ 3G	867553057659401	11/25/2024	C0056729	RAK-C-95280	VSKDD3C23LA135328
753	FM ECO4 LIGHT+ 3G	867553057649386	11/25/2024	C0056941	RAK-C-96095	RKLB80BE5L0027391
754	FM ECO4 LIGHT+ 3G	868899046752735	5/24/2023	B0026223	11-17261	KMJWA37R3GU749739
755	TRACE5 LTM (Rev.A) 4G	863257067819856	11/26/2024	B0043978	W-91780	JL5BHJ6S8KRP20530
756	FM ECO4 LIGHT+ 3G	866381051052378	7/18/2023	C0037310	SHJ-3-79360	MMBMG45H5HH023848
757	FM ECO4 LIGHT+ 3G	869530045128192	10/30/2023	C0042916	V-84696	JMYSTCY4AGU741509
758	FM ECO4 LIGHT+ 3G	869530045123789	11/26/2024	B0043056	W-40438	JL5BHJ6S3KRP20676
759	FM ECO4 LIGHT+ 3G	868899043927983	11/27/2024	C0054994	5-53175	JHMRC1831LC400170
760	FM ECO4 LIGHT+ 3G	869530045122658	11/27/2024	C0046469	5-57531	JTEBU3FJ2KK168594
761	FM ECO4 LIGHT+ 3G	869530045211238	11/27/2024	C0053530	14-66052	5N1DR2M56LC578031

762	FM ECO4 LIGHT+ 3G	867688036754889	11/27/2024	C0046798	6-31957	JTNBZ4HK6K3007849
763	FM ECO4 LIGHT+ 3G	868899046741720	11/27/2024	C0056721	7-26549	JTNBF4HK5L3057989
764	FM ECO4 LIGHT+ 3G	867688039810365	11/27/2024	C0049574	14-28478	JTNBZ4HK2K3010702
765	FM ECO4 LIGHT+ 3G	869530045228463	11/27/2024	C0056970	AD-6-26725	5N1DR2M5XLC582986
766	FM ECO4 LIGHT+ 3G	867553056760572	11/27/2024	C0046542	AD-6-25410	VSKDD3C23KA105714
767	FM ECO4 LIGHT+ 3G	863003048363931	11/27/2024	C0056661	16-94852	RKLBA0BEXL1001804
768	TRACE5 LTM (Rev.A) 4G	869084063980696	11/27/2024	C0062512	AD-6-54857	JTNBZ4HK1P3134648
769	TRACE5 LTM (Rev.A) 4G	869084063975514	11/27/2024	C0062511	AD-6-54886	JTNBZ4HK2P3134593
770	FM ECO4 LIGHT+ 3G	867553057665432	11/27/2024	C0057970	AD-13-53084	AD- JTMB13FV0MD080408
771	FM ECO4 LIGHT+ 3G	869530043774955	11/27/2024	C0056850	AD-13-55907	RKLBB0B8EL0026722
772	FM ECO4 LIGHT+ 3G	869530045155195	11/27/2024	C0056969	AD-6-28107	5N1DR2M50LC583225
773	FM ECO4 LIGHT+ 3G	868899046781049	11/27/2024	C0056663	15-80295	RKLBA0BEXL1001821
774	FM ECO4 LIGHT+ 3G	867553057661134	4/5/2022	C0055070	AD-7-56489	JN8AY2NY4L9405421
775	FM ECO4 LIGHT+ 3G	867688035672702	11/27/2024	C0047311	13-27369	JTEBU3FJ2KK167834
776	FM ECO4 LIGHT+ 3G	863003048305056	11/27/2024	C0056718	7-26573	JTNBF4HK2L3058002
777	FM ECO4 LIGHT+ 3G	869530045175474	11/27/2024	N/A	6-71820	RKLBL9HE1K5266270
778	FM ECO4 LIGHT+ 3G	869530045175334	11/27/2024	N/A	6-72407	RKLBL9HE5K5265767
779	FM ECO4 LIGHT+ 3G	869530045126014	12/11/2023	C0052104	AD-15-57012	5N1DR2M51LC575375
780	FM ECO4 LIGHT+ 3G	867688036606071	11/27/2024	C0044423	9-40673	JTEBU9FJ6KK162414
781	FM ECO4 LIGHT+ 3G	867688036770141	11/27/2024	C0050542	14-28590	4T1BZ1FB6KU031452
782	FM ECO4 LIGHT+ 3G	869530045127772	1/0/1900	N/A	6-71973	RKLBB9HE0K5266308
783	FM ECO4 LIGHT+ 3G	867688036603177	1/0/1900	C0047321	13-45867	JTEBU3FJ7KK167977
784	FM ECO4 LIGHT+ 3G	867688036747131	11/27/2024	C0049549	6-67835	JTNBZ4HK3K3010031
785	FM ECO4 LIGHT+ 3G	869530045145063	2/20/2024	C0047170	AD-6-27504	MHFDX8F53K0098212
786	FM ECO4 LIGHT+ 3G	867688037018979	12/11/2023	C0041059	13-41370	MR0CX8CDXJ0694186
787	FM ECO4 LIGHT+ 3G	867688036635906	5/13/2023	B0053105	12-92642	LJM1HCGD0EAS00349
788	FM ECO4 LIGHT+ 3G	867688032831103	11/27/2024	C0042591	AD-16-35589	JTNBF9HK7K3020406
789	FM ECO4 LIGHT+ 3G	867553057664294	11/27/2024	C0054633	AD-7-44593	JTNBF4HK8L3050910
790	FM ECO4 LIGHT+ 3G	869530045285679	11/27/2024	C0052316	AD-10-31522	RKLBB0BE5L0013488
791	FM ECO4 LIGHT+ 3G	867688036617516	11/27/2024	C0050215	O-26770	2G1135S38K9140752
792	FM ECO4 LIGHT+ 3G	869530045280951	11/27/2024	C0056222	AD-12-42088	JTNBF9HK2L3055467
793	FM ECO4 LIGHT+ 3G	866381051034483	2/17/2023	C0039227	AD-17-74982	2G1135S32J9127283
794	FM ECO4 LIGHT+ 3G	867553053328613	2/18/2023	C0044505	AD-14-73063	MDHBN7ADXKG668645
795	FM ECO4 LIGHT+ 3G	869530045150964	2/28/2023	B0015414	AD-12-92598	JTGF85185C1052814
796	FM ECO4 LIGHT+ 3G	868899046768947	11/28/2024	B0036769	7-82493	KMJTG18V7HC025111
797	FM ECO4 LIGHT+ 3G	869530045290729	2/17/2023	C0033935	17-28786	RKLBB9HE0H5181920
798	FM ECO4 LIGHT+ 3G	869530045307085	2/18/2023	C0042537	17-76323	MR0DX9CD4K2520775
799	FM ECO4 LIGHT+ 3G	869530045217417	2/17/2023	C0033005	17-76481	MR0HX8CDXG0905420
800	FM ECO4 LIGHT+ 3G	869530041913936	11/28/2024	B0042525	4-37168	JL5BHJ6S6JRP20198
801	FM ECO4 LIGHT+ 3G	867688037019365	11/28/2024	B0037464	17-98611	KMJTG18V0HC025127
802	FM ECO4 LIGHT+ 3G	867533059769810	#N/A	#N/A	#N/A	#N/A
803	FM ECO4 LIGHT+ 3G	867553059780759	6/19/2023	C0034397	AD-15-59432	JTMR9EV7HJ137618

804	FM ECO4 LIGHT+ 3G	869530045183080	2/18/2023	C0045151	SHJ-3-47793	JTHBZ1B13K2005631
805	TRACES LTM (Rev.A) 4G	863257067760951	2/18/2023	C0043883	AD-13-35057	MDHBN7AD2KG655811
806	FM ECO4 LIGHT+ 3G	869530045187453	2/28/2023	B0014440	AD-4-58638	JTGF85188C1049342
807	FM ECO4 LIGHT+ 3G	869530041991965	11/28/2024	B0037949	6-87135	JTGF87185H6002758
808	FM ECO4 LIGHT+ 3G	869530045237415	2/28/2023	B0015206	12-17503	JTGF85183C1052245
809	FM ECO4 LIGHT+ 3G	869530045179591	11/28/2024	B0016974	T-44580	KMJKG18B6DC909455
810	FM ECO4 LIGHT+ 3G	867688032969044	2/15/2023	B0015433	AD-12-17905	JTGF85184C1052996
811	FM ECO4 LIGHT+ 3G	867553056682610	2/18/2023	C0042530	AD-17-78233	MHFKU8F51J0176405
812	FM ECO4 LIGHT+ 3G	869530045264930	11/28/2024	B0034690	6-88972	MB1PBFA2HUGA6059
813	FM ECO4 LIGHT+ 3G	868899046781072	11/28/2024	N/A	N-30754	MB1PAEHD4LU1B2771
814	FM ECO4 LIGHT+ 3G	867553053292421	2/18/2023	C0050242	DXB-O-67829	JTHBZ1B16K2006854
815	FM ECO4 LIGHT+ 3G	863003048305619	11/28/2024	B0037465	17-98604	KMJTG18V1HC025122
816	FM ECO4 LIGHT+ 3G	869530045185044	11/28/2024	B0055435	DXB-L-87943	MB1PAEHD7LU1B2747
817	FM ECO4 LIGHT+ 3G	863003042156349	11/28/2024	N/A	N-58931	MB1PAEHD7LU1B2733
818	FM ECO4 LIGHT+ 3G	869530045143829	May 30, 2021	B0019810	AD-11-76394	KMJTG18V8EC016462
819	FM ECO4 LIGHT+ 3G	869530045309065	Removed- 07-Mar-21	B0019815	AD-11-13572	KMJTG18VXEC016463
820	FM ECO4 LIGHT+ 3G	867688032987111	3/7/2021	B0025448	AD-15-48236	JTGF85187F1071773
821	FM ECO4 LIGHT+ 3G	869530043195318	11/30/2024	C0053211	AD-7-49953	JTNBF9HK5K3043943
822	FM ECO4 LIGHT+ 3G	869530041400587	3/7/2021	B0014856	AD-8-22047	KMJKG18B8DC908548
823	FM ECO4 LIGHT+ 3G	867688036994550	4/26/2022	C0045865	AD-9-85117	1N4BL4A96KC146432
824	FM ECO4 LIGHT+ 3G	867553057586406	12/11/2023	C0036472	AD-17-93840	JTMR9F9EV2HD214054
825	FM ECO4 LIGHT+ 3G	867688036601379	11/29/2024	B0022240	8-53162	JTGF85180E1066106
826	FM ECO4 LIGHT+ 3G	869530045135817	3/3/2021	B0014853	AD-9-18524	KMJKG18BXCC908372
827	FM ECO4 LIGHT+ 3G	867688036635666	Removed- 14-Feb- 2021	B0019809	AD-11-76853	KMJTG18V6EC016461
828	FM ECO4 LIGHT+ 3G	869530045191596	Removed- 07-Mar-21	B0010182	AD-10-50872	KMJJK18B89C902788
829	FM ECO4 LIGHT+ 3G	869530045165277	2/27/2021	B0012172	AD-10-35652	KMJKG18B0BC906130
830	FM ECO4 LIGHT+ 3G	869530045190929	Removed- 27-Feb- 2021	B0025446	AD-15-48210	JTGF85188F1072723
831	FM ECO4 LIGHT+ 3G	869530045211113	Removed- 04-Mar-21	B0010181	AD-10-50868	KMJJK18B69C902644
832	FM ECO4 LIGHT+ 3G	869530045240625	Removed- 14-Feb- 2021	B0019806	AD-11-13358	KMJTG18V1EC016464
833	FM ECO4 LIGHT+ 3G	869530045238363	7/7/2023	C0053259	11-32670	MMBNG4546LH003991
834	FM ECO4 LIGHT+ 3G	863003048383004	Removed- 07-Mar-21	B0019812	AD-11-80259	KMJTG18V7EC016453
835	FM ECO4 LIGHT+ 3G	867553053271128	11/28/2024	B0032877	AD-17-75568	MB1PBFA7GUXA4998
836	FM ECO4 LIGHT+ 3G	867688037019373	2/17/2023	C0031027	17-95357	JTFHX02P1G0103972
837	FM ECO4 LIGHT+ 3G	869530045202997	Removed- 07-Mar-21	B0012179	AD-10-43406	KMJKG18B4BC906132
838	FM ECO4 LIGHT+ 3G	867688036609497	Removed- 27-Feb- 2021	B0018570	AD-13-69143	KMJKG18B8DC909845
839	FM ECO4 LIGHT+ 3G	869530045152440	Removed- 07-Mar-21	B0019801	AD-11-76471	KMJTG18V0EC016455

840	FM ECO4 LIGHT+ 3G	869530045142318	Removed-07-Mar-21	B0019804	AD-11-65180	KMJTG18V5EC016452
841	FM ECO4 LIGHT+ 3G	869530045119720	Removed-27-Feb-2021	B0025444	AD-15-46177	JTGFB5187F1072678
842	FM ECO4 LIGHT+ 3G	869530045122997	Removed-3-March-2021	B0019811	AD-11-80517	KMJTG18V5EC016466
843	FM ECO4 LIGHT+ 3G	867688033153960	11/1/2023	C0053255	11-34128	MMBNG4547LH003952
844	FM ECO4 LIGHT+ 3G	867688039805985	5/16/2023	B0053043	9-55826	LSFD132E2GC000964
845	FM ECO4 LIGHT+ 3G	869530045237522	2/18/2023	C0046497	12-74763	JN8AY2NY3K9369235
846	FM ECO4 LIGHT+ 3G	867688032981999	11/28/2024	B0037208	17-99437	KMJTG18V9HC025126
847	TRACE5 LTE EMEA 4G	863514051806392	11/29/2024	C0042071	AD-16-52704	JHHUCN1H7JK026513
848	TRACE5 LTE EMEA 4G	863514051788699	11/29/2024	B0024660	P-14960	JL5B3J6P5FRN20284
849	FM ECO4 LIGHT+ 3G	867688037043498	Removed-07-Mar-21	B0012176	AD-10-26157	KMJKG18B9BC906126
850	FM ECO4 LIGHT+ 3G	863003042054619	11/28/2024	B0055681	M-35908	JN6BE6DS3L9064068
851	FM ECO4 LIGHT+ 3G	867553056682842	2/18/2023	C0045044	DXB-E-67961	JTHBZ1B10K2005618
852	FM ECO4 LIGHT+ 3G	863003048305858	2/17/2023	C0039554	17-60973	JTNBF4HK3J3003989
853	FM ECO4 LIGHT+ 3G	867688037043464	11/28/2024	B0036768	7-74629	KMJTG18V0HC025113
854	FM ECO4 LIGHT+ 3G	867688037013624	2/17/2023	C0039358	9-71889	JN8BY2NY7J9117457
855	FM ECO4 LIGHT+ 3G	867553059780494	2/18/2023	C0044506	AD-14-75351	MDHBN7ADXXKG668726
856	FM ECO4 LIGHT+ 3G	867688037000407	11/28/2024	B0036765	7-72443	KMJTG18VXHC025118
857	FM ECO4 LIGHT+ 3G	867688036760977	2/18/2023	C0046761	17-71461	JTNBZ4HKKX3009751
858	FM ECO4 LIGHT+ 3G	869530041405552	Removed 01-March-2021	B0025456	AD-15-48237	JTGFB5189F1072326
859	FM ECO4 LIGHT+ 3G	867688032971354	Removed-04-Mar-21	B0019814	AD-11-13507	KMJTG18V9EC016454
860	FM ECO4 LIGHT+ 3G	867688036737355	Removed-14-Feb-2021	B0019805	AD-11-79725	KMJTG18V6EC016458
861	FM ECO4 LIGHT+ 3G	869530041360468	Removed-07-Mar-21	B0016994	AD-7-18658	KL5UP61JEDU006952
862	FM ECO4 LIGHT+ 3G	867688032982500	Removed 01-March-2021	B0017294	AD-9-51136	KMJKG18BXDC909586
863	FM ECO4 LIGHT+ 3G	863003042167510	Removed-07-Mar-21	B0025449	AD-15-48220	JTGFB5189F1071807
864	FM ECO4 LIGHT+ 3G	863003048383806	8/8/2024	C0041089	13-41350	MHFCX8EM5J0111748
865	FM ECO4 LIGHT+ 3G	867688036607202	8/9/2024	C0047162	6-27455	MHFDX8FS0K0098135
866	FM ECO4 LIGHT+ 3G	869530045290695	1/17/2023	C0036393	AD-15-81330	1N4AL3A95HC172891
867	FM ECO4 LIGHT+ 3G	867688036776411	5/24/2023	C0047683	14-38540	RLKB30BE0L0001441
868	TRACE5 LTM (Rev.A) 4G	863257067772030	12/7/2024	C0062514	AD-6-54799	JTNB24HK2P3134996
869	FM ECO4 LIGHT+ 3G	869530045130636	8/8/2024	C0021022	14-90646	RKLBL9HEXE5208565
870	FM ECO4 LIGHT+ 3G	869530041369220	1/17/2023	B0035226	13-26569	JTGFB7184H6000743
871	FM ECO4 LIGHT+ 3G	867688036757064	5/3/2023	B0053095	7-60491	LJM1HCGD6EAS00338
872	FM ECO4 LIGHT+ 3G	869530045313406	1/17/2023	B0034238	AD-15-91698	KMJWA37R4HU877361
873	FM ECO4 LIGHT+ 3G	863003048382329	8/13/2024	C0030965	17-98773	RKLBL9HE1G525299
874	FM ECO4 LIGHT+ 3G	867688033152046	8/8/2024	C0039463	16-85536	JTNBF4HK2J3002011
875	FM ECO4 LIGHT+ 3G	869530045248230	12/12/2022	B0013610	N-80968	KMJWA37RXCU413094

876	FM ECO4 LIGHT+ 3G	867688036641078	5/17/2023	C0046369	12-36293	JN8AY2NY6K9369391
877	FM ECO4 LIGHT+ 3G	869530045180474	2/16/2023	B0015326	12-54784	JTGFB518201051555
878	FM ECO4 LIGHT+ 3G	869530045312564	2/15/2023	B0022313	AD-10-96527	JTGFB5180E1066784
879	FM ECO4 LIGHT+ 3G	869530045182462	1/17/2023	C0041251	6-71482	RKLBL9HE7K5265558
880	FM ECO4 LIGHT+ 3G	869530045126287	12/12/2022	B0015435	12-17918	JTGFB5186C1052919
881	FM ECO4 LIGHT+ 3G	869530045281934	8/8/2024	C0045156	AJM-A-9830	MHFKU8F56K0178443
882	FM ECO4 LIGHT+ 3G	869530045242019	2/6/2023	B0034681	15-67335	JTGJX02P2G5048609
883	FM ECO4 LIGHT+ 3G	869530045280597	8/8/2024	C0039524	AD-11-62940	WD4WG3E10J3405418
884	FM ECO4 LIGHT+ 3G	867553057661852	8/3/2023	C0046422	AD-16-49862	1N4BL4A95KC192382
885	FM ECO4 LIGHT+ 3G	867688033164090	8/8/2024	C0047219	6-27328	MHFDX8F50K0098099
886	FM ECO4 LIGHT+ 3G	869530045144611	12/13/2022	C0030981	17-10163	RKLBL9HE9G5252771
887	FM ECO4 LIGHT+ 3G	867553058480591	8/8/2024	C0039455	AD-17-74230	JTNBF4HK2J3002042
888	FM ECO4 LIGHT+ 3G	869530045163629	1/23/2023	C0041772	AD-6-30821	MR0DX9CD4K2635411
889	FM ECO4 LIGHT+ 3G	868899043923891	12/12/2022	B0015450	12-17932	JTGFB5187C1053009
890	FM ECO4 LIGHT+ 3G	867688039806033	5/22/2023	B0048889	9-62160	JTGFE7289K6270371
891	FM ECO4 LIGHT+ 3G	869530041414737	1/17/2023	B0032680	13-72754	JTGSX23P1G6172525
892	FM ECO4 LIGHT+ 3G	868899046773848	12/7/2024	C0056701	9-31584	JTNBF4HK0L3057270
893	FM ECO4 LIGHT+ 3G	868899046750754	12/7/2024	C0056705	7-38658	JTNBF4HK3L3057280
894	FM ECO4 LIGHT+ 3G	869530045167166	12/12/2022	B0013603	S-38122	KMJWA37R3CU411509
895	FM ECO4 LIGHT+ 3G	869530041914413	8/9/2024	C0030996	17-98717	RKLBL9HE6G5252839
896	FM ECO4 LIGHT+ 3G	869530045150311	1/17/2023	N/A	6-72214	RKLBL9HEXK5265666
897	FM ECO4 LIGHT+ 3G	869530041991288	1/17/2023	C0045823	16-67547	RKLBL9HE5K5269740
898	FM ECO4 LIGHT+ 3G	869530045310584	8/8/2024	C0039222	AD-17-74953	2G1135S30J9127928
899	FM ECO4 LIGHT+ 3G	869530043227517	8/9/2024	C0040699	AD-7-52870	5FNYP6851JB700133
900	FM ECO4 LIGHT+ 3G	863003048305080	12/7/2024	C0056716	7-24980	JTNBF4HK0L3058189
901	FM ECO4 LIGHT+ 3G	868899043910989	12/7/2024	C0037246	3-78470	MHFDX8F58J0085129
902	FM ECO4 LIGHT+ 3G	867688036609018	7/11/2024	C0047173	17-66804	MHFDX8FS3K0098162
903	TRACE5 LTM (Rev.A) 4G	863257067752198	5/25/2023	C0053242	AD-8-93713	JL6B6E6PXHK017890
904	FM ECO4 LIGHT+ 3G	868899046783326	12/7/2024	C0056726	7-26532	JTNBF4HK9L3058370
905	TRACE5 IP-67 LTM (Rev.A) 4G	863514050794037	12/7/2024	C0063724	AD-16-19803	5N1DR3MRXPC237004
906	TRACE5 IP-67 LTM (Rev.A) 4G	863514050750831	12/7/2024	C0063725	AD-16-26641	5N1DR3MR6PC237744
907	FM ECO4 LIGHT+ 3G	868899046738825	12/6/2024	C0056671	15-50427	RKLBA0BE0L1001844
908	FM ECO4 LIGHT+ 3G	863003042133140	12/6/2024	C0056679	15-50281	RKLBA0BE1L1001853
909	FM ECO4 LIGHT+ 3G	863003042133470	12/6/2024	C0056696	9-65704	RKLBA0BE3L1001823
910	FM ECO4 LIGHT+ 3G	868899046752701	12/6/2024	C0056667	15-61743	RKLBA0BE0L1001794
911	FM ECO4 LIGHT+ 3G	868899046781684	8/27/2024	C0056674	15-50394	RKLBA0BE1L1001786
912	FM ECO4 LIGHT+ 3G	869530043178884	12/6/2024	C0059735	AD-18-62372	1N4BL4A99NN320096
913	FM ECO4 LIGHT+ 3G	863003048306302	12/6/2024	C0056666	15-66812	RKLBA0BE0L1001780
914	FM ECO4 LIGHT+ 3G	867688033159801	12/6/2024	C0040992	16-74149	RKLBB9HE7K5228450
915	FM ECO4 LIGHT+ 3G	867688032826533	12/6/2024	C0044484	6-62173	JTEBU3FJ7K5085323
916	FM ECO4 LIGHT+ 3G	868899046738023	12/6/2024	C0056676	15-50359	RKLBA0BE1L1001819
917	FM ECO4 LIGHT+ 3G	867553056753791	12/6/2024	C0052307	AD-10-29835	RKLBB0BE6L0013676

918	FM ECO4 LIGHT+ 3G	867553053369476	12/6/2024	C0052306	AD-10-29820	RKLBB0BE6L0013628
919	FM ECO4 LIGHT+ 3G	863003048349591	8/27/2024	C0056689	15-49897	RKLBA0BE2L1001831
920	FM ECO4 LIGHT+ 3G	868899046782708	12/6/2024	C0056681	15-49973	RKLBA0BE2L1001781
921	FM ECO4 LIGHT+ 3G	867688039824937	12/6/2024	C0049568	14-28560	JTNBZ4HK6K3010637
922	FM ECO4 LIGHT+ 3G	868899046752834	8/27/2024	C0056677	15-50346	RKLBA0BE1L1001822
923	FM ECO4 LIGHT+ 3G	868899046781197	12/6/2024	C0056684	15-49935	RKLBA0BE4L1001801
924	FM ECO4 LIGHT+ 3G	868899046781080	8/27/2024	C0056683	15-49936	RKLBA0BE4L1001815
925	FM ECO4 LIGHT+ 3G	866381051075031	12/6/2024	C0040707	DXB-V-48593	RKLBL9HE3K5265573
926	FM ECO4 LIGHT+ 3G	869530045215122	12/6/2024	C0043921	DXB-W-58518	WD4WG3E15K3558104
927	FM ECO4 LIGHT+ 3G	868899046751562	8/27/2024	C0056691	15-49874	RKLBA0BE2L1001859
928	FM ECO4 LIGHT+ 3G	867688036615262	12/6/2024	C0046795	6-32091	JTNBZ4HK8K3007853
929	FM ECO4 LIGHT+ 3G	868899046783508	12/6/2024	C0056687	15-49916	RKLBA0BE3L1001854
930	FM ECO4 LIGHT+ 3G	869530045177884	3/6/2024	C0041241	6-72178	RKLBL9HE6K5266460
931	FM ECO4 LIGHT+ 3G	867553057671745	10/31/2023	B0025277	AD-4-59276	JTGFB5185F1070928
932	FM ECO4 LIGHT+ 3G	863003042026591	8/2/2022	C0030877	AD-8-5631	JN8AY2NY5J9351544
933	FM ECO4 LIGHT+ 3G	868899046735946	12/6/2024	C0056672	15-50413	RKLBA0BE0L1001858
934	FM ECO4 LIGHT+ 3G	867688036760944	5/3/2023	B0053103	12-95917	LJM1HCGD9EAS00348
935	TRACES LTM (Rev.A) 4G	863257067740870	12/4/2024	C0036609	AD-15-18215	MR1DX8FS1H0008234
936	FM ECO4 LIGHT+ 3G	869530045136666	12/11/2023	C0024242	V-59586	WDDWG6FB4FA106212
937	FM ECO4 LIGHT+ 3G	869530045241631	12/9/2024	C0057603	AD-12-75614	JN18T2MW9LW016440
938	FM ECO4 LIGHT+ 3G	867688036771453	5/13/2023	B0049507	9-62194	JTGFE7284K6270374
939	FM ECO4 LIGHT+ 3G	869530045310535	12/11/2023	C0047964	O-28490	MDHBN7AD2KG685116
940	FM ECO4 LIGHT+ 3G	867688033151006	12/20/2023	C0046793	13-25947	JTNBZ4HK6K3009682
941	FM ECO4 LIGHT+ 3G	867688036770778	5/13/2023	B0053139	6-73142	LSFD132E6JC001509
942	FM ECO4 LIGHT+ 3G	869530045251812	12/11/2023	C0034048	T-57684	RKLBL9HE7G5254681
943	FM ECO4 LIGHT+ 3G	869530045190325	2/28/2023	B0015634	12-22431	JTGFB5188C1053293
944	FM ECO4 LIGHT+ 3G	867688032991436	5/13/2023	B0049399	10-36105	JTGFE7289K6270418
945	FM ECO4 LIGHT+ 3G	863003048305643	12/10/2024	C0046287	16-39586	JTEBU3FJ1KK164326
946	FM ECO4 LIGHT+ 3G	869530045159031	Removed- 3-March- 2021	C0052960	AD-9-89002	JTNBZ4HK4K3010782
947	FM ECO4 LIGHT+ 3G	867688036731499	5/16/2023	B0053099	7-60534	LJM1HCGD8EAS00342
948	FM ECO4 LIGHT+ 3G	869530041908977	11/16/2023	C0031674	AD-17-93105	JTMHU01J4G4128338
949	FM ECO4 LIGHT+ 3G	863003048306401	12/10/2024	C0056670	15-52749	RKLBA0BE0L1001830
950	FM ECO4 LIGHT+ 3G	869530045279441	12/11/2023	C0046851	J-41889	MDHBN7AD1KG682191
951	FM ECO4 LIGHT+ 3G	867688038864835	12/9/2024	C0050549	15-68739	JTNBZ4HK5K3010533
952	FM ECO4 LIGHT+ 3G	869530045185598	12/9/2024	C0052317	AD-10-31509	RKLBB0BE7L0013394
953	FM ECO4 LIGHT+ 3G	869530045145808	3/3/2021	C0046825	AD-12-36349	1N4AA6AP2KC369577
954	FM ECO4 LIGHT+ 3G	867688039845544	12/9/2024	C0046769	17-71476	JTNBZ4HK9K3009725
955	FM ECO4 LIGHT+ 3G	868899046782088	8/2/2022	H0031697	AD-17-63559	JL6B6E6P9GK011464
956	FM ECO4 LIGHT+ 3G	869530043220702	12/9/2024	C0054637	AD-7-44387	JTNBF4HK6L3050856
957	FM ECO4 LIGHT+ 3G	867688036761934	12/9/2024	C0049546	6-68263	JTNBZ4HK1K3010027
958	FM ECO4 LIGHT+ 3G	867688036777963	12/9/2024	C0046767	15-69139	JTNBZ4HK0K3009886

959	FM ECO4 LIGHT+ 3G	869530045168172	11/21/2023	C0036556	AD-13-64851	MR1DX8FS3H0008395
960	FM ECO4 LIGHT+ 3G	867688036730947	5/15/2023	B0053082	14-28199	LSFD832B8JC001500
961	FM ECO4 LIGHT+ 3G	869530045264153	2/3/2024	B0032351	17-86827	MB1PBEFB8GUAA4693
962	FM ECO4 LIGHT+ 3G	867688036613994	5/24/2023	B0048874	9-62243	JTGFE7280K6270386
963	FM ECO4 LIGHT+ 3G	869530045246358	1/0/1900	B0033352	17-62795	JL5B3J6P9GRP20974
964	FM ECO4 LIGHT+ 3G	867688036768186	5/11/2023	B0053080	17-67338	LSFD832B5JC001504
965	FM ECO4 LIGHT+ 3G	869530045173149	12/5/2024	B0053598	11-17646	JTGFE7288L6270606
966	FM ECO4 LIGHT+ 3G	867688039845312	5/4/2023	B0053052	16-93678	LSFD132E5FC000956
967	FM ECO4 LIGHT+ 3G	869530041367315	12/5/2024	B0031279	17-95376	JTGFB5188G1078796
968	FM ECO4 LIGHT+ 3G	867688036771412	5/16/2023	B0049396	10-36120	JTGFE7285K6270416
969	FM ECO4 LIGHT+ 3G	869530045240591	6/24/2022	B0038168	AD-13-30538	KL5UM52HEHU007367
970	FM ECO4 LIGHT+ 3G	867688036768251	5/18/2023	C0053147	10-73405	6T1BF9FK3HX656832
971	FM ECO4 LIGHT+ 3G	867688037043050	10/19/2023	C0041090	13-41363	MHFCX8EM4J011787
972	FM ECO4 LIGHT+ 3G	867688037019506	12/5/2024	B0037534	17-93620	KMJTG18V5HC025107
973	FM ECO4 LIGHT+ 3G	867688036746240	5/16/2023	B0049968	14-70734	LSFD132E6LC000055
974	FM ECO4 LIGHT+ 3G	863003048386148	12/5/2024	B0037533	A-93621	KMJTG18V3HHC025106
975	FM ECO4 LIGHT+ 3G	869530041905445	12/5/2024	B0053588	9-50498	JTGFE7284L6270554
976	FM ECO4 LIGHT+ 3G	867553053372942	5/25/2023	C0046121	AD-10-29368	JTNBF9HK5K3031386
977	FM ECO4 LIGHT+ 3G	863003042031518	8/1/2022	B0052692	AD-11-17928	JTGFE7281L6270589
978	FM ECO4 LIGHT+ 3G	863003048304950	12/5/2024	B0037210	17-98641	JMJTG18V3HC025123
979	FM ECO4 LIGHT+ 3G	867688036619165	12/5/2024	B0036770	9-31148	KMJTG18V5HC025110
980	FM ECO4 LIGHT+ 3G	867553053298501	7/18/2023	C0040693	AD-12-94642	VSKDD3C48JA094015
981	FM ECO4 LIGHT+ 3G	867688036754855	3/1/2021	B0012767	AD-10-80714	KMJTG18V4CC009411
982	FM ECO4 LIGHT+ 3G	869530045149206	12/5/2024	B0036508	SHJ--61784	JTGFB7180H6001923
983	FM ECO4 LIGHT+ 3G	863003048350375	12/5/2024	B0036760	12-36149	KMJTG18VXHC025121
984	FM ECO4 LIGHT+ 3G	867553053358511	8/26/2022	B0038166	AD-13-30536	KL5UM52HEHU007365
985	FM ECO4 LIGHT+ 3G	869530045144850	12/5/2024	B0016304	AD-8-46154	JTGFB5187D1055523
986	FM ECO4 LIGHT+ 3G	867688036741019	5/15/2023	B0053079	6-87438	LSFD832B2JC001492
987	FM ECO4 LIGHT+ 3G	868899043810486	5/4/2023	B0053044	9-55864	LSFD132EXGC000968
988	FM ECO4 LIGHT+ 3G	867688036771461	5/11/2023	B0049394	12-94623	JTGFE7280K6270422
989	FM ECO4 LIGHT+ 3G	863003042168054	12/5/2024	B0015438	12-17926	JTGFB5188C1052936
990	FM ECO4 LIGHT+ 3G	866191031527856	10/31/2021	B0044401	AJM-B-27691	JTGFE7283K6270110
991	FM ECO4 LIGHT+ 3G	869530041975133	3/1/2021	B0010180	AD-10-50865	KMJJK18B39C903430
992	FM ECO4 LIGHT+ 3G	869530045198864	7/13/2023	C0035215	15-66374	MR0DB8CD8H0115757
993	FM ECO4 LIGHT+ 3G	869530045180367	12/5/2024	B0013255	11-65112	KMJTG18BXC008817
994	FM ECO4 LIGHT+ 3G	869530041935400	12/12/2024	C0052558	9-50872	RKLB30BE5L0002245
995	FM ECO4 LIGHT+ 3G	869530041909553	12/12/2024	B0053527	17-54820	JTGFE7283L6270626
996	FM ECO4 LIGHT+ 3G	869530041906682	12/12/2024	C0039502	16-96381	JTEBX9FJ6JK294742
997	FM ECO4 LIGHT+ 3G	869530045189012	12/12/2024	C0052557	9-50882	RKLB30BE6L0002304
998	FM ECO4 LIGHT+ 3G	869530041915410	12/12/2024	B055188	9-47031	LSFD132E4LC000118
999	FM ECO4 LIGHT+ 3G	869530041932092	12/12/2024	C0052086	11-17734	2G1135S36K915266396
1000	FM ECO4 LIGHT+ 3G	869530045273063	1/0/1900	C0051681	12-34214	WD4WG3E13L3613330
1001	FM ECO4 LIGHT+ 3G	869530045278864	12/11/2024	B0034197	AD-17-23486	KMJWA37R2HU881473

1002	FM ECO4 LIGHT+ 3G	869530045232754	12/11/2023	C0024590	14-17429	JHHUCK1H6FK010857
1003	FM ECO4 LIGHT+ 3G	863003042033951	12/11/2023	C0037828	DXB-U-67021	RKLBB9HE7J5204891
1004	FM ECO4 LIGHT+ 3G	869530045190853	6/20/2022	C0033347	AD-17-38987	RKLBB9HE6G5162593
1005	FM ECO4 LIGHT+ 3G	869530045118672	12/11/2024	C0046123	DXB-U-12665	JTNBF9HK5K3031162
1006	FM ECO4 LIGHT+ 3G	867553053298246	7/18/2023	C0052318	AD-8-68293	VSKDD3C27LA129581
1007	FM ECO4 LIGHT+ 3G	869530045228406	3/2/2022	C0060361	AD-18-52213	1N4BL4A93NN355166
1008	FM ECO4 LIGHT+ 3G	869530045219884	12/11/2024	C0042590	AD-16-35683	JTNBF9HKXK3019962
1009	FM ECO4 LIGHT+ 3G	867688039781327	12/11/2024	C0049578	14-28475	JTNBZ4HK0K3010682
1010	FM ECO4 LIGHT+ 3G	869530045179682	12/11/2024	C0057013	16-91926	JTNBF9HK6L3056850
1011	FM ECO4 LIGHT+ 3G	869530045148190	Removed- 02-Apr- 2021	C0041754	AD-6-30921	JTEBU9HJ5KK152537
1012	FM ECO4 LIGHT+ 3G	867553059805341	12/11/2024	B0032262	AD-15-31896	JTGF85185G1079405
1013	FM ECO4 LIGHT+ 3G	869530045127103	11/16/2023	B0034290	15-67328	KMJWA37RUHU876811
1014	FM ECO4 LIGHT+ 3G	869530045114291	11/4/2022	C0057655	AD-13-74352	1GTZ79FG7L1223162
1015	FM ECO4 LIGHT+ 3G	863003048338313	12/11/2024	C0056664	15-79950	RKLBA0BEXL1001835
1016	FM ECO4 LIGHT+ 3G	869530045237001	12/11/2023	C0050124	Q-64428	MHKEF8BFOLK006643
1017	FM ECO4 LIGHT+ 3G	869530045249931	12/11/2024	C0033360	17-43828	JTNGE52M0H7134485
1018	FM ECO4 LIGHT+ 3G	869530043186275	12/11/2024	C0042528	AD-8-54725	4T1BZ1FB2KU015880
1019	FM ECO4 LIGHT+ 3G	869530045268063	12/11/2024	C0057607	AD-18-42635	JTNBF9HK9L3062075
1020	FM ECO4 LIGHT+ 3G	869530045127319	12/11/2024	C0044063	9-41864	MR0HX8CD8K1389500
1021	FM ECO4 LIGHT+ 3G	869530045179781	4/28/2022	C0060369	AD-18-53662	1N4BL4A97NN339360
1022	FM ECO4 LIGHT+ 3G	869530043178777	6/14/2024	C0039475	AD-16-94590	JTNBF4HK4J3002222
1023	FM ECO4 LIGHT+ 3G	869530045238264	9/14/2023	B0014797	8-19782	JTGF85188C1051057
1024	TRACE 5 LTE	863514051875066	12/11/2024	H0037904	AD-7-84182	JL7B6E1P8HK005126
1025	FM ECO4 LIGHT+ 3G	869530045208820	12/11/2024	C0057413	AD-13-82851	RKLBA0BE4L1002463
1026	FM ECO4 LIGHT+ 3G	869530045206121	12/11/2024	B0050396	15-98692	MB1PBEHD8KU0B1423
1027	TRACE5 LTM (Rev.A) 4G	863940058661144	12/11/2024	C0059912	AD-18-54942	1N4BL4A94NN325951
1028	TRACE5 LTM (Rev.A) 4G	863940058653018	12/11/2024	C0059935	AD-15-94216	1N4BL4A94NN326002
1029	TRACE5 LTM (Rev.A) 4G	863940058769996	7/6/2022	C0060643	AD-18-48355	JTNB19HK8N3170687
1030	TRACE5 LTM (Rev.A) 4G	863940058796692	12/11/2024	C0059918	AD-18-54947	1N4BL4A90NN325963
1031	FM ECO4 LIGHT+ 3G	869530045158561	12/19/2024	B0026173	12-79448	LSFD832B3GC000134
1032	FM ECO4 LIGHT+ 3G	869530045282643	12/21/2024	C0048643	AJM-B-82593	JTNB29HK7K3022376
1033	FM ECO4 LIGHT+ 3G	867553056762404	12/21/2024	C0051409	DXB-P-42452	MHFDX8FS1K0098693
1034	FM ECO4 LIGHT+ 3G	869530041387909	12/29/2024	B0042621	17-51305	LSKG5GC18KA041965
1035	FM ECO4 LIGHT+ 3G	869530045115058	12/29/2024	B0035773	15-74801	JL5B3J6P1GRP20967
1036	FM ECO4 LIGHT+ 3G	869530045206899	12/29/2024	B0042628	11-36715	LSKG5GC1XKA041983
1037	FM ECO4 LIGHT+ 3G	869530045160807	12/29/2024	B0042495	8-65345	JTGFE7187J6200111
1038	FM ECO4 LIGHT+ 3G	869530045255649	12/28/2024	B0042496	8-63476	JTGFE7183J6200168
1039	FM ECO4 LIGHT+ 3G	869530045213580	12/28/2024	B0026185	12-79419	LSFD832BXGC000180
1040	FM ECO4 LIGHT+ 3G	869530045157589	12/26/2024	B0026629	9-86825	LSFD832B0GC000317
1041	FM ECO4 LIGHT+ 3G	869530045240054	1/5/2025	B0026520	12-66854	LSFD832B3GC000313
1042	FM ECO4 LIGHT+ 3G	869530045149958	11/17/2023	B0022136	14-62787	JTGFB5187E1066250
1043	FM ECO4 LIGHT+ 3G	869530045133846	1/16/2025	C0057581	AD-18-42690	JTNBF9HK3L3058247

1044	FM ECO4 LIGHT+ 3G	869530045172554	10/30/2024	C0047917	DXB-L-91037	MDHAK3CR1KG001050
1045	FM ECO4 LIGHT+ 3G	869530041402070	1/12/2025	B0042624	17-51270	LSKG5GC17KA041973
1046	FM ECO4 LIGHT+ 3G	868899043977236	1/16/2025	B0050009	6-57504	0
1047	FM ECO4 LIGHT+ 3G	869530041912516	1/0/1900	B0052464	AD-17-27150	JL5BHJ654LRP21403
1048	FM ECO4 LIGHT+ 3G	869530045259054	1/0/1900	B0026200	9-57049	KMJWA37R7GU748321
1049	FM ECO4 LIGHT+ 3G	869530045286743	1/14/2025	B0026204	11-16713	KMJWA37R1GU749769
1050	FM ECO4 LIGHT+ 3G	867688036619785	1/14/2025	B0026221	11-17138	KMJWA37R6GU749380
1051	FM ECO4 LIGHT+ 3G	869530045175144	1/14/2025	B0032687	AD-17-52915	KMJWA37R7HU859730
1052	FM ECO4 LIGHT+ 3G	869530045286990	5/25/2023	B0015251	12-17625	JTGFB5187C1052412
1053	FM ECO4 LIGHT+ 3G	869530045237076	1/14/2025	B0026217	11-17078	KMJWA37R7GU749422
1054	FM ECO4 LIGHT+ 3G	869530045114481	1/14/2025	B0037197	M-17062	KMJWA37R2HU896703
1055	FM ECO4 LIGHT+ 3G	869530041904802	6/30/2021	B0036954	AD-11-43051	JTGFB7180H6002554
1056	FM ECO4 LIGHT+ 3G	869530045210396	1/18/2025	C0057590	AD-14-59131	MHFB29F36M2119307
1057	FM ECO4 LIGHT+ 3G	869530045174352	10/30/2023	C0048775	SHJ-2-71502	KL1ZA5CA5JB053117
1058	FM ECO4 LIGHT+ 3G	868899046781791	1/18/2025	C0056688	15-49907	RKLBA0BE3L1001840
1059	TRACES LTM (Rev.A) 4G	866381051067889	10/30/2023	C0055165	DXB-F-76413	VF14SRAB3LT560791
1060	FM ECO4 LIGHT+ 3G	866381051070883	1/22/2025	C0058707	AD-19-26317	VR3E1NFJ2NJ512858
1061	FM ECO4 LIGHT+ 3G	869530045144934	1/22/2025	C0044568	DXB-D-18193	MHFDX8FS0K0096465
1062	FM ECO4 LIGHT+ 3G	869530045281207	1/22/2025	0	2-51338	MHFDX8FS5M0109441
1063	FM ECO4 LIGHT+ 3G	869530045184377	1/22/2025	C0044567	DXB-D-19285	MHFDX8FSXK0096537
1064	FM ECO4 LIGHT+ 3G	869530045310089	1/22/2025	C0054949	DXB-S-40688	MHFKU8FS7L0181787
1065	FM ECO4 LIGHT+ 3G	869530045248438	1/22/2025	C0040713	DXB-V-46312	MHFDX8FS7J0090323
1066	FM ECO4 LIGHT+ 3G	869530045114341	1/22/2025	C0044574	DXB-D-25933	MHFDX8FS1K0096703
1067	FM ECO4 LIGHT+ 3G	869530045298342	1/22/2025	C0044571	DXB-D-26652	MHFDX8FS8K0096603
1068	FM ECO4 LIGHT+ 3G	867688032815213	1/0/1900	C0045037	5-69585	MR0DX9CD0K2521986
1069	FM ECO4 LIGHT+ 3G	866381051077862	9/21/2023	C0034474	SHJ-3-55803	MMBMG45H6HH012003
1070	FM ECO4 LIGHT+ 3G	867553059767426	10/30/2023	C0027157	DXB-R-29305	MHFXX42G3F5034848
1071	FM ECO4 LIGHT+ 3G	868899043833975	1/22/2025	C0051769	P-73622	VSKDD3C4XLA130130
1072	FM ECO4 LIGHT+ 3G	869530041901931	9/12/2023	C0019185	2-25194	MNTBD0E5E9E6613416
1073	FM ECO4 LIGHT+ 3G	869530045204225	1/23/2025	C0056117	1-35940	MEC201DP4LP042066
1074	FM ECO4 LIGHT+ 3G	869530045184609	9/21/2023	C0044602	D-69543	MDHBN7AD1KG671367
1075	TRACES LTM (Rev.A) 4G	869738069862121	1/22/2025	H0056140	SHJ-3-34289	MEC0463P8KP036084
1076	FM ECO4 LIGHT+ 3G	863003042146522	7/19/2023	C0055536	S 19206	VF1HSRMX1LA567078
1077	FM ECO4 LIGHT+ 3G	869530041908712	1/23/2025	B0037036	11-34087	JTGFB7182H6002233
1078	FM ECO4 LIGHT+ 3G	867688039336320	9/21/2023	H0051921	I-74275	MEC201DP6LP039282
1079	FM ECO4 LIGHT+ 3G	866381051071956	1/22/2025	C0056108	SHJ-3-51882	MEC201DP3LP042009
1080	FM ECO4 LIGHT+ 3G	866381051098546	9/12/2023	C0037298	SHJ-3-79363	MMBMG45H8HH024475
1081	FM ECO4 LIGHT+ 3G	869530045179583	7/19/2023	C0044627	D-46391	MDHBN7AD9KG671262
1082	FM ECO4 LIGHT+ 3G	869530045129703	8/11/2022	C0028715	DXB-D-45234	MDHBN7AD8GG710799
1083	FM ECO4 LIGHT+ 3G	866381051074166	9/12/2023	C0034440	SHJ-3-55602	MDHBN7AD7GG745303
1084	FM ECO4 LIGHT+ 3G	869530045211048	1/21/2025	C0052142	DXB-K-26524	MHKEF8BF7LK008843
1085	TRACES LTM (Rev.A) 4G	863514050814116	1/22/2025	0	MMBMGU5H8PH003947	MMBMGU5H8PH003947
1086	FM ECO4 LIGHT+ 3G	869530045135049	1/21/2025	C0052596	DXB-Q-80031	MHKEF8BFXLK009694

1087	FM ECO4 LIGHT+ 3G	866381051073663	7/18/2023	C0036857	SHJ-3-77192	MMBMG35H5HH026940
1088	FM ECO4 LIGHT+ 3G	869530045209620	6/8/2023	C0044635	D-46326	MDHBN7ADXKG671254
1089	FM ECO4 LIGHT+ 3G	869530045119555	10/30/2023	C0045811	DXB-H-62886	VF14SRAB6KT486863
1090	FM ECO4 LIGHT+ 3G	869530045189905	7/19/2023	C0044618	D-69525	MDHBN7AD5KG671341
1091	TRACE5 LTM (Rev.A) 4G	863257068978537	12/11/2023	C0039622	DXB-K-81634	MNTBB7A98J6056316
1092	FM ECO4 LIGHT+ 3G	869530045209265	1/20/2025	B0035771	SHJ-15-74807	JL5B3J6P3GRP20985
1093	FM ECO4 LIGHT+ 3G	867553057654998	1/20/2025	C0045123	AD-6-87973	MR0DB9CD6K5141371
1094	FM ECO4 LIGHT+ 3G	867688039343714	10/31/2021	C0035046	AJM-A-31746	JTFHX02PXH0111814
1095	FM ECO4 LIGHT+ 3G	869530045281165	1/0/1900	C0047414	DXB-M-68009	MHFDX8FS4K0098686
1096	FM ECO4 LIGHT+ 3G	869530045184302	1/0/1900	C0044564	DXB-D-24483	MHFDX8FS8K0096522
1097	FM ECO4 LIGHT+ 3G	869530041961687	1/0/1900	C0040675	SHJ-3-12585	MHFDX8FS1J0090852
1098	FM ECO4 LIGHT+ 3G	869530045247786	1/0/1900	C0033275	DXB-S-83493	MR1DX8FS1H0007102
1099	FM ECO4 LIGHT+ 3G	867553058478843	6/7/2023	C0025933	DXB-Q-47325	MDHBN7AD1GG707131
1100	FM ECO4 LIGHT+ 3G	869530045117948	1/28/2025	C0045015	2-15870	JTNBF9HK3K3028177
1101	FM ECO4 LIGHT+ 3G	869530045118102	1/28/2025	C0033266	WHITE-38209	MR1DX8FS7H0006875
1102	FM ECO4 LIGHT+ 3G	869530045139256	2/13/2025	C0047767	3-37917	MHFDX8FS6K0098656
1103	FM ECO4 LIGHT+ 3G	869530045117971	1/28/2025	C0047769	3-37805	MHFDX8FS5K0098678
1104	FM ECO4 LIGHT+ 3G	869530045266661	1/28/2025	C0045067	2-29852	MHFDX8FS0K0097146
1105	FM ECO4 LIGHT+ 3G	867688039809482	9/12/2021	C0040463	SHJ-2-58456	MHFDX8FS8J0089617
1106	FM ECO4 LIGHT+ 3G	869530045139181	1/28/2025	C0045068	2-53293	MHFDX8FS2K0096855
1107	FM ECO4 LIGHT+ 3G	869530045266406	1/28/2025	C0047771	3-37886	MHFDX8FS5K0098647
1108	FM ECO4 LIGHT+ 3G	867553057656787	1/19/2022	C0059622	DXB-Q-99649	MHFku8FS3N0186357
1109	FM ECO4 LIGHT+ 3G	869530045149164	1/28/2025	C0045071	2-29864	MHFDX8FS0K0096644
1110	FM ECO4 LIGHT+ 3G	867688032969887	2/1/2025	B0050040	A-16233	KMJWA37R0LU098614
1111	FM ECO4 LIGHT+ 3G	866381051032412	8/9/2022	C0060152	AD-50-83689	JTNB29HKXN3118474
1112	FM ECO4 LIGHT+ 3G	867688039342047	2/1/2025	C0050402	1-92463	JTNB29HK8K3026937
1113	FM ECO4 LIGHT+ 3G	867688039796259	2/1/2025	C0050400	B-14611	JTNB29HKXK3036546
1114	FM ECO4 LIGHT+ 3G	867688039821149	2/12/2020	N/A	11-19244	JTGFE7287L6270614
1115	FM ECO4 LIGHT+ 3G	869530041394806	1/31/2025	B0043722	11-32657	LSKG5GC11KA042438
1116	FM ECO4 LIGHT+ 3G	869530041404357	1/29/2025	B0043725	11-33092	LSKG5GC12KA042447
1117	FM ECO4 LIGHT+ 3G	869530041415296	2/2/2025	B0042626	11-36703	LSKG5GC18KA041979
1118	FM ECO4 LIGHT+ 3G	869530041408747	2/2/2025	B0043726	9-44397	LSKG5GC12KA042433
1119	FM ECO4 LIGHT+ 3G	869530045249865	2/2/2025	B0042627	17-51203	LSKG5GC16KA041981
1120	FM ECO4 LIGHT+ 3G	869530041395712	2/2/2025	B0042629	11-36726	LSKG5GC13KA041968
1121	FM ECO4 LIGHT+ 3G	869530041390804	2/2/2025	B0042625	11-36716	LSKG5GC19KA041974
1122	FM ECO4 LIGHT+ 3G	869530041360963	2/2/2025	B0042622	11-36701	LSKG5GC1XKA041966
1123	TRACE5 LTM (Rev.A) 4G	863257067808495	2/3/2025	C0053758	DXB-C-91612	MMBMG45H7LH004226
1124	FM ECO4 LIGHT+ 3G	868899046784233	2/3/2025	B0055436	L-65841	MB1PAEHD4LU1B2754
1125	FM ECO4 LIGHT+ 3G	869530045267164	2/3/2025	B0033973	T-49611	JTGFB518XG1080243
1126	FM ECO4 LIGHT+ 3G	867553058470006	12/7/2023	C0040739	DXB-V-67408	JL6B9H6J3HK011627
1127	FM ECO4 LIGHT+ 3G	867553059810416	2/3/2025	B0033412	AD-17-62785	JL5B3J6P4GRP21367
1128	FM ECO4 LIGHT+ 3G	868899046735821	2/3/2025	B0055434	N-13902	MB1PAEHD5LU1B2746
1129	FM ECO4 LIGHT+ 3G	869530045301385	12/16/2022	B0023926	Q-28632	JL5B3J6P6FRN20214

1130	FM ECO4 LIGHT+ 3G	869530043185756	2/5/2025	C0037158	DXB-U-35175	JTFPX22P3H0078484
1131	FM ECO4 LIGHT+ 3G	867688039289388	2/6/2025	C0054074	F-51629	5N1DR2M59LC575186
1132	FM ECO4 LIGHT+ 3G	868899043923214	2/6/2025	C0055137	H-29204	5N1DR2M58LC575213
1133	FM ECO4 LIGHT+ 3G	868899043908942	2/6/2025	C0055136	H-25386	5N1DR2M56LC575310
1134	FM ECO4 LIGHT+ 3G	866381052392088	2/7/2025	C0058712	AD-16-73267	MMBMGU5H2MH005088
1135	FM ECO4 LIGHT+ 3G	867688038866954	2/8/2025	C0050352	G-76236	JTNB29HK9K3027109
1136	FM ECO4 LIGHT+ 3G	867688039824978	2/8/2025	C0051412	P-42140	RKLBA0BE2L1000405
1137	FM ECO4 LIGHT+ 3G	867688036617540	2/8/2025	PV66806	O-70830	1GCWGW9CG0H1337292
1138	FM ECO4 LIGHT+ 3G	868899043953872	2/8/2025	SA016	S-66189	JN8BY2NY3H9006172
1139	FM ECO4 LIGHT+ 3G	867688035668643	8/3/2022	C0060153	AD-50-83685	JTNB29HK8N3118473
1140	FM ECO4 LIGHT+ 3G	867688035667181	2/8/2025	PV44444	B-57470	1GNER8KW2JJ147421
1141	FM ECO4 LIGHT+ 3G	867688036747172	11/1/2022	SA014	B-25443	MHFXX43GXE0053388
1142	FM ECO4 LIGHT+ 3G	867688039813534	2/8/2025	B0050206	C-41858	KMJWA37R2LU097884
1143	FM ECO4 LIGHT+ 3G	867688039830256	2/8/2025	C0050721	C-36512	MHFDX8F50K0099611
1144	FM ECO4 LIGHT+ 3G	869530041964483	2/8/2025	C0042568	C-42437	2G1135S30K9105512
1145	FM ECO4 LIGHT+ 3G	867688039784131	2/8/2025	SA015	F-98721	JN6AE52S1DX116934
1146	FM ECO4 LIGHT+ 3G	867688036772519	2/8/2025	C0050025	K-15692	WBA7T2A00LB452407
1147	FM ECO4 LIGHT+ 3G	867688036767857	2/8/2025	C0050208	G-45159	2G1135S34K9141722
1148	FM ECO4 LIGHT+ 3G	867688036768046	2/8/2025	C0050210	G-46486	2G1135S34K9150744
1149	FM ECO4 LIGHT+ 3G	869530045149800	2/9/2025	B0042611	17-31657	JTGFE7183J6200221
1150	FM ECO4 LIGHT+ 3G	867553056774979	2/9/2025	B0055097	AD-5-54263	JTGFE7280L6270664
1151	FM ECO4 LIGHT+ 3G	869530045301153	4/1/2022	B0031303	DXB-V-47732	JTGSX23P1G6167826
1152	FM ECO4 LIGHT+ 3G	869530045278724	2/11/2025	B0056888	SHJ-2-95450	JN6BE6DS4L9064581
1153	FM ECO4 LIGHT+ 3G	867553057593469	2/11/2025	C0036517	SHJ-36532	6T1BF9FK9HX689768
1154	FM ECO4 LIGHT+ 3G	869530045282676	2/11/2025	C0050925	FUJ-C-38784	JTNGE52MXK7174905
1155	FM ECO4 LIGHT+ 3G	869530045280704	2/11/2025	C0036371	SHJ-63065	6T1BF9FK7HX690417
1156	FM ECO4 LIGHT+ 3G	869530043778261	2/11/2025	C0050926	FUJ-C-38774	JTNGE52MOK7175013
1157	FM ECO4 LIGHT+ 3G	867553057671919	2/11/2025	C0036513	SHJ-WHITE-35991	RKLBB9HE8H5190803
1158	FM ECO4 LIGHT+ 3G	869530045306814	2/11/2025	C0056835	SHJ-2-14237	JTNBF9HK3L3056756
1159	FM ECO4 LIGHT+ 3G	867553053275459	2/11/2025	C0051341	UAQ-A-13570	RKLBB9HE8K5238713
1160	FM ECO4 LIGHT+ 3G	867553057651184	2/11/2025	C0051339	UAQ-A-75006	RKLBB9HE4K5238997
1161	FM ECO4 LIGHT+ 3G	867553057661811	2/11/2025	C0045468	FUJ-C-10652	RKLBB9HE3K5238392
1162	FM ECO4 LIGHT+ 3G	869530045313059	2/11/2025	C0056875	DXB-O-24727	RKLBB0BE8L0026896
1163	FM ECO4 LIGHT+ 3G	869530045311970	2/11/2025	C0050928	FUJ-C-38779	MHFKU8F5XX0178588
1164	FM ECO4 LIGHT+ 3G	867553053296844	2/11/2025	C0056640	DXB-Q-70558	MDHBN7AD1LG737675
1165	FM ECO4 LIGHT+ 3G	869530045285950	10/30/2023	B0048656	O-28796	KMJWA37R2LU089073
1166	FM ECO4 LIGHT+ 3G	867553053378717	2/12/2025	C0054852	DXB-G-86031	RKLBA0BE8L1001297
1167	FM ECO4 LIGHT+ 3G	869530045135767	2/13/2025	C0045025	C-80765	MHFDX8F54K0096761
1168	FM ECO4 LIGHT+ 3G	869530043203781	1/19/2022	C0059623	DXB-Q-99527	MHFKU8FS2N0186365
1169	FM ECO4 LIGHT+ 3G	869530045118516	11/9/2021	C0059626	DXB-Q-99387	MHFKU8FS0N0186414
1170	FM ECO4 LIGHT+ 3G	869530045135932	2/13/2025	C0045021	C-80753	MHFDX8FS3K0097139
1171	FM ECO4 LIGHT+ 3G	869530045184468	2/13/2025	C0045019	C-80749	MHFDX8FS3K0096900
1172	FM ECO4 LIGHT+ 3G	869530045153604	2/13/2025	C0033244	C-31748	MR1DX8FS9H0007039

1173	FM ECO4 LIGHT+ 3G	869530045137631	2/13/2025	C0047415	M-68017	MHFDX8FS4K0098669
1174	FM ECO4 LIGHT+ 3G	869530045131691	2/13/2025	C0045018	C-80748	MHFDX8FS5K0096641
1175	FM ECO4 LIGHT+ 3G	869530045150170	2/13/2025	C0045029	C-80755	MHFDX8FS2K0097004
1176	FM ECO4 LIGHT+ 3G	869530045183411	2/13/2025	C0045028	C-80761	MHFDX8FS2K0097066
1177	FM ECO4 LIGHT+ 3G	869530045200561	2/13/2025	C0045020	C-80763	MHFDX8FS2K0096984
1178	FM ECO4 LIGHT+ 3G	869530045261571	1/28/2025	C0047770	3-37884	MHFDX8FS5K0098650
1179	FM ECO4 LIGHT+ 3G	869530045185382	2/13/2025	C0045026	C-80751	MHFDX8FS3K0097142
1180	FM ECO4 LIGHT+ 3G	869530045293434	2/13/2025	C0054899	C-75443	JTNBF9HK4L3052540
1181	FM ECO4 LIGHT+ 3G	869530045200041	2/13/2025	C0045022	C-80754	MHFDX8FS4K0097134
1182	FM ECO4 LIGHT+ 3G	869530043175096	2/12/2025	B0025380	AD-10-89165	KMHWG81R8GU734577
1183	FM ECO4 LIGHT+ 3G	869530045225253	2/12/2025	C0032994	17-70371	5N1AR2M58GC621728
1184	TRACES LTM (Rev.A) 4G	863257068996703	2/12/2025	C0062513	AD-6-54810	JTNB24HK2P3134982
1185	FM ECO4 LIGHT+ 3G	863003048350243	2/12/2025	C0041021	12-67086	1N4AL3A99JC107838
1186	FM ECO4 LIGHT+ 3G	869530043178710	2/14/2023	C0040115	AD-8-69120	RKLBB9HE7J5225353
1187	FM ECO4 LIGHT+ 3G	869530043195268	2/12/2025	C0057830	AD-10-39721	MROJX8CD7M3644632
1188	FM ECO4 LIGHT+ 3G	869530045126923	5/22/2023	B0013879	5-16536	JTGBF5188C1046991
1189	FM ECO4 LIGHT+ 3G	869530041394814	2/10/2025	B0042630	11-36706	LSKG5GC16KA041978
1190	FM ECO4 LIGHT+ 3G	869530045124415	2/10/2025	B0032677	17-43835	JTGSX23P9G6172899
1191	FM ECO4 LIGHT+ 3G	867553057661746	2/14/2025	C0051336	UAQ-A-99662	JTNGE52M7K7172075
1192	FM ECO4 LIGHT+ 3G	867553057649907	2/14/2025	C0045544	UAQ-A-33919	JTNBF9HK7K3029526
1193	FM ECO4 LIGHT+ 3G	867553057661357	2/14/2025	B0056849	UAQ-A-72153	JN6BE6DS4L9064659
1194	FM ECO4 LIGHT+ 3G	867553057629453	2/14/2025	H0056436	UAQ-A-26084	MEC201DP1LP040842
1195	FM ECO4 LIGHT+ 3G	867688033153697	2/14/2025	C0035047	A-4583	1GCZG9CG2H1106858
1196	FM ECO4 LIGHT+ 3G	867553057650277	2/14/2025	C0030290	SHJ-2-95404	1GCZG9FG5G1158592
1197	FM ECO4 LIGHT+ 3G	867553057671596	2/14/2025	C0051338	UAQ-A-49864	RKLBB9HE3K5238988
1198	FM ECO4 LIGHT+ 3G	867553057652000	2/14/2025	C0056958	UAQ-A-69967	JTNBF9HK9L3056390
1199	FM ECO4 LIGHT+ 3G	869530045244064	2/14/2025	C0029072	SHJ-2-62876	1GCZG9CG7F1270085
1200	FM ECO4 LIGHT+ 3G	869530045181498	2/14/2025	C0029999	SHJ-1-21060	1GCZG9FGXG1158202
1201	FM ECO4 LIGHT+ 3G	867553057668485	2/14/2025	C0048644	UAQ-A-99661	JTNB29HK5K3022392
1202	FM ECO4 LIGHT+ 3G	867553057661274	2/14/2025	C0056848	UAQ-A-21483	VSKDD3C29LA136726
1203	FM ECO4 LIGHT+ 3G	867553057634263	2/14/2025	C0051337	UAQ-A-60795	RKLBB9HE2K5238819
1204	FM ECO4 LIGHT+ 3G	869530045294663	2/14/2025	C0029070	SHJ-2-62607	1GCZG9CG1F1273029
1205	FM ECO4 LIGHT+ 3G	867553057649543	2/14/2025	C0056512	UAQ-A-26473	JTFPX22P2L0093616
1206	FM ECO4 LIGHT+ 3G	867553057661803	2/14/2025	C0056435	UAQ-A-25619	JTFPX22P2L0093700
1207	FM ECO4 LIGHT+ 3G	867553059806075	2/14/2025	C0029058	SHJ-2-62490	1GCZG9CG6F1273544
1208	FM ECO4 LIGHT+ 3G	869530041395423	9/12/2023	C0042383	C-29941	MMBMG45H9HH025084
1209	FM ECO4 LIGHT+ 3G	869530045170665	7/17/2023	C0044596	D-69181	MDHBN7AD7KG671549
1210	FM ECO4 LIGHT+ 3G	868899046774135	2/13/2025	C0056685	15-49927	RKLBA0BE4L1001796
1211	FM ECO4 LIGHT+ 3G	869530041912532	9/14/2023	B0014685	8-27147	JTGBF518XC1050587
1212	FM ECO4 LIGHT+ 3G	866381051069836	9/13/2023	C0036879	SHJ-3-77062	MR1DX8FS9H0008806
1213	FM ECO4 LIGHT+ 3G	869530045122468	11/4/2022	C0014291	H-15287	MROFR22G3C0673134
1214	FM ECO4 LIGHT+ 3G	869530045141286	7/17/2023	C0037303	3-81227	MMBMG45H0HH023207
1215	FM ECO4 LIGHT+ 3G	866381051070495	7/18/2023	C0037308	SHJ-3-79357	MMBMG45H2HH023645

1216	FM ECO4 LIGHT+ 3G	869530045190978	9/14/2023	B0015618	AD-12-21429	JTGFB5182C1053239
1217	FM ECO4 LIGHT+ 3G	867553057659658	6/8/2023	C0044626	DXB-D-46783	MDHBN7AD8KG671480
1218	FM ECO4 LIGHT+ 3G	867553057661696	7/19/2023	C0044641	DXB-D-69313	MDHBN7ADXKG671352
1219	FM ECO4 LIGHT+ 3G	866381051068655	9/21/2023	C0036832	SHJ-3-77165	MDHBN7AD4JG620458
1220	FM ECO4 LIGHT+ 3G	866381051065693	12/7/2023	C0040736	DXB-V-67411	JL6B9H6J8HK011591
1221	FM ECO4 LIGHT+ 3G	869530045134547	2/17/2025	C0030293	SHJ-WHITE-31449	1GCZG9FG3G1158994