

Comprehensive Test Certificate (With OBD)

Plate# : R 62080

Chassis#: JN8AY2ND5H9009874 Vehicle Make & Model: Nissan Armada

Body Type : Station Fuel: Petrol Color : Gray

Origin: Japan Engine# : NILL Model/Year: 2017 Current Odometer: 113814

Engine Size : 5600 HP: 400 Cylinders: 8 No of Seats : 8 Unloaded Wt : 2441

Loaded Wt: 3000 No of Doors : 4 Gear Type : Automatic Certificate# : COM-GNL-0000011053

Inspection Date: 10-09-2024 Total Time Taken: 00:42:00

Attempt: 1 GCC : No Token#: 8008

Printed by : Fahmi Ghlissi

Report Printed Time: 10-09-2024 21:19

Report Printed Count : 1

#### Visual Inspection

Details	Remarks	مالاء
Paint	BODY PORTION REPAIR & REPAINTED / NON METAL AREA PAINT NOT TESTED	حاثة المجسد والإبواب
Body Condition & Doors	MINOR DENT & SCRATCHES ON BODY / BODY PARTS OPEN & REFIXING / VEHICLE BODY CHANGE FROM NISSAN ARMADA TO N  ISSAN NISMO / BONNET SHOCK HARD	بمسان
Bumber	FRONT & REAR BUMPER REPAINTED / MINOR SCRATCHES ON BUMPERS / FRONT BUMPER GRILL MISALIGNED & DAMAGE	بطلع الاصداءه والاشتراء
Lights and Signals	BOTH SIDE HEADLIGHT MISALIGNED	ريع / النظار ال
Rim/Tires	FRONT BOTH SIDE TIRE DOT 2022 WORN OUT & CRACK / REAR BOTH SIDE DOT 2023 MINOR DRY CRACK / DENT & SCRATCHES ON RIMS	and the second second
Interior (Seat/Seat Belt/Air Bags)	DRIVER SEATS COVER SIDE DAMAGE / INTERIOR SEATS COVER REFABRICATED / INNTEROIR ROOF LIGHTS & SUNSHIELD LIG HTS NOT WORKING / RPM NOT WORKING PROPORLY	السفاعد / الاحرسة / حقيبة اليبواء سائدة / نواف
Window/WindowSheilds	FRONT WINDSHEILD REPLACED / FRONT OUTER WINDSHEILD RUBBER WORN OUT	لوجه الصادة والعموب
DashBoard & Audio	DASHBOARD COVER REFABRICATED / RPM NOT WORKING PROPERLY ON DAHSBOARD	المقود
Steering System	POWER STEERING OIL LEAKING	المساعات
Wipers& Motor	WIPER BLADE WORN OUT	الحصير الباجلي ويطالة السف
Interior Floor Mats & Roof Liner	INTERIOR ROOF LINER & PILLER COVER REFABRICATED	كسرات / احيرة استشعار
	ОК	المعتب الكهر سية
Camera & Sensors	ОК	
Electrical Switches	ALL BRAKES DISC GETTING RUSTY & LINE / BRAKES PADS GETTING TO LIMIT / HANDE BRAKE LOSS	الغر امل و الحطوط
Brakes & Lines	OK	مطام تكبيف الهواء
Air Conditioning System (A/C)	ENGINE OIL LEAK & COMPARTMENT ENGINE DIRTY & MUDDY / ENGINE WATER COOLANT LEAKING	انظمة المحرك والعناد
Engine & Gear Systems	FRONT BOTH SIDE LOWER ARM BUSHES MINOR DRY CRCAK	بطنه التعليق / العشم
Suspension/Exhaust System		اشنصى
Chassis Frame	FRONT RIGHT SIDE CHASSIS REPAIRED / FOR FULL INSPECTION MAKE PROPER STEAM WASH FOR RECHECK	نحب السبيره ونطاء الوقود
Under Flooring and Fuel System	UNDER BODY FULLY DIRTY & MUDDY / SUSPENTION PARTS GETTING RUSTY	بطائم اللطل
Transmission System	NO SIGN OF LEAK	1 N . 6 Name
	Test Certificate Attached Externally شهادة اختبار مرفقة حرجيا	وحدة النحكم في المعرك
Engine Control Unit(O.B.D)	Volume Petrol CO Reading	Vehicle on Patrol HC Reading

Engine Control Unit(O.B.D)		شهادة اختبار مرفقة خارجيا		and the second description of the	
	Pear Avie	Parking Brake Imbalance b/w LHS and RHS	Vehicle on Patrol CO Reading	Vehicle on Patrol HC Reading	
Service Brake Imbalance on Front Axle	Service Brake imbalance si	PASS	PASS	PASS	
PASS	PASS				

VEHICLE ROAD TEST NO DONE / FRONT RIGHT SIDE INNER FENDER FRAME, BULKHEAD, RADIATOR SUPPORT, BUMPER FRAME, APRON REPAIRED

Inspected By

Inspection Location

Fahmi Ghlissi

Al Zoumorrod- Al Qouz 2

This Test Certificate shows the Test Result at The Time Of Inspection Only. Almutakamela is not Responsible for Any Hidden Defects and further consequences

المتكاملة لتسجيل و" قيد النصر الثانل عبر عدفع الأمادات والمركز غير مسرول عن اي اعدال خفية بعد لجراء الفحص المستكاملة لتسجيل و" وي اعدال خفية بعد لجراء الفحص المستكاملة المستكاملة على ال 21 MIJ TAXAMELA VEHICLES TESTING AND REGISTRATION L.L.C الفحص الشامل COMPREHENSIVE لايعتمد الأجراء المعاسلات PPORT COMPLETION OF TRANSACTIONS

This Certificate is not valid for Renewal or Registration.

الشهادة غير صالحة لغايات النسجبل والنجديد



Shop: --Tel: --Email: -Address: -- Report ID: MAXIA20240910160730 Test Time: 2024-09-10 16:07:30

Technician: --

# 2017 Nissan VEHICLE DIAGNOSTIC REPORT

**Vehicle Information** 

2017/Nissan/Armada/ VIN: JN8AY2ND5H9009874

**Customer Information** 

Name: --

**Device information** 

Scanner: MaxiDAS DS808

Version: V9.90

Odometer Reading: --License Plate: --

Tel: --

Serial Number: DS7GK4C01832

Repair Order Number: --

## System Scanned( 14 )

System	11 . 11 . 1	11	1
Engine	0	0	
Transmission	3	2	
ABS	3	1	
Air bag	0	0	
Meter/M&A	0	0	
Air pressure monitor	0	0	
BCM	3	1	
HVAC	3	2	
Multi AV .	0	0	
IPDM E/R	0	0	
Auto back door	0	0	ĺ
E-SUS	0	0	١

## **DTC (10)**

### Transmission (2 DTCs)

Occupant detection

DTC

Description

P0725

Sonar

'Engine speed

Past

U1000

. CAN COMM circuit

CRNT

AUTEL www.autel.com

MaxiDAS DS808



Report ID: MAXIA20240910160730 2017/Nissan/Armada/ Test Time: 2024-09-10 16:07:30 ABS (1 DTC)

5-5 Statut

C1116 Past Stop lamp switch

BCM (1 DTC)

B26FE Past . Hood switch CAN diagnosis error

HVAC (2 DTCs)

CTC Description

B2631 Sunload sensor Current

Pass sunload sensor B2668 Current

Sonar (4 DTCs)

0.0 Description B2701 Sensor harness circuit open (CR-left front) 39 time B2703 Sensor harness circuit open (CR-right front) 39 time

39 time B270D Sensor harness open (CT-left front)

B270F Sensor harness open (CT-right front) 39 time

**Technician Notes** 

Customer name:

Technician:

Date:

Note:Please save a copy of this report for your records.

Distribution This report provides a time content of values inspection and maintenance any Autotis not kaple for any action of the loss of this intermation.

