

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: HYUNDAI/H1
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 19 SEP 2024 11:50:46	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN PASSENGER
Token Number	: 9	Un laden Weight	: 2000
Transaction Number	: 34622924	Laden Weight	: 2800
Reference import Doc.	: 962896 DSC	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 12
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: KMJWA37R0JU962896	Odometers	: 196329

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.220	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 102.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Ties Rods, Bushes, Center Link, Left And Right		SUSPENSION BUSHES CRACKED.		ربلات ذراع التوجيه
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2022, WORN OUT.		الاطارات الامامية
Rear Left And Right Hand Tires		DOT 2019-2022, WORN OUT.		الاطارات الخلفية
Body				الهيكل
Rusty		UNDERNEATH AND SUSPENSION PARTS RUSTY		الصدأ
Floor		BACK PANEL,COMARTMENT REPAIRED.		الارضية
Floor		UNDERNEATH RUST PROOF COATED		الارضية
Chassis (Frame)		FRONT BOTH SIDE FRAME MEMBER REPAIRED.		الشاصية
Front And Rear Windshields		FRONT WINDSHIELD CRACKED.		الزجاج الامامي والخلفي

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: HYUNDAI/H1
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 19 SEP 2024 11:50:46	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN PASSENGER
Token Number	: 9	Un laden Weight	: 2000
Transaction Number	: 34622924	Laden Weight	: 2800
Reference import Doc.	: 962896 DSC	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 12
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: KMJWA37R0JU962896	Odometers	: 196329

Defect	Result	Remarks	Test Value
Side Safety Frame		BULK HEAD ASSEMBLY,FENDER FRAMES,APRON,SHOCK TOWER,FIREWAL JOINT AREA REPAIRED.	الواقبات الجانبية
General Items			الاشياء العامة
Engine Condition, Smoke		ENGINE AND GEAR REPAIRED.	حالة المحرك - الدخان
Auction			الفحص الكامل
Engine Oil Leaking		ENGINE OIL LEAKING	تهریب زيت المحرك
Gear Box Oil Leaking		GEAR BOX OIL LEAKING	تهریب زيت الجير
Body Repainted		ENGINE HOOD,FENDERS,DOORS,REAR CABIN,TAIL DOOR REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice						
Payment Method	: CREDIT	Transaction Number : 34622924				
Credit Customer Name	: 971 : AL WATANEYA AUCTION-756					
Customer Tax Registration No.	: TO BE UPDATED					
Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00
ENOC TAX Registration No.	: 100221692500003					
Processed By	: Inaam UI Haq Mohammed Sharif					

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها