

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2017
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/CAMRY
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 04 APR 2024 12:06:28	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 6	Un laden Weight	: 1450
Transaction Number	: 33978260	Laden Weight	: 1850
Reference import Doc.	: 84391 DSC	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: 6T1BF9FK7HX684391	Odometers	: 563286

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.540	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 189.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Ties Rods, Bushes, Center Link, Left And Right		SUSPENSION BUSHING CRACKED		ربلات ذراع التوجيه
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		ALL TYRE 2021-2022, WORN OUT, CRACKED		الاطارات الامامية
Body				الهيكل
Rusty		BODY PARTLY RUSTY DAMAGED.		الصدأ
Rusty		UNDER BODY PARTS RUSTED		الصدأ
Doors		RHS B,C DOOR PILLAR REPAIRED		الابواب
Bumpers		BUMPER FRAME REPAIRED, REFEXED-MISALIGNED		الدعامية
Floor		REAR COMPARTMENT, QUARTER PANELS REPAIRED. SPARE WHEELHOUSE COMPLETE RUSTY (HOLE) DAMAGED. FLOOR IMPACT		الارضية

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2017
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/CAMRY
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 04 APR 2024 12:06:28	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 6	Un laden Weight	: 1450
Transaction Number	: 33978260	Laden Weight	: 1850
Reference import Doc.	: 84391 DSC	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: 6T1BF9FK7HX684391	Odometers	: 563286

Defect	Result	Remarks	Test Value
Chassis (Frame)		BENT.JOINT DETACHED. REAR BOTH SIDE MEMBER EXTENSION REPAIRED-IMPACT BENT.	الشاصية
Side Safety Frame		BULKHEAD ASSEMBLY REPAIRED STILL DENT.	الواقيات الجانبية
Auction			الفحص الكامل
Steering Oil Leaking		STEERING OIL LEAKING	تهريب زيت صندوق عجلة القيادة
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير
Engine Oil Leaking		ENGINE OIL LEAKING	تهريب زيت المحرك
Body Repainted		BODY REPAINTED	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها