

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2017
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/YARIS
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 24 SEP 2024 11:46:44	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 8	Un laden Weight	: 1400
Transaction Number	: 34641282	Laden Weight	: 1800
Reference import Doc.	: 1022239 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MR2B29F31H1022239	Odometers	: 346622

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.260	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 249.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Ties Rods, Bushes, Center Link, Left And Right		SUSPENSION BUSHES CRACKED.		ربلات ذراع التوجيه
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2022, WORN OUT.		الاطارات الامامية
Rear Left And Right Hand Tires		DOT 2023, WORN OUT.		الاطارات الخلفية
Body				الهيكل
Rusty		UNDERNEATH AND SUSPENSION PARTS RUSTY		الصدأ
Paint		MINOR SCRATCHES		الصبغ
Fenders		LHS QUARTER PANEL, ROOF RAIL DENT.		المدكار
Bumpers		BUMPER FRAMES REPAIRED, DENT, BOTH BUMPER CRACKED.		الدعامية
Floor		UNDERNEATH RUST PROOF COATED		الارضية

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2017
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/YARIS
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 24 SEP 2024 11:46:44	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 8	Un laden Weight	: 1400
Transaction Number	: 34641282	Laden Weight	: 1800
Reference import Doc.	: 1022239 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MR2B29F31H1022239	Odometers	: 346622

Defect	Result	Remarks	Test Value
Floor		BACK PANEL,RHS QUARTER PANEL,WHEELHOUSE REPAIRED,RUNNING BOARD FLOOR DENT.	الارضية
Chassis (Frame)		FRONT RHS FRAME MEMBER DENT.	الشاصية
Side Safety Frame		BULK HEAD ASSEMBLY FENDER FRAME REPAIRED STILL DENT.	الواقيات الجانبية
General Items			الاشياء العامة
Engine Condition, Smoke		SIGN OF PARTS REFIXED, KNOCKING SOUND.	حالة المحرك - الدخان
Auction			الفحص الكامل
Engine Oil Leaking		ENGINE OIL LEAKING	تهريب زيت المحرك
Gear Box Oil Leaking		GEAR BOX OIL LEAKING	تهريب زيت الجير
Gear Ok		GEAR OK	الجير جيد
Body Repainted		RHS DOORS,QUARTER PANEL AND ROOF RAIL PORTION REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34641282
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : Inaam UI Haq Mohammed Sharif

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها