

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: CHEVROLET/CORVETE
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 29 OCT 2024 12:54:46	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: RED-BLACK - RED-BLACK
Test Count	:	Vehicle Category	: COUPE
Token Number	: 4	Un laden Weight	: 1500
Transaction Number	: 34787508	Laden Weight	: 1900
Reference import Doc.	: 02116 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 2
Plate Number	:	Number of Seats	: 2
Plate Category	:	Number of Cylinders	: 8
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	:
Chassis Number	: 1G1Y92D79K5102116	Odometers	: 92842

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		ALL TYRES DOT.22	الاطارات الامامية
Body			الهيكل
Doors		HOOD NOT OPENING & NOT CHECKED ENGINE ROOM (SIGN OF FRONT ACCEDENT)	الابواب
Bumpers		BOTH SIDE BUMPERS REFITTED,PAINTED & FRT MINOR PAINT PEEL OFF	الدعامية
Bumpers		FRONT BUMPER FRAME REPAIRED	الدعامية
Floor		LHS ROCKER PANEL SKIRT CRACK.	الارضية
Floor		UNDERNEATH COVEREDED	الارضية
General Items			الاشياء العامة
Engine Condition, Smoke		SIGN OF PARTS REFITTED & MINOR OIL STAINS.	حالة المحرك - الدخان
Remarks			ملاحظات
Others		PAINT TEST NOT DONE.	ملاحظات اخرى
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34787508
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها