



TEST CERTIFICATE

Site Number 840-Emirates Auctions Transaction Date 11 Sep 2024, 14:13:07
Transaction Number 88493120 (CC10010) (CC10010) Queue Number 1054569



Chassis Number JTGJX02P6C0041380
Engine Number
Vehicle Class Car
Manufacturer Toyota
Model Hiace
Model Year 2012
Color White
Mileage 125022 Km
Fuel Type Petrol
No. Of Cylinders 4
Specification GCC Specification

DEFECT

REMARKS

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED ,PORTION REPAIRED .MINOR DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY .	الصبغ
01.B Rusty	UNDER BODY SUSPE NSION PARTS GETTING RUSTY .	صدأ
01.C Floor	PORTION DENT .	الارضية
01.D Bumper	MISALIGN ,SCRATCHES .	دعامية
01.E Fuel Tank	DAMAGE	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY /OK.	الشاسيه
--------------	----------------------------	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED . MINOR OIL LEAK .	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION LOOSE ,DIRTY .	حالة المقاعد
---------------------	------------------------	--------------

05 Transmission Condition

الجير

DEFECT	REMARKS	
05.A Gear Box Visual Condition	NOT CHECKED .	الحالة النظرية للجير
05.B Gear Box Mount	BUSHES CRACKED .	كرسي الجير
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE BROKEN	الانارة
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY .	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
09.B Leaf Spring	BUSHES CRACKED .	
09.C Arms	BUSHES CRACKED .	ازرع
09.D Stabilizer Bar And Link Rod	BUSHES CRACKED .	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR CONDITION DIRTY .	اخرى
10.B AC Condition	NOT CHECKED .	المكيف
10.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.D Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.
- For complaints and inquiries reach out to us on wecare@carscheck.ae



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.
- لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae