



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	10 Mar 2023, 16:59:52
Transaction Number	90514165 (CC10010)	Queue Number	686647



Chassis Number	MALAN51C2GM612941
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	i10
Model Year	2016
Color	Blue
Mileage	124921 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Interior Condition</b>		الحاله الداخليه
01.A AC Condition	NOT CHECKED	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C Sun Visor	RIGHT SIDE LOOSE	حاجب الشمس
<b>02 Transmission Condition</b>		الجير
02.A Road Test	NOT CHECKED	فحص علي الطريق
02.B Visual Gear Box Condition	NOT CHECKED,SIGN OF OIL LEAK.	حالة الجير النظري
<b>03 Tires and Rims Condition</b>		الاطارات
03.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED,DAMAGED	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED,DAMAGED	الاطار الامامي
<b>04 Engine Condition</b>		المحرك
04.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,OIL LEAK ,AIR FILTER INTAKE HOSE DAMAGE.	حالة المحرك النظري
<b>05 Lights</b>		الاضاءة
05.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECK	الاضاءة الرئيسية

DEFECT	REMARKS	
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY	الصبغ
06.B Bumper	MISALIGN PORTION DAMAGED	دعامية
06.C Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
06.D Floor	PORTION DENT .	الارضية
06.E Roof	PORTION RUSTY	السقف
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.