

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2013
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HILUX
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 04 NOV 2024 13:17:07	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: PICKUP
Token Number	: 8	Un laden Weight	: 2000
Transaction Number	: 34811282	Laden Weight	: 2400
Reference import Doc.	: 099395 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 2
Plate Number	:	Number of Seats	: 3
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: MIL	GCC	: YES
Chassis Number	: MR0CX12G3D0099395	Odometers	: 168198

Statement of Vehicle Condition.
حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		DOT.2020	الاطارات الامامية
Rear Left And Right Hand Tires		DOT.2020	الاطارات الخلفية
Body			الهيكال
Rusty		CHASSIS FRAME,UNDERNEATH RUSTY. DO PREVENTIVE MAINTENANCE	الصدأ
Fenders		RIGHT SIDE FENDER FRAME AND APRON REPAIRED	المدكار
Side Safety Frame		BULK HEAD AND RADIATOR FRAME REPAIRED	الواقيات الجانبية
Remarks			ملاحظات
Others		ROAD TEST NOT DONE DUE TO TYRE PUNCTURE.	ملاحظات اخرى
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Body Repainted		RHS DOORS,REAR B/S QUARTER PANELS,FRT RHS FENDER REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34811282
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها