

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: LEXUS/ES 350
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 04 NOV 2024 10:17:58	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: BLACK - BLACK
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 3	Un laden Weight	: 1500
Transaction Number	: 34809865	Laden Weight	: 1900
Reference import Doc.	: 011898 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL + ELECTRIC POWER
Engine Number	: NIL	GCC	: YES
Chassis Number	: JTHB21B11K2011898	Odometers	: 286437

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		BOTH SIDE DOT.2020 & WORN OUT	الاطارات الامامية
Rear Left And Right Hand Tires		BOTH SIDE DOT.2020 & WORN OUT	الاطارات الخلفية
Rims		REAR LHS DISC DENT.	الرنجات
Body			الهيكل
Bumpers		FRT BUMPER MIS ALIGN & GRILL CRACKED.	الدعامية
Bumpers		REAR LHS CRASH BOX & FRAME END DENT.	الدعامية
Floor		REAR LHS QUARTER PANEL,COMP/PANEL DENT	الارضية
Remarks			ملاحظات
Others		ROAD TEST NOT DONE DUE TO TYRE PUNCTURE.	ملاحظات اخرى
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34809865
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها