



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **12 Sep 2024, 16:46:39**
 Transaction Number **64111499 (CC10010) (CC10019)** Queue Number **1054988**



Chassis Number **1GKS27KJ4FR255387**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **GMC**
 Model **Yukon**
 Model Year **2015**
 Color **White**
 Mileage **144512 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
01.D Floor	PORTION DENT .	الارضية
01.E Bumper	SCRATCHES ,MINOR MISALIGN .	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETE RUSTY,PORTION MINOR DENT	الشاسيه
02.B Chassis Number	VIN NUMBER AREA RUSTY NOT VISIBLE PROPERLY .	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHEKCKED ,PARTS REFITTED , MINOR OIL LEAK .	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED MINOR OIL LEAK .	الحالة النظرية للجير

DEFECT	REMARKS	
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021.GETTING CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021,GETTING CRACKED .	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	WEAK,	ممتص الصدمات
07.B Arms	BUSHES CRACKED	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
07.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Steering Condition		المقود
08.A Axle	BOOT CUT	اكسلات
09 Interior Condition		الحالة الداخليه
09.A Other	ALL SYSTEM NOT CHECKED .	اخرى
09.B AC Condition	NOT CHECKED	المكيف
09.C Door Panel	PORTION LOOSE .	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.
- For complaints and inquiries reach out to us on wecare@carscheck.ae



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.
- للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae