

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: NISSAN/MICRA
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 06 NOV 2024 10:04:10	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: HATCHBACK
Token Number	: 6	Un laden Weight	: 1000
Transaction Number	: 34820999	Laden Weight	: 1400
Reference import Doc.	: 001129 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MDHAK3CR3KG001129	Odometers	: 258625

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Steering And Suspension System			عجلة القيادة ونظام التوصيلات
Shock Absorbers		REAR LHS SHOCK LEAKE.	مخمد الصدمات
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		ALL TYRES DOT.2022 & NEED ALIGNMENT.	الاطارات الامامية
Body			الهيكل
Fenders		FRT FENDERS REPAIRED	المدكار
General Items			الاشياء العامة
Engine Condition, Smoke		INLET MANIFOLD HOSE CRACK..	حالة المحرك - الدخان
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير
Body Repainted		FRT B/S FENDERS,HOOD,RHS DOORS,REAR RHS QUARTER PANEL REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34820999
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها