

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: NISSAN/SUNNY
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 06 NOV 2024 10:19:30	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 7	Un laden Weight	: 1000
Transaction Number	: 34821097	Laden Weight	: 1400
Reference import Doc.	: 82363 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: HR15793619G	GCC	: YES
Chassis Number	: MDHBN7AD4KG682363	Odometers	: 205808

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		HC 188.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		CO 0.320	فحص الغاز العادم-الكربون
VISUAL TEST:				
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		ALL TYRES DOT.2023		الاطارات الامامية
Body				الهيكل
Fenders		REAR B/S QUARTER PANEL REPAIRED		المنكار
Floor		BACK PANEL,QUARTER PANELS REPAIRED		الارضية
Auction				الفحص الكامل
Chassis Ok		CHASSIS OK		الشاسي جيد
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK		فحص حالة الماكينة والجير
Body Repainted		REAR BOTH SIDE QUARTER PANEL,TRUNK LID & ENGINE HOOD REPAINTED.		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34821097
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها