

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2020
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/AVANZA
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 05 NOV 2024 12:32:20	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: STATION
Token Number	: 5	Un laden Weight	: 1800
Transaction Number	: 34816798	Laden Weight	: 2200
Reference import Doc.	: 010525 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 7
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MHKMF5CF2LK010525	Odometers	: 121433

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		ALL SIDE TYRES DOT.2024	الاطارات الامامية
Body			الهيكل
Bumpers		FRT BUMPER MIS ALIGNED	الدعامية
General Items			الاشياء العامة
Transmission Condition		MINOR LEAKE,OIL STAINS	حالة ناقل الحركة
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير
Engine Oil Leaking		MINOR LEAKE FROM DRAIN NUT.	تهریب زيت المحرك
Sign Of Rear Accident		REAR RHS QUARTER PANEL REPAIRED	آثر حادث في مؤخرة المركبة
Body Repainted		REAR RHS QUARTER PANEL PAINTED.	آثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34816798
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها