

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2017
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/CAMRY
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 05 NOV 2024 13:12:55	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 7	Un laden Weight	: 1400
Transaction Number	: 34817111	Laden Weight	: 1800
Reference import Doc.	: 92267 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: 6T1BF9FK2HX692267	Odometers	: 301678

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 11.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Suspension Crack Or Bend, Bushes		FRT LOWER ARM BUSH CRACK.		التوصيلات
Brake System				نظام الفرامل
Hand Brake Cable And Bracket		LHS IMB:94%		فرامل اليد
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		ALL TYRES DOT.2023		الاطارات الامامية
Body				الهيكل
Doors		TRUNK LID REPAIRED & MIS ALIGNED		الابواب
Fenders		REAR B/S QUARTER PANEL REPAIRED.		المنكار
Bumpers		BOTH SIDE BUMPERS MIS ALIGNED.		الدعامية
Bumpers		BOTH SIDE REPAIRED & MIS ALIGNED.		الدعامية
Floor		REAR COMPARTMENT PANEL, FLOOR, QUARTER PANEL REPAIRED		الارضية

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2017
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/CAMRY
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 05 NOV 2024 13:12:55	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 7	Un laden Weight	: 1400
Transaction Number	: 34817111	Laden Weight	: 1800
Reference import Doc.	: 92267 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: 6T1BF9FK2HX692267	Odometers	: 301678

Defect	Result	Remarks	Test Value
Chassis (Frame)		FRT LHS CHASSIS END DENT,JOINT OPEN & CROSS MEMBER BENT.	الشاصية
Side Safety Frame		BULK HEAD,RAD FRAME DENT.	الواقبات الجانبية
General Items			الاشياء العامة
Seats Condition And Seats Fixing		FRT LHS SEAT MIS ALIGN.	المقاعد وحالتها وتثبيتها
Engine Condition, Smoke		MINOR LEAKE,STAINS FROM VALVE COVER.	حالة المحرك - الدخان
Auction			الفحص الكامل
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير
Body Repainted		FRT BOTH SIDE FENDERS,HOOD,LHS BOTH DOORS,RHS FRT DOOR & REAR BOTH SIDE QUARTER PANEL,TRUNK LID REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34817111
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها