

| | | | |
|-----------------------|--------------------------------|---------------------|--------------------------------|
| Legal Entity Name | : ENOC TASJEEL L.L.C | Vehicle Year Model | : 2015 |
| Site Location | : 677-AL WATANEYA | Vehicle Make/Model | : TOYOTA/INOVA |
| Tester ID(1) | : 33794 - HARIZE VENNEER KUZHI | Tester ID(2) | : 33794 - HARIZE VENNEER KUZHI |
| Test Date And Time | : 26 NOV 2024 10:08:46 | Vehicle Type | : LIGHT VEHICLE |
| Test Type | : DSC AUCTION | Vehicle Color | : WHITE - WHITE |
| Test Count | : | Vehicle Category | : STATION |
| Token Number | : 6 | Un laden Weight | : 2000 |
| Transaction Number | : 34899453 | Laden Weight | : 2400 |
| Reference import Doc. | : 33392 AWA | Number of Axles | : 2 |
| Plate Location Place | : SHJ | Number of Doors | : 4 |
| Plate Number | : | Number of Seats | : 7 |
| Plate Category | : | Number of Cylinders | : 4 |
| Plate Code | : | Fuel Type | : PETROL |
| Engine Number | : NIL | GCC | : YES |
| Chassis Number | : MHFXX42G3F5033392 | Odometers | : 343372 |

Statement of Vehicle Condition.

حالة المركبة

| Defect | Result | Remarks | Test Value |
|------------------------------------|--------|-------------------------------------------|--------------------------|
| VISUAL TEST: | | | |
| Lights | | | الانوار |
| Head Lights | | COVER FADED. | الانوار الامامية |
| Tires Rims | | | الاطارات والعجلات |
| Front Left And Right Hands Tires | | DOT.2023 & WORN OUT.NEED WHEEL ALIGNMENT. | الاطارات الامامية |
| Rear Left And Right Hand Tires | | DOT.2023 & 2021 | الاطارات الخلفية |
| Body | | | الهيكل |
| Doors | | HOOD EDGE LINER DAMAGE. | الابواب |
| Bumpers | | MISALIGNED | الدعامية |
| Bumpers | | FRONT BUMPER FRAME BENT. | الدعامية |
| General Items | | | الاشياء العامة |
| Wiper Blades | | DEFECTIVE WIPER MOTOR | ماسحات الزجاج الامامي |
| Auction | | | الفحص الكامل |
| Chassis Ok | | CHASSIS OK | الشاصي جيد |
| Engine And Gear Box Performance Ok | | ENGINE AND GEAR BOX PERFORMANCE OK | فحص حالة الماكينة والجير |
| Body Repainted | | REAR LHS QUARTER PANEL REPAINTED. | أثر صبغ في المركبة |

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34899453
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

| Description | Unit Rate | Quantity | Rate% | Amount | VAT | Total Amount |
|-----------------------|-----------|----------|-------|--------|-------|--------------|
| DISCOUNT AUCTION TEST | 200.00 | 1 | | 200.00 | 10.00 | 210.00 |
| Total : | | | | 200.00 | 10.00 | 210.00 |

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها