

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/CAMRY
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 26 NOV 2024 10:01:43	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: YELLOW-GREEN - YELLOW-GREEN
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 5	Un laden Weight	: 1400
Transaction Number	: 34899404	Laden Weight	: 1800
Reference import Doc.	: 05875 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: JTNBF9HK2J3005875	Odometers	: 325390

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		DOT.2023	الاطارات الامامية
Rear Left And Right Hand Tires		DOT.2023, RHS PUNCTURE	الاطارات الخلفية
General Items			الاشياء العامة
Seats Condition And Seats Fixing		DASH BOARD DAMAGE/COVER MISSING.	المقاعد وحالتها وثبيتها
Engine Condition, Smoke		SIGN OF REPAIRS OR PARTS REFITTED	حالة المحرك - الدخان
Remarks			ملاحظات
Others		ROAD TEST NOT DONE DUE TO TIRE PUNCTURE.	ملاحظات اخرى
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
A/C Not Cooling		A/C NOT COOLING	عطل في المكيف
Body Repainted		BODY REPAINTED	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34899404
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها