

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2016
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HI ACE
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 09 NOV 2024 09:50:14	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN PASSENGER
Token Number	: 6	Un laden Weight	: 2000
Transaction Number	: 34833144	Laden Weight	: 2400
Reference import Doc.	: 69441 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 15
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: JTGSX23P2G6169441	Odometers	: 789415

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.010	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 12.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Steering Ball Joints, Boots		BOOT CRACK,LEAKE.		وصلات عمود عجلة القيادة
Shock Absorbers		FRONT BOTH SIDE & REAR RHS SHOCKS LEAKE.		مخمد الصدمات
Gear Box Mounting		GEAR MOUNT CRACKED.		كراسي ناقل الحركة
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT.2024 & WORN OUT.NEED ALIGNMENT.		الاطارات الامامية
Rear Left And Right Hand Tires		DOT.2023		الاطارات الخلفية
Body				الهيكل
Paint		BODY DENTS & REAR LHS Q PANEL CRACK.		الصبغ
Floor		REAR COMPARTMENT PANEL, FLOOR, QUARTER PANEL REPAIRED		الارضية
General Items				الاشياء العامة

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2016
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HI ACE
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 09 NOV 2024 09:50:14	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN PASSENGER
Token Number	: 6	Un laden Weight	: 2000
Transaction Number	: 34833144	Laden Weight	: 2400
Reference import Doc.	: 69441 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 15
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: JTGSX23P2G6169441	Odometers	: 789415

Defect	Result	Remarks	Test Value
Engine Condition, Smoke		SIGN OF REPAIRS & SIGN OF PARTS REFITTED.	حالة المحرك - الدخان
Auction			الفحص الكامل
Steering Oil Leaking		STEERING OIL LEAKE FROM RESOURVIOR.	تهريب زيت صندوق عجلة القيادة
Chassis Ok		CHASSIS OK	الشاصي جيد
Engine Oil Leaking		ENGINE OIL LEAKING	تهريب زيت المحرك
Body Repainted		REAR BOTH SIDE CABIN,REAR RHS DOOR,TAIL DOOR REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method	:	CREDIT	Transaction Number : 34833144			
Credit Customer Name	:	971 : AL WATANEYA AUCTION-756				
Customer Tax Registration No.	:	TO BE UPDATED				
Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00
ENOC TAX Registration No.	:	100221692500003				
Processed By	:	HARIZE VENNEER KUZHI				

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها