

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2016
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HI ACE
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 13 NOV 2024 08:11:04	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN CARGO
Token Number	: 1	Un laden Weight	: 2000
Transaction Number	: 34848427	Laden Weight	: 2400
Reference import Doc.	: 09872 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 3
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: JTFHX02P5G0109872	Odometers	: 64100

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Brake System			نظام الفرامل
Brake Pedal		LIGHT HARD.	دواسة الفرامل
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		DOT.2021	الاطارات الامامية
Rear Left And Right Hand Tires		DOT.2021	الاطارات الخلفية
Body			الهيكل
Rusty		UNDER BODY MINOR RUSTY.	الصدأ
Paint		BODY DENTS,SCRATCHES & TAIL DOOR DENT.	الصبغ
General Items			الاشياء العامة
Co & Hc A.Normal B.Low C.High			الغاز العادم والكربون
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34848427
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها