

|                       |                                |                     |                                |
|-----------------------|--------------------------------|---------------------|--------------------------------|
| Legal Entity Name     | : ENOC TASJEEL L.L.C           | Vehicle Year Model  | : 2019                         |
| Site Location         | : 677-AL WATANEYA              | Vehicle Make/Model  | : NISSAN/SUNNY                 |
| Tester ID(1)          | : 33794 - HARIZE VENNEER KUZHI | Tester ID(2)        | : 33794 - HARIZE VENNEER KUZHI |
| Test Date And Time    | : 07 NOV 2024 14:32:26         | Vehicle Type        | : LIGHT VEHICLE                |
| Test Type             | : DSC AUCTION                  | Vehicle Color       | : WHITE - WHITE                |
| Test Count            | :                              | Vehicle Category    | : HATCHBACK                    |
| Token Number          | : 8                            | Un laden Weight     | : 1000                         |
| Transaction Number    | : 34827570                     | Laden Weight        | : 1400                         |
| Reference import Doc. | : 001479 AWA                   | Number of Axles     | : 2                            |
| Plate Location Place  | : SHJ                          | Number of Doors     | : 4                            |
| Plate Number          | :                              | Number of Seats     | : 5                            |
| Plate Category        | :                              | Number of Cylinders | : 4                            |
| Plate Code            | :                              | Fuel Type           | : PETROL                       |
| Engine Number         | : NIL                          | GCC                 | : YES                          |
| Chassis Number        | : MDHAK3CR8KG001479            | Odometers           | : 210924                       |

### Statement of Vehicle Condition.

حالة المركبة

| Defect                             | Result | Remarks                                       | Test Value |                          |
|------------------------------------|--------|-----------------------------------------------|------------|--------------------------|
| AUTOMATIC TEST:                    |        |                                               |            |                          |
| Brake System                       |        |                                               |            | الفرامل                  |
| Brake Test                         | Passed |                                               |            | فحص الفرامل              |
| Exhaust Gas Test                   |        |                                               |            | الغاز العادم والكربون    |
| Exhaust Gas Test                   | Passed |                                               | HC 1.000   | فحص الغاز العادم-الكربون |
| Exhaust Gas Test                   | Passed |                                               | CO 0.070   | فحص الغاز العادم-الكربون |
| VISUAL TEST:                       |        |                                               |            |                          |
| Tires Rims                         |        |                                               |            | الاطارات والعجلات        |
| Rear Left And Right Hand Tires     |        | BOTH SIDE DOT.2021,DRY CRACK.                 |            | الاطارات الخلفية         |
| Body                               |        |                                               |            | الهيكل                   |
| Rusty                              |        | LHS DOT.2021,WORN OUT & RHS 2018.             |            | الصدأ                    |
| Fenders                            |        | FRT LHS FENDER DENT.                          |            | المنكار                  |
| Auction                            |        |                                               |            | الفحص الكامل             |
| Chassis Ok                         |        | CHASSIS OK                                    |            | الشاسي جيد               |
| Engine And Gear Box Performance Ok |        | ENGINE AND GEAR BOX PERFORMANCE OK            |            | فحص حالة الماكينة والجير |
| Body Repainted                     |        | FRONT BOTH SIDE FENDERS,ENGINE HOOD REPAINTED |            | أثر صبغ في المركبة       |

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34827570  
Credit Customer Name : 971 : AL WATANEYA AUCTION-756  
Customer Tax Registration No. : TO BE UPDATED

| Description           | Unit Rate | Quantity | Rate% | Amount | VAT   | Total Amount |
|-----------------------|-----------|----------|-------|--------|-------|--------------|
| DISCOUNT AUCTION TEST | 200.00    | 1        |       | 200.00 | 10.00 | 210.00       |
| Total :               |           |          |       | 200.00 | 10.00 | 210.00       |

ENOC TAX Registration No. : 100221692500003  
Processed By : HARIZE VENNEER KUZHI

\* Change(s) observed while testing.

\* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

\* أي كشط أو تغيير على الشهادة يلغيها