



REPRINT Page 1 of 2

: STATION

Legal Entitity Name : ENOC TASJEEL L.L.C Vehicle Year Model : 2016

Site Location : 677-AL WATANEYA Vehicle Make/Model : MERCEDES/GLE 63

Tester ID(1) : 33794 - HARIZE VENNEER KUZHI Tester ID(2) : 33794 - HARIZE VENNEER KUZHI

Vehicle Category

Test Count :

Token Number : 5 Un laden Weight : 1800

Transaction Number : 34791699 Laden Weight : 2200

Reference import Doc. : 011568 AWA Number of Axles : 2

Plate Location Place: SHJNumber of Doors: 4Plate Number: 5

Plate Category : Number of Cylinders : 8

Plate Code : Fuel Type : PETROL

Engine Number : NIL GCC : YES

Chassis Number : WDCED7FB5GA011568 Odometers : 110185

## Statement of Vehicle Condition.

حالة المركبة

أر صبغ في المركبة

Defect	Result	Remarks	Test Value	
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Shock Absorbers		AIR SUSPUNSION MAL	FUNCTION	مخمد الصدمات
Body				الهيكل
Doors		RHS DOORS,FENDERS	S REPAIRED.	الابواب
Floor		REAR RHS QUARTER I HOUSE REPAIRED.	PANEL,WHEEL	الارضية
General Items				الاشياء العامة
Engine Condition, Smoke		ENGINE OIL LEAKING	& COOLENT	حالة المحرك - الدخان
Remarks				ملاحظات
Others		ROAD TEST NOT DONI PUNCTURE.	E.DUE TO TYRE	ملاحظات اخرى
Auction				الفحص الكامل
Chassis Ok		CHASSIS OK		الشاصي جيد

SIGN OF RHS ACCEDENT.

FRT RHS FENDER,RHS DOORS & REAR RHS QUARTER PANEL REPAIRED &

REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

Sign Of Side Accident

**Body Repainted** 





REPRINT Page 2 of 2

Reprint on: 01-NOV-2024 Reprinted by: MOHDS

\* Change(s) observed while testing.

 $\ensuremath{^{\star}}$  Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

\* أي كشط أو تغيير على الشهادة يلغيها