

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: NISSAN/X TRAIL
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 19 NOV 2024 11:19:59	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: STATION
Token Number	: 7	Un laden Weight	: 1800
Transaction Number	: 34872534	Laden Weight	: 2200
Reference import Doc.	: 11671 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: JN1BT2MU9JW011671	Odometers	: 200235

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Steering And Suspension System			عجلة القيادة ونظام التوصيلات
Engine Mounting		SIGN OF MOUNTING REFITTED.	كراسي المحرك
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		DOT.2020	الاطارات الامامية
Rear Left And Right Hand Tires		DOT.2020	الاطارات الخلفية
Body			الهيكل
Fenders		FRONT FENDER FRAME REPAIRED	المدكار
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير
Body Repainted		FRONT BOTH SIDE FENDERS,HOOD,LHS DOORS,REAR RHS QUARTER PANEL REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 34872534
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها