

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/YARIS
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 20 NOV 2024 10:18:40	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: HATCHBACK
Token Number	: 6	Un laden Weight	: 1000
Transaction Number	: 34877028	Laden Weight	: 1400
Reference import Doc.	: 37411 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MR2K19F36J1037411	Odometers	: 168550

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		HC 113.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		CO 0.020	فحص الغاز العادم-الكربون
VISUAL TEST:				
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT.2024		الاطارات الامامية
Rear Left And Right Hand Tires		DOT.2022		الاطارات الخلفية
Body				الهيكل
Paint		MINOR BODY DENTS & SCRATCHES		الصبغ
Doors		HOOD REPAIRED,FENDER,BUMPER REFITTED		الابواب
Fenders		FRONT FENDER FRAME REPAIRED		المدكار
Fenders		FRONT RHS FENDER LOWER DENT.		المدكار
Bumpers		FRONT BUMPER/FRAME REPAIRED & MISALIGNED.		الدعامية
Chassis (Frame)		FRONT RHS CHASSIS END REPAIRED.		الشاصية
Front And Rear Windshields		FRONT REPLACED		الزجاج الامامي والخلفي
Side Safety Frame		BULK HEAD AND RADIATOR FRAME REPAIRED		الواقيات الجانبية

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/YARIS
Tester ID(1)	: 33794 - HARIZE VENNEER KUZHI	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 20 NOV 2024 10:18:40	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: HATCHBACK
Token Number	: 6	Un laden Weight	: 1000
Transaction Number	: 34877028	Laden Weight	: 1400
Reference import Doc.	: 37411 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MR2K19F36J1037411	Odometers	: 168550

Defect	Result	Remarks	Test Value
Auction			الفحص الكامل
Engine And Gear Box Performance Ok		ENGINE AND GEAR BOX PERFORMANCE OK	فحص حالة الماكينة والجير
Gear Box Oil Leaking		GEAR BOX OIL LEAKING	تهريب زيت الجير
A/C Not Cooling		A/C NOT COOLING	عطل في المكيف
Body Repainted		FRONT RHS FENDER & HOOD REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method	:	CREDIT	Transaction Number : 34877028			
Credit Customer Name	:	971 : AL WATANEYA AUCTION-756				
Customer Tax Registration No.	:	TO BE UPDATED				
Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00
ENOC TAX Registration No.	:	100221692500003				
Processed By	:	HARIZE VENNEER KUZHI				

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها