

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2016
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: MITSUBISHI/L200
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 24 DEC 2024 12:13:55	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: PICK UP
Token Number	: 2	Un laden Weight	: 2050
Transaction Number	: 35009716	Laden Weight	: 2700
Reference import Doc.	: 009454 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MMBJNKL40GH009454	Odometers	: 226404

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Failed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.100	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 96.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Lights				الانوار
Tail Lights		LHS LENS CRACKED.		الانوار الخلفية
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Steering Ball Joints, Boots		STEERING BOOTS CRACKED.		وصلات عمود عجلة القيادة
Transmission Shaft, Flange Or Joint		4WD GEAR SIGN OF REPAIRS. OIL LEAK.		عمود التعشيق
Suspension Crack Or Bend, Bushes		SUSPENSION BUSHES CRACKED.		التوصيلات
Brake System				نظام الفرامل
Brake Efficiency Front Wheels Left And Right Hands		MORE THAN 30% IMBALANCE BETWEEN LHS AND		قوة فرامل المحور الامامي
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2022, CRACKS.		الاطارات الامامية
Rear Left And Right Hand Tires		DOT 2021, WORN OUT, CRACKED.		الاطارات الخلفية
Body				الهيكل

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2016
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: MITSUBISHI/L200
Tester ID(1)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF	Tester ID(2)	: 38024 - INAAM UL HAQ MUHAMMAD SHARIF
Test Date And Time	: 24 DEC 2024 12:13:55	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: PICK UP
Token Number	: 2	Un laden Weight	: 2050
Transaction Number	: 35009716	Laden Weight	: 2700
Reference import Doc.	: 009454 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4
Plate Code	:	Fuel Type	: PETROL
Engine Number	: NIL	GCC	: YES
Chassis Number	: MMBJNKL40GH009454	Odometers	: 226404

Defect	Result	Remarks	Test Value
Rusty		UNDERNEATH AND SUSPENSION PARTS RUSTY	الصدأ
Bumpers		FRONT FRAME REPAIRED, BUMPERS REFIXED,MISALIGNED.	الدعامية
Chassis (Frame)		FRONT CROSS MEMBER DENT.	الشاصية
General Items			الاشياء العامة
Engine Condition, Smoke		ENGINE AND GEAR SIGNS OF REPAIRED/PARTS REFIXED. UNUSUAL SOUND. ENGINE CHECK LIGHT ON.	حالة المحرك - الدخان
Auction			الفحص الكامل
Steering Oil Leaking		STEERING OIL LEAKING	تهريب زيت صندوق عجلة القيادة
Engine Oil Leaking		ENGINE OIL LEAKING	تهريب زيت المحرك
Gear Box Oil Leaking		GEAR BOX OIL LEAKING	تهريب زيت الجير
Body Repainted		ENGINE HOOD,FENDERS,LHS DOOR AND CARRIER BOTH SIDE REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 35009716
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : Inaam UI Haq Mohammed Sharif

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها