

|                       |                                        |                     |                                        |
|-----------------------|----------------------------------------|---------------------|----------------------------------------|
| Legal Entity Name     | : ENOC TASJEEL L.L.C                   | Vehicle Year Model  | : 2019                                 |
| Site Location         | : 677-AL WATANEYA                      | Vehicle Make/Model  | : NISSAN/KICKS                         |
| Tester ID(1)          | : 38024 - INAAM UL HAQ MUHAMMAD SHARIF | Tester ID(2)        | : 38024 - INAAM UL HAQ MUHAMMAD SHARIF |
| Test Date And Time    | : 05 DEC 2024 07:36:09                 | Vehicle Type        | : LIGHT VEHICLE                        |
| Test Type             | : DSC AUCTION                          | Vehicle Color       | : WHITE - WHITE                        |
| Test Count            | :                                      | Vehicle Category    | : STATION                              |
| Token Number          | : 1                                    | Un laden Weight     | : 1650                                 |
| Transaction Number    | : 34928726                             | Laden Weight        | : 2200                                 |
| Reference import Doc. | : 464619 AWA                           | Number of Axles     | : 2                                    |
| Plate Location Place  | : SHJ                                  | Number of Doors     | : 4                                    |
| Plate Number          | :                                      | Number of Seats     | : 5                                    |
| Plate Category        | :                                      | Number of Cylinders | : 4                                    |
| Plate Code            | :                                      | Fuel Type           | : PETROL                               |
| Engine Number         | : NIL                                  | GCC                 | : YES                                  |
| Chassis Number        | : 3N1CP5C95KL464619                    | Odometers           | : 417562                               |

### Statement of Vehicle Condition.

حالة المركبة

| Defect                           | Result | Remarks                                                    | Test Value |                              |
|----------------------------------|--------|------------------------------------------------------------|------------|------------------------------|
| AUTOMATIC TEST:                  |        |                                                            |            |                              |
| Brake System                     |        |                                                            |            | الفرامل                      |
| Brake Test                       | Passed |                                                            |            | فحص الفرامل                  |
| Exhaust Gas Test                 |        |                                                            |            | الغاز العادم والكربون        |
| Exhaust Gas Test                 | Passed |                                                            | HC 210.000 | فحص الغاز العادم-الكربون     |
| Exhaust Gas Test                 | Passed |                                                            | CO 0.460   | فحص الغاز العادم-الكربون     |
| VISUAL TEST:                     |        |                                                            |            |                              |
| Steering And Suspension System   |        |                                                            |            | عجلة القيادة ونظام التوصيلات |
| Stub Axle Assemblies, Boots      |        | FRONT AXLE BOOT LEAK                                       |            | المحور                       |
| Suspension Crack Or Bend, Bushes |        | SUSPENSION BUSHES CRACKED.                                 |            | التوصيلات                    |
| Brake System                     |        |                                                            |            | نظام الفرامل                 |
| Brake Pedal                      |        | LOW PEDAL, SPONGY                                          |            | دواسة الفرامل                |
| Tires Rims                       |        |                                                            |            | الاطارات والعجلات            |
| Front Left And Right Hands Tires |        | DOT 2023, WORN OUT.                                        |            | الاطارات الامامية            |
| Rear Left And Right Hand Tires   |        | DOT 2023, WORN OUT.                                        |            | الاطارات الخلفية             |
| Body                             |        |                                                            |            | الهيكل                       |
| Bumpers                          |        | BUMPERS MISALIGNED, FRAMES REPAIRED.                       |            | الدعامية                     |
| Floor                            |        | BACK PANEL,COMPARTMENT,QUARTER PANEL REPAIRED STILL DENTS. |            | الارضية                      |

|                       |                                        |                     |                                        |
|-----------------------|----------------------------------------|---------------------|----------------------------------------|
| Legal Entity Name     | : ENOC TASJEEL L.L.C                   | Vehicle Year Model  | : 2019                                 |
| Site Location         | : 677-AL WATANEYA                      | Vehicle Make/Model  | : NISSAN/KICKS                         |
| Tester ID(1)          | : 38024 - INAAM UL HAQ MUHAMMAD SHARIF | Tester ID(2)        | : 38024 - INAAM UL HAQ MUHAMMAD SHARIF |
| Test Date And Time    | : 05 DEC 2024 07:36:09                 | Vehicle Type        | : LIGHT VEHICLE                        |
| Test Type             | : DSC AUCTION                          | Vehicle Color       | : WHITE - WHITE                        |
| Test Count            | :                                      | Vehicle Category    | : STATION                              |
| Token Number          | : 1                                    | Un laden Weight     | : 1650                                 |
| Transaction Number    | : 34928726                             | Laden Weight        | : 2200                                 |
| Reference import Doc. | : 464619 AWA                           | Number of Axles     | : 2                                    |
| Plate Location Place  | : SHJ                                  | Number of Doors     | : 4                                    |
| Plate Number          | :                                      | Number of Seats     | : 5                                    |
| Plate Category        | :                                      | Number of Cylinders | : 4                                    |
| Plate Code            | :                                      | Fuel Type           | : PETROL                               |
| Engine Number         | : NIL                                  | GCC                 | : YES                                  |
| Chassis Number        | : 3N1CP5C95KL464619                    | Odometers           | : 417562                               |

| Defect                  | Result | Remarks                                                       | Test Value           |
|-------------------------|--------|---------------------------------------------------------------|----------------------|
| Chassis (Frame)         |        | REAR BOTH SIDE FRAME MEMBER END DENT.                         | الشاصية              |
| General Items           |        |                                                               | الاشياء العامة       |
| Engine Condition, Smoke |        | EMITTING WHITE SMOKE                                          | حالة المحرك - الدخان |
| Auction                 |        |                                                               | الفحص الكامل         |
| Engine Oil Leaking      |        | ENGINE OIL LEAKING                                            | تهريب زيت المحرك     |
| Gear Box Oil Leaking    |        | GEAR BOX OIL LEAKING                                          | تهريب زيت الجير      |
| Body Repainted          |        | ENGINE HOOD,FENDERS,DOORS,QUARTER PANELS,TAIL DOOR REPAINTED. | أثر صبغ في المركبة   |

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

#### TAX Invoice

|                               |           |                               |                               |        |       |              |
|-------------------------------|-----------|-------------------------------|-------------------------------|--------|-------|--------------|
| Payment Method                | :         | CREDIT                        | Transaction Number : 34928726 |        |       |              |
| Credit Customer Name          | :         | 971 : AL WATANEYA AUCTION-756 |                               |        |       |              |
| Customer Tax Registration No. | :         | TO BE UPDATED                 |                               |        |       |              |
| Description                   | Unit Rate | Quantity                      | Rate%                         | Amount | VAT   | Total Amount |
| DISCOUNT AUCTION TEST         | 200.00    | 1                             |                               | 200.00 | 10.00 | 210.00       |
| Total :                       |           |                               |                               | 200.00 | 10.00 | 210.00       |
| ENOC TAX Registration No.     | :         | 100221692500003               |                               |        |       |              |
| Processed By                  | :         | Inaam Ul Haq Mohammed Sharif  |                               |        |       |              |

\* Change(s) observed while testing.

\* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

\* أي كشط أو تغيير على الشهادة يلغيها