

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2016
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HI ACE
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 39152 - SAM THOMAS
Test Date And Time	: 26 FEB 2025 10:32:36	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN CARGO
Token Number	: 3	Un laden Weight	: 1500
Transaction Number	: 35264840	Laden Weight	: 2500
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 3
Plate Number	: 60466 AWA	Number of Seats	: 3
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: 0	GCC	: YES
Chassis Number	: JTFPX22P3F0060466	Odometers	: 0

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Brake System			نظام الفرامل
Brake Efficiency Rear Wheels Left And Right Hand		VEHICLE NOT STARTING CONDITION - BRAKE NOT INSPECTED.	قوة فرامل المحور الخلفي
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2024.	الاطارات الامامية
Rear Left And Right Hand Tires		DOT 2021.	الاطارات الخلفية
Body			الهيكل
Paint		MINOR BODY DENTS & SCRATCHES	الصبغ
General Items			الاشياء العامة
Engine Condition, Smoke		EMISSION NOT INSPECTED DUE TO CAR NOT STARTING CONDITION.	حالة المحرك - الدخان
Remarks			ملاحظات
Others		TEST DRIVE NOT DONE.	ملاحظات اخرى
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 35264840
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : Sam Thomas

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها