

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/AVANZA
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 39152 - SAM THOMAS
Test Date And Time	: 27 FEB 2025 12:51:15	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: STATION
Token Number	: 8	Un laden Weight	: 1200
Transaction Number	: 35271269	Laden Weight	: 2000
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	: 10107 AWA	Number of Seats	: 7
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: 2NR	GCC	: YES
Chassis Number	: MHKMF5CF6LK010107	Odometers	: 137194

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		CO 0.040	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		HC 1.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2024.		الاطارات الامامية
Body				الهيكل
Floor		UNDERNEATH RUST PROOF COATED		الارضية
General Items				الاشياء العامة
Transmission Condition		TRANSFER CASE OIL LEAK.		حالة ناقل الحركة
Remarks				ملاحظات
Others		TEST DRIVE NOT DONE.		ملاحظات اخرى
Auction				الفحص الكامل
Chassis Ok		CHASSIS OK		الشاسي جيد

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 35271269
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : Sam Thomas

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها