

|                       |                        |                     |                      |
|-----------------------|------------------------|---------------------|----------------------|
| Legal Entity Name     | : ENOC TASJEEL L.L.C   | Vehicle Year Model  | : 2019               |
| Site Location         | : 677-AL WATANEYA      | Vehicle Make/Model  | : HYUNDAI/ACCENT     |
| Tester ID(1)          | : 39152 - SAM THOMAS   | Tester ID(2)        | : 39152 - SAM THOMAS |
| Test Date And Time    | : 21 APR 2025 09:23:31 | Vehicle Type        | : LIGHT VEHICLE      |
| Test Type             | : DSC AUCTION          | Vehicle Color       | : WHITE - WHITE      |
| Test Count            | :                      | Vehicle Category    | : SEDAN              |
| Token Number          | : 6                    | Un laden Weight     | : 1200               |
| Transaction Number    | : 35452348             | Laden Weight        | : 2000               |
| Reference import Doc. | :                      | Number of Axles     | : 2                  |
| Plate Location Place  | : SHJ                  | Number of Doors     | : 4                  |
| Plate Number          | : 117270 AWA           | Number of Seats     | : 5                  |
| Plate Category        | : PRIVATE              | Number of Cylinders | : 4                  |
| Plate Code            | : 0                    | Fuel Type           | : PETROL             |
| Engine Number         | : G4FG                 | GCC                 | : NO                 |
| Chassis Number        | : MALC741C7KM117270    | Odometers           | : 139362             |

### Statement of Vehicle Condition.

### حالة المركبة

| Defect                                           | Result | Remarks                           | Test Value |                          |
|--------------------------------------------------|--------|-----------------------------------|------------|--------------------------|
| AUTOMATIC TEST:                                  |        |                                   |            |                          |
| Brake System                                     |        |                                   |            | الفرامل                  |
| Brake Test                                       | Passed |                                   |            | فحص الفرامل              |
| Exhaust Gas Test                                 |        |                                   |            | الغاز العادم والكربون    |
| Exhaust Gas Test                                 | Passed |                                   | HC 7.000   | فحص الغاز العادم-الكربون |
| Exhaust Gas Test                                 | Passed |                                   | CO 0.020   | فحص الغاز العادم-الكربون |
| VISUAL TEST:                                     |        |                                   |            |                          |
| Brake System                                     |        |                                   |            | نظام الفرامل             |
| Brake Efficiency Rear Wheels Left And Right Hand |        | NOT CHECKED DUE TO TYRE PUNCTURE. |            | قوة فرامل المحور الخلفي  |
| Tires Rims                                       |        |                                   |            | الاطارات والعجلات        |
| Front Left And Right Hands Tires                 |        | DOT 2021.                         |            | الاطارات الامامية        |
| Rear Left And Right Hand Tires                   |        | DOT 2021/2023.                    |            | الاطارات الخلفية         |
| Rear Left And Right Hand Tires                   |        | AIR LEAKING OR PUNCTURE           |            | الاطارات الخلفية         |
| Body                                             |        |                                   |            | الهيكل                   |
| Bumpers                                          |        | REFITTED.                         |            | الدعامية                 |
| Floor                                            |        | BACK PANEL,COMP/PANEL REPAIRED.   |            | الارضية                  |
| Floor                                            |        | UNDERNEATH RUST PROOF COATED      |            | الارضية                  |
| Remarks                                          |        |                                   |            | ملاحظات                  |
| Others                                           |        | TEST DRIVE NOT DONE.              |            | ملاحظات اخرى             |

|                       |                        |                     |                      |
|-----------------------|------------------------|---------------------|----------------------|
| Legal Entity Name     | : ENOC TASJEEL L.L.C   | Vehicle Year Model  | : 2019               |
| Site Location         | : 677-AL WATANEYA      | Vehicle Make/Model  | : HYUNDAI/ACCENT     |
| Tester ID(1)          | : 39152 - SAM THOMAS   | Tester ID(2)        | : 39152 - SAM THOMAS |
| Test Date And Time    | : 21 APR 2025 09:23:31 | Vehicle Type        | : LIGHT VEHICLE      |
| Test Type             | : DSC AUCTION          | Vehicle Color       | : WHITE - WHITE      |
| Test Count            | :                      | Vehicle Category    | : SEDAN              |
| Token Number          | : 6                    | Un laden Weight     | : 1200               |
| Transaction Number    | : 35452348             | Laden Weight        | : 2000               |
| Reference import Doc. | :                      | Number of Axles     | : 2                  |
| Plate Location Place  | : SHJ                  | Number of Doors     | : 4                  |
| Plate Number          | : 117270 AWA           | Number of Seats     | : 5                  |
| Plate Category        | : PRIVATE              | Number of Cylinders | : 4                  |
| Plate Code            | : 0                    | Fuel Type           | : PETROL             |
| Engine Number         | : G4FG                 | GCC                 | : NO                 |
| Chassis Number        | : MALC741C7KM117270    | Odometers           | : 139362             |

| Defect                | Result | Remarks                           | Test Value                |
|-----------------------|--------|-----------------------------------|---------------------------|
| Auction               |        |                                   | الفحص الكامل              |
| Chassis Ok            |        | CHASSIS OK                        | الشاسي جيد                |
| Sign Of Rear Accident |        | SIGN OF REAR ACCIDENT             | أثر حادث في مؤخرة المركبة |
| Body Repainted        |        | B/S QUATER PANEL,TRUNK REPAINTED. | أثر صبغ في المركبة        |

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

#### TAX Invoice

|                               |           |                               |                               |        |       |              |
|-------------------------------|-----------|-------------------------------|-------------------------------|--------|-------|--------------|
| Payment Method                | :         | CREDIT                        | Transaction Number : 35452348 |        |       |              |
| Credit Customer Name          | :         | 971 : AL WATANEYA AUCTION-756 |                               |        |       |              |
| Customer Tax Registration No. | :         | TO BE UPDATED                 |                               |        |       |              |
| Description                   | Unit Rate | Quantity                      | Rate%                         | Amount | VAT   | Total Amount |
| DISCOUNT AUCTION TEST         | 200.00    | 1                             |                               | 200.00 | 10.00 | 210.00       |
| Total :                       |           |                               |                               | 200.00 | 10.00 | 210.00       |
| ENOC TAX Registration No.     | :         | 100221692500003               |                               |        |       |              |
| Processed By                  | :         | Sam Thomas                    |                               |        |       |              |

\* Change(s) observed while testing.

\* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

\* أي كسح أو تغيير على الشهادة يلغيها