

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: NISSAN/SUNNY
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 39152 - SAM THOMAS
Test Date And Time	: 23 APR 2025 07:56:18	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 2	Un laden Weight	: 1200
Transaction Number	: 35461718	Laden Weight	: 2000
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	: 55029 AWA	Number of Seats	: 5
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: HR15	GCC	: YES
Chassis Number	: MDHBN7AD0KG655029	Odometers	: 237007

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		HC 105.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		CO 0.030	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Ties Rods, Bushes, Center Link, Left And Right		SUSPENSION BUSHES CRACKED.		ربلات ذراع التوجيه
Stub Axle Assemblies, Boots		CRACKED, BROKEN		المحور
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2024.		الاطارات الامامية
Rear Left And Right Hand Tires		DOT 2021/2022.		الاطارات الخلفية
Body				الهيكل
Fenders		FRONT FENDER FRAME REPAIRED		المدكار
Floor		UNDERNEATH RUST PROOF COATED		الارضية
Floor		BACK PANEL REPAIRED.		الارضية
Chassis (Frame)		FRONT B/S CHASSIS REPAIRED.		الشاصية
Front And Rear Windshields		FRONT GLASS REPLACED.		الزجاج الامامي والخلفي
Side Safety Frame		BULK HEAD AND RADIATOR FRAME		الواقيات الجانبية

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2019
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: NISSAN/SUNNY
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 39152 - SAM THOMAS
Test Date And Time	: 23 APR 2025 07:56:18	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 2	Un laden Weight	: 1200
Transaction Number	: 35461718	Laden Weight	: 2000
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	: 55029 AWA	Number of Seats	: 5
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: HR15	GCC	: YES
Chassis Number	: MDHBN7AD0KG655029	Odometers	: 237007

Defect	Result	Remarks	Test Value
General Items		REPAIRED	الأشياء العامة
Transmission Condition		OIL LEAK & SIGN OF REFITTED.	حالة ناقل الحركة
Remarks			ملاحظات
Others		TEST DRIVE NOT DONE.	ملاحظات أخرى
Auction			الفحص الكامل
Sign Of Front Accident		SIGN OF FRONT ACCIDENT	أثر حادث في مقدمة المركبة
A/C Not Cooling		A/C NOT COOLING	عطل في المكيف
Body Repainted		BODY PORTIONS REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method	:	CREDIT	Transaction Number : 35461718			
Credit Customer Name	:	971 : AL WATANEYA AUCTION-756				
Customer Tax Registration No.	:	TO BE UPDATED				
Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00
ENOC TAX Registration No.	:	100221692500003				
Processed By	:	Sam Thomas				

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها