

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2023
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: MITSUBISHI/MIRAGE
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 33794 - HARIZE VENNEER KUZHI
Test Date And Time	: 10 MAY 2025 18:13:01	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: HATCHBACK
Token Number	: 40	Un laden Weight	: 1000
Transaction Number	: 35529196	Laden Weight	: 1400
Reference import Doc.	: 001250 AWA	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	:	Number of Seats	: 5
Plate Category	:	Number of Cylinders	: 4 *
Plate Code	:	Fuel Type	: PETROL
Engine Number	: 0	GCC	: YES
Chassis Number	: MMDAAT8J8PH001250	Odometers	: 16337

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		HC 2.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		CO 0.000	فحص الغاز العادم-الكربون
EXPORT/IMPORT DATA:				
Vehicle Details				بيانات المركبة
No. Of Cylinders		3		عدد الاسطوانات
VISUAL TEST:				
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		ALL TYRES DOT.2023		الاطارات الامامية
Remarks				ملاحظات
Others		TEST DRIVE NOT DONE.		ملاحظات اخرى
Auction				الفحص الكامل
Chassis Ok		CHASSIS OK		الشاسي جيد
Body Repainted		RHS DOOR REPAINTED		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 35529196
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : HARIZE VENNEER KUZHI

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها