

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2020
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: NISSAN/NAVARA
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 31138 - MOHAMMED MAKANDAR
Test Date And Time	: 13 MAY 2025 20:22:06	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: PICK UP
Token Number	: 50	Un laden Weight	: 1800
Transaction Number	: 35540224	Laden Weight	: 2200
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	: 31811 AWA	Number of Seats	: 5
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: QR25	GCC	: YES
Chassis Number	: VSKDD3C28LA131811	Odometers	: 102524

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		HC 0.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		CO 0.000	فحص الغاز العادم-الكربون
VISUAL TEST:				
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		ALL 4 TYRES BADLY UNEVEN WORN OUT 2022.		الاطارات الامامية
Body				الهيكل
Paint		MINOR BODY DENTS & SCRATCHES		الصبغ
Bumpers		FRONT BUMPER MISALIGNED UNSECURE.		الدعامية
General Items				الاشياء العامة
Engine Condition, Smoke		ROAD TEST NOT DONE.		حالة المحرك - الدخان
Auction				الفحص الكامل
Chassis Ok		CHASSIS OK		الشاسي جيد
Sign Of Front Accident		BUMPER SUPPORTS BRACKETS DENTS.		أثر حادث في مقدمة المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 35540224
Credit Customer Name : 971 : AL WATANEYA AUCTION-756
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003
Processed By : Mohammed Makandar

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها