

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2018
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/CAMRY
Tester ID(1)	: 31138 - MOHAMMED MAKANDAR	Tester ID(2)	: 31138 - MOHAMMED MAKANDAR
Test Date And Time	: 14 MAY 2025 15:54:18	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: YELLOW-RED - YELLOW-RED
Test Count	:	Vehicle Category	: SEDAN
Token Number	: 27	Un laden Weight	: 1500
Transaction Number	: 35543247	Laden Weight	: 1800
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 4
Plate Number	: 03528 AWA	Number of Seats	: 5
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: 2AR	GCC	: YES
Chassis Number	: JTNBF9HK4J3003528	Odometers	: 673001

### Statement of Vehicle Condition.

### حالة المركبة

Defect	Result	Remarks	Test Value
VISUAL TEST:			
Steering And Suspension System			عجلة القيادة ونظام التوصيلات
Stub Axle Assemblies, Boots		CRACKED, BROKEN	المحور
Tires Rims			الاطارات والعجلات
Front Left And Right Hands Tires		ALL 4 TYRES 2024 UNEVEN WORN OUT.	الاطارات الامامية
Body			الهيكل
Paint		MINOR BODY DENTS & SCRATCHES	الصبغ
General Items			الاشياء العامة
Seats Condition And Seats Fixing		INTERIOR WEAR N TEAR.	المقاعد وحالتها وتثبيتها
Engine Condition, Smoke		ROAD TEST NOT DONE.	حالة المحرك - الدخان
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Body Repainted		BODY REPAINTED	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

TAX Invoice

Payment Method : CREDIT Transaction Number : 35543247  
Credit Customer Name : 971 : AL WATANEYA AUCTION-756  
Customer Tax Registration No. : TO BE UPDATED

Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00

ENOC TAX Registration No. : 100221692500003  
Processed By : Mohammed Makandar

\* Change(s) observed while testing.

\* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

\* أي كشط أو تغيير على الشهادة يلغيها