

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2015
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HI ACE
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 39152 - SAM THOMAS
Test Date And Time	: 24 APR 2025 11:58:43	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN FRIDGE
Token Number	: 11	Un laden Weight	: 1500
Transaction Number	: 35467342	Laden Weight	: 2500
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 3
Plate Number	: 100876 AWA	Number of Seats	: 2
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: 2TR	GCC	: YES
Chassis Number	: JTFHX02P3F0100876	Odometers	: 290090

Statement of Vehicle Condition.

حالة المركبة

Defect	Result	Remarks	Test Value	
AUTOMATIC TEST:				
Brake System				الفرامل
Brake Test	Passed			فحص الفرامل
Exhaust Gas Test				الغاز العادم والكربون
Exhaust Gas Test	Passed		HC 79.000	فحص الغاز العادم-الكربون
Exhaust Gas Test	Passed		CO 0.680	فحص الغاز العادم-الكربون
VISUAL TEST:				
Steering And Suspension System				عجلة القيادة ونظام التوصيلات
Steering Ball Joints, Boots		LEAK.		وصلات عمود عجلة القيادة
Shock Absorbers		FRONT B/S LEAKING.		مخمد الصدمات
Tires Rims				الاطارات والعجلات
Front Left And Right Hands Tires		DOT 2024.		الاطارات الامامية
Rear Left And Right Hand Tires		DOT 2022/2019 - WORN OUT.		الاطارات الخلفية
Body				الهيكل
Rusty		UNDER FLOORING RUSTY & THICK RUST PROOFED.		الصدأ
Fenders		RHS FRONT LOWER FLOORING POARTIONS DENT REPAIRED.		المدكار
Bumpers		BUMPER FRAME,CRASH BOX REPAIRED DENT.		الدعامية
Floor		BACK PANEL,FLOOR REPAIRED.		الارضية
Front And Rear Windshields		FRONT GLASS REPLACED.		الزجاج الامامي والخلفي

Legal Entity Name	: ENOC TASJEEL L.L.C	Vehicle Year Model	: 2015
Site Location	: 677-AL WATANEYA	Vehicle Make/Model	: TOYOTA/HI ACE
Tester ID(1)	: 39152 - SAM THOMAS	Tester ID(2)	: 39152 - SAM THOMAS
Test Date And Time	: 24 APR 2025 11:58:43	Vehicle Type	: LIGHT VEHICLE
Test Type	: DSC AUCTION	Vehicle Color	: WHITE - WHITE
Test Count	:	Vehicle Category	: VAN FRIDGE
Token Number	: 11	Un laden Weight	: 1500
Transaction Number	: 35467342	Laden Weight	: 2500
Reference import Doc.	:	Number of Axles	: 2
Plate Location Place	: SHJ	Number of Doors	: 3
Plate Number	: 100876 AWA	Number of Seats	: 2
Plate Category	: PRIVATE	Number of Cylinders	: 4
Plate Code	: 0	Fuel Type	: PETROL
Engine Number	: 2TR	GCC	: YES
Chassis Number	: JTFHX02P3F0100876	Odometers	: 290090

Defect	Result	Remarks	Test Value
Remarks			ملاحظات
Others		TEST DRIVE NOT DONE.	ملاحظات اخرى
Auction			الفحص الكامل
Chassis Ok		CHASSIS OK	الشاسي جيد
Engine Oil Leaking		ENGINE OIL LEAKING	تهريب زيت المحرك
Gear Box Oil Leaking		GEAR BOX OIL LEAKING	تهريب زيت الجير
Body Repainted		BONNET,RHS DOOR AND BACK DOOR REPAINTED.	أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

TAX Invoice						
Payment Method	: CREDIT	Transaction Number : 35467342				
Credit Customer Name	: 971 : AL WATANEYA AUCTION-756					
Customer Tax Registration No.	: TO BE UPDATED					
Description	Unit Rate	Quantity	Rate%	Amount	VAT	Total Amount
DISCOUNT AUCTION TEST	200.00	1		200.00	10.00	210.00
Total :				200.00	10.00	210.00
ENOC TAX Registration No.	: 100221692500003					
Processed By	: Sam Thomas					

* Change(s) observed while testing.

* Any deletion or alteration effected to this document will render it invalid.

تم تعديل بيانات المركبة بعد إجراء الفحص الفني

* أي كشط أو تغيير على الشهادة يلغيها